

provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent inadvertent opening of a door during flight, which could result in rapid decompression of the passenger cabin, accomplish the following:

(a) Within 3 months or 300 flight hours after the effective date of this AD, whichever occurs later, accomplish the requirements of paragraphs (a)(1) and (a)(2) of this AD.

(1) Modify the passenger and crew doors in accordance with CASA Service Bulletin SB-235-52-54, Revision 1, dated October 24, 1995; and

(2) Perform follow-on actions (i.e., inspections for discrepancies, adjustments, and tests) in accordance with CASA COM 235-098, Revision 02, dated October 19, 1995. If any discrepancy is found, prior to further flight, accomplish the applicable corrective action in accordance with the COM. Thereafter accomplish the requirements of paragraphs (a)(2)(i) and (a)(2)(ii) of this AD.

(i) Repeat the visual inspection for discrepancies of the passenger door and crew door latching and locking systems, in accordance with paragraph 1. of CASA COM 235-098, Revision 02, dated October 19, 1995, at intervals not to exceed 300 flight hours. If any discrepancy is found, prior to further flight, accomplish the applicable corrective action in accordance with the COM.

(ii) Repeat adjustments and tests of the door latching and locking systems, in accordance with paragraph 2., 3., and paragraph V) of Annex II of CASA COM 235-098, Revision 02, dated October 19, 1995, at intervals not to exceed 1,200 flight hours. If any discrepancy is found during any adjustment or test, prior to further flight, accomplish the applicable corrective action in accordance with the COM.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in Spanish airworthiness directive 3/95, Revision 1, dated October 1, 1995.

Issued in Renton, Washington, on March 23, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-8134 Filed 3-26-98; 8:45 am]

BILLING CODE 4901-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-309-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 747 series airplanes. This proposal would require repetitive detailed visual inspections to detect corrosion on the rear spar web of the wing center section and adjacent bulkhead fittings at body station 1241; and corrective action, if necessary. This proposal is prompted by reports of corrosion found on the rear spar web and bulkhead fitting. The actions specified by the proposed AD are intended to detect and correct such corrosion, which could cause cracking of the rear spar web, and result in a fuel leak and consequent fire/explosion in the wheel well of the main landing gear.

DATES: Comments must be received by May 11, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-309-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group,

P.O. Box 3707, Seattle, Washington 98124-2207.

This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Bob Breneman, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington; telephone (425) 227-2776; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 97-NM-309-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-309-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received reports of corrosion found on Boeing Model 747 series airplanes. The corrosion was found on the rear spar web and the bulkhead fitting of body station 1241; corrosion thicknesses ranged from 0.030 to 0.250 inch. Investigation revealed that moisture trapped between the rear

spar web and the bulkhead fitting resulted in the corrosion. Such corrosion, if not detected and corrected in a timely manner, could cause cracking of the rear spar web, and result in a fuel leak and consequent fire/explosion in the wheel well of the main landing gear.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Service Bulletin 747-57-2263, Revision 1, dated December 21, 1995, which describes procedures for repetitive detailed visual inspections to detect corrosion of the rear spar web of the wing center section and adjacent bulkhead fittings at body station 1241; and corrective action, if necessary. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously, except as discussed in the following section.

Differences Between Proposed Rule and Service Bulletin

Operators should note that, while the service bulletin specifies that the application of corrosion inhibitor following an inspection eliminates the necessity for further inspections, this proposed AD would require that the inspection be repeated at regular intervals. The FAA has determined that repetitive inspections and corrective action are necessary in order to detect and correct corrosion in a timely manner and to adequately address the identified unsafe condition.

Additionally, operators should note that, although the service bulletin specifies that the manufacturer may be contacted for disposition of certain repair conditions, this proposal would require that the repair of those conditions be accomplished in accordance with a method approved by the FAA.

Cost Impact

There are approximately 816 airplanes of the affected design in the worldwide fleet. The FAA estimates that 236 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 2 work hours per airplane to accomplish the proposed

actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$28,320, or \$120 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 97-NM-309-AD.

Applicability: Model 747 series airplanes, line positions 1 through 816 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct corrosion and consequent cracking of the rear spar web of the wing center section and adjacent bulkhead fittings at body station 1241, which could result in a fuel leak and subsequent fire/explosion in the wheel well of the main landing gear, accomplish the following:

(a) Within 18 months after the effective date of this AD, perform a detailed visual inspection to detect corrosion of the rear spar web of the wing center section and adjacent bulkhead fittings at body station 1241, in accordance with Boeing Service Bulletin 747-57-2263, Revision 1, dated December 21, 1995. Thereafter, repeat the inspection at intervals not to exceed 2 years.

(1) If no corrosion is detected during the inspection: Prior to further flight, apply corrosion inhibitor in accordance with the service bulletin.

(2) If any corrosion is detected during the inspection, and the corrosion is within the limits specified by the service bulletin: Prior to further flight, accomplish the actions specified in paragraphs (a)(2)(i), (a)(2)(ii), and (a)(2)(iii).

(i) Remove the corrosion in accordance with the service bulletin. And

(ii) Perform a high frequency eddy current inspection to detect cracking in the area of removed corrosion in accordance with the service bulletin. If any crack is detected, prior to further flight, repair it in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. And

(iii) Apply corrosion inhibitor in accordance with the service bulletin.

(3) If any corrosion is detected during the inspection, and the corrosion exceeds the limits specified by the service bulletin: Prior to further flight, repair the corroded area in accordance with a method approved by the Manager, Seattle ACO.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle

ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on March 23, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 98-8133 Filed 3-25-98; 8:45 am]

BILLING CODE 4910-13-U

FEDERAL TRADE COMMISSION

16 CFR Part 243

Guides for the Decorative Wall Paneling Industry

AGENCY: Federal Trade Commission.

ACTION: Request for public comments.

SUMMARY: The Federal Trade Commission ("Commission") is requesting public comments on its Guides for the Decorative Wall Paneling Industry ("Decorative Wall Paneling Guides" or "the Guides"). The Commission is also requesting comments about the overall costs and benefits of its Guides and their overall economic impact, as part of its systematic review of all current Commission regulations and guides.

DATES: Written comments will be accepted until May 26, 1998.

ADDRESSES: Mailed comments should be directed to: Secretary, Federal Trade Commission, Room H-159, Sixth Street and Pennsylvania Ave., N.W., Washington, D.C. 20580. Mailed comments about the Guides for the Decorative Wall Paneling Industry should be identified as "CFR Part 243—Comment." E-mail comments will be accepted at [paneling@ftc.gov]. Those who comment by e-mail should give a mailing address to which an acknowledgment can be sent.

FOR FURTHER INFORMATION CONTACT: Eric Nickerson, Investigator, Federal Trade Commission, Denver Regional Office, 1961 Stout Street, Suite 1523, Denver, CO 80294, telephone number (303) 844-3584, E-mail [enickerson@ftc.gov].

SUPPLEMENTARY INFORMATION:

I. Decorative Wall Paneling Guides

The Commission promulgated the Guides for the Decorative Wall Paneling Industry on December 15, 1971, 36 FR 23796 (1971), under section 5 of the Federal Trade Commission Act ("FTC Act"), 15 U.S.C. 45.¹ The Guides became effective on December 15, 1972.

These Guides, like the other industry guides issued by the Commission, "are administrative interpretations of laws administered by the Commission for the guidance of the public in conducting its affairs in conformity with legal requirements." 16 CFR 1.5. Conduct inconsistent with the Guides may result in corrective action by the Commission under applicable statutory provisions.

The Decorative Wall Paneling Guides provide guidance to manufacturers, retail distributors, and other suppliers ("sellers") of decorative wall panels in labeling, advertising, and promoting their products in a manner consistent with Section 5 of the FTC Act. The guides are designed to protect purchasers from being misled by the appearance of a product, or by deceptive descriptions, depictions, designations, or representations in advertisements, labels, or other promotional materials.

The Guides provide examples of non-deceptive references and representations with respect to the construction, composition, or appearance of industry products. The Guides also point out that sellers bear the affirmative responsibility of providing detailed disclosures regarding the composition of the products being offered.

II. Regulatory Review Program

The Commission has determined, as part of its oversight responsibilities, to review its rules and guides periodically. These reviews seek information about the costs and benefits of the Commission's rules and guides and their regulatory and economic impact. The information obtained assists the Commission in identifying rules and guides that warrant modification or rescission. The Commission solicits comments on, among other things, the economic impact of and the continuing need for the Guides; possible conflict between the Guides and state, local, or other federal laws; and the effect on the Guide of any technological, economic, or other industry changes.

¹ Section 5 of the FTC Act declares unfair methods of competition and unfair or deceptive acts or practices to be unlawful.

III. Request For Comment

The Commission solicits written public comments on the following questions:

- (1) Is there a continuing need for the Decorative Wall Paneling Guides?
 - (a) What benefits have the Guides provided to purchasers of the products affected by the Guides?
 - (b) Have the Guides imposed costs on purchasers?
 - (2) What changes, if any, should be made to the Guides to increase the benefits of the Guides to purchasers?
 - (a) How would these changes affect the costs the Guides impose on firms adhering to their advice? How would these changes affect the benefits to purchasers?
 - (3) What significant burdens or costs, including costs of compliance, have the Guides imposed on firms subject to their advice?
 - (a) Have the Guides provided benefits to such firms? If so, what benefits?
 - (4) What changes, if any, should be made to the Guides to reduce the burdens or costs imposed on firms subject to their advice?
 - (a) How would these changes affect the benefits provided by the Guides?
 - (5) Do the Guides overlap or conflict with other federal, state, or local laws or regulations?
 - (6) Since the Guides were issued, what effects, if any, have changes in the global marketplace, relevant technology or economic conditions had on the Guides? For example, do example, do sellers use E-mail, the Internet or CD ROM to advertise or sell decorative wall panels? If so, in what manner? Does use of this new technology affect consumers' rights or sellers' responsibilities under the Guides?
 - (7) Are there problems today in the labeling, advertising, or selling of decorative wall panels? If yes, what are the nature of these problems? Do the Guides adequately address any problems that may exist?
 - (8) Are any portions of the Guides outdated or otherwise no longer relevant in this industry?
 - (9) Are there industry standards covering any of the issues addressed by the Guides? If yes, what are they?

List of Subjects in 16 CFR Part 243

Advertising, Forests and forest products, Labeling, Trade practices, Wall paneling industry.

Authority: 15 U.S.C. 41-58.

By direction of the Commission.

Donald S. Clark,
Secretary.

[FR Doc. 98-8073 Filed 3-26-98; 8:45 am]

BILLING CODE 6750-01-M