

## Cost Impact

The FAA estimates that 141 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed replacement, and that the average labor rate is \$60 per work hour. Required parts would be supplied by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$8,460, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

## Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

## The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Aerospatiale:** Docket 97-NM-64-AD.

**Applicability:** Model ATR42-300 and -320 series airplanes, on which Aerospatiale Modification 1878, 2482, 3193, or 8154 has not been installed, or on which simultaneous installation of Modifications 0481 and 0588 has not been accomplished; and Model ATR72-102, -202, and -212 series airplanes on which Aerospatiale Modification 2482, 3193, or 4648 has not been installed; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent blockage of the access door, which could restrict access for crewmembers between the flight deck and the passenger compartment during normal operations or an emergency evacuation, accomplish the following:

(a) Within 6 months after the effective date of this AD, replace existing cargo nets with new improved cargo nets, in accordance with paragraph (a)(1) or (a)(2) of this AD, as applicable.

(1) For Model ATR-42 series airplanes: Accomplish replacement of cargo nets in accordance with Aerospatiale Service Bulletin ATR42-25-0108, dated January 24, 1997; or Revision 1, dated February 28, 1997; or Revision 2, dated July 1, 1997.

(2) For Model ATR-72 series airplanes: Accomplish replacement of cargo nets in accordance with Aerospatiale Service Bulletin ATR72-25-1052, dated February 11, 1997; or Revision 1, dated July 1, 1997.

(b) As of the effective date of this AD, no person shall install on any airplane any cargo net having one of the following part numbers: 5366, 5367, 5370, 5375, or 5579.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an

appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Note 3:** The subject of this AD is addressed in French airworthiness directives 96-289-069(B)R1 and 96-288-032(B)R1, both dated December 18, 1996.

Issued in Renton, Washington, on April 7, 1998.

**Darrell M. Pederson,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 98-9760 Filed 4-13-98; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

### 14 CFR Part 39

[Docket No. 97-NM-194-AD]

RIN 2120-AA64

### Airworthiness Directives; Airbus Model A320 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A320 series airplanes. This proposal would require repetitive inspections to detect fatigue cracking on the connecting angle between frame 56 and the right-hand frame support at stringer 38; and replacement of the connecting angle, if necessary. This proposal also provides for an optional terminating action for the repetitive inspections. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to detect and correct fatigue cracking on the connecting angle, which could result in reduced structural integrity of the airplane.

**DATES:** Comments must be received by May 14, 1998.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation

Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-194-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:**

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 97-NM-194-AD." The postcard will be date stamped and returned to the commenter.

**Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No.

97-NM-194-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

**Discussion**

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Airbus Model A320 series airplanes. The DGAC advises that, during full-scale testing on a Model A320 test article, fatigue cracks were found at 60,500 simulated flights on the connecting angle between frame 56 and the right-hand frame support at stringer 38. This condition, if not corrected, could result in reduced structural integrity of the airplane.

**Explanation of Relevant Service Information**

Airbus has issued Service Bulletin A320-53-1084, Revision 1, dated November 28, 1995, which describes procedures for repetitive visual inspections to detect fatigue cracking on the connecting angle between frame 56 and the right-hand frame support at stringer 38. In addition, Airbus has issued Service Bulletin A320-53-1011, dated December 9, 1994, which describes procedures for replacement of the connecting angle with a new part, which would eliminate the need for the repetitive inspections described in Airbus Service Bulletin A320-53-1084. Accomplishment of the actions specified in the service bulletins is intended to adequately address the identified unsafe condition.

The DGAC classified Airbus Service Bulletin A320-53-1084, Revision 1, as mandatory and issued French airworthiness directive 96-237-090(B), dated October 23, 1996, and Erratum to French airworthiness directive 96-237-090(B), dated February 26, 1997, in order to assure the continued airworthiness of these airplanes in France. The DGAC has also approved Airbus Service Bulletin A320-53-1011.

**FAA's Conclusions**

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

**Explanation of Requirements of Proposed Rule**

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletins described previously, except as discussed below. This proposed AD also would provide for optional terminating action for the repetitive inspections.

Operators should note that, in consonance with the findings of the DGAC, the FAA has determined that the repetitive inspections proposed by this AD can be allowed to continue in lieu of accomplishment of a terminating action. In making this determination, the FAA considers that, in this case, long-term continued operational safety will be adequately assured by accomplishing the repetitive inspections to detect fatigue cracking before it represents a hazard to the airplane.

**Differences Between Proposed Rule and Service Bulletins**

Operators should note that, unlike the procedures described in Airbus Service Bulletin A320-53-1084, Revision 1, dated November 28, 1995, this proposed AD would not permit further flight if cracks are detected on the connecting angle between frame 56 and the right-hand frame support at stringer 38. The FAA has determined that, because of the safety implications and consequences associated with such cracking, any subject connecting angle that is found to be cracked must be replaced with a new part prior to further flight.

**Cost Impact**

The FAA estimates that 5 airplanes of U.S. registry would be affected by this proposed AD. It would take approximately 1 work hour per airplane to accomplish the inspection proposed by this AD, at an average labor rate of \$60 per work hour. Based on this figure, the cost impact of the inspection proposed by this AD on U.S. operators is estimated to be \$300, or \$60 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Should an operator elect to perform the optional terminating replacement proposed by this AD, it would take approximately 3 work hours per airplane to accomplish the modification,

at an average labor rate of \$60 per work hour. Required parts would cost \$136 or \$153 per airplane, depending on the service kit purchased. Based on these figures, the cost impact of the optional terminating modification proposed by this AD on U.S. operators is estimated to be as low as \$1,580, or \$316 per airplane and as high as \$1,665, or \$333 per airplane.

### Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Airbus Industrie:** Docket 97-NM-194-AD.

**Applicability:** Model A320 series airplanes, on which Airbus Modification 20941

(reference Airbus Service Bulletin A320-53-1011, dated December 9, 1994) has not been accomplished, certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To detect and correct fatigue cracking on the connecting angle between frame 56 and the right-hand frame support at stringer 38, which could result in reduced structural integrity of the airplane, accomplish the following:

(a) Prior to the accumulation of 20,000 total flight cycles, or within 1,000 flight cycles after the effective date of this AD, whichever occurs later, perform a visual inspection for fatigue cracking on the connecting angle between frame 56 and the right-hand frame support at stringer 38, in accordance with Airbus Service Bulletin A320-53-1084, Revision 1, dated November 28, 1995.

(1) If no cracking is detected, accomplish either paragraph (a)(1)(i) or (a)(1)(ii) of this AD.

(i) Prior to further flight, replace the connecting angle between frame 56 and the right-hand frame support at stringer 38 with a new part, in accordance with Airbus Service Bulletin A320-53-1011, dated December 9, 1994; or

(ii) Repeat the visual inspection thereafter at intervals not to exceed 12,000 flight cycles.

(2) If any cracking is detected, prior to further flight, replace the connecting angle between frame 56 and the right-hand frame support at stringer 38 with a new part, in accordance with Airbus Service Bulletin A320-53-1011, dated December 9, 1994.

(b) Accomplishment of the replacement of the connecting angle constitutes terminating action for the repetitive inspection requirements of this AD.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199

of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Note 3:** The subject of this AD is addressed in French airworthiness directive 96-237-090(B), dated October 23, 1996, and Erratum to French airworthiness directive 96-237-090(B), dated February 26, 1997.

Issued in Renton, Washington, on April 7, 1998.

**Darrell M. Pederson,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 98-9759 Filed 4-13-98; 8:45 am]

BILLING CODE 4910-13-U

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 97-NM-197-AD]

RIN 2120-AA64

### Airworthiness Directives; Airbus Model A320 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A320 series airplanes. This proposal would require repetitive inspections for fatigue cracking of the bottom flanges of the longitudinal floor beams at frame 43; and repair, if necessary. This proposal also would require a one-time inspection for fatigue cracking of the fastener holes in the longitudinal floor beams, and modification of the floor beams, which would constitute terminating action for the repetitive inspections. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent fatigue cracking on the bottom flanges of the longitudinal floor beams, which could result in reduced structural integrity of the airplane.

**DATES:** Comments must be received by May 14, 1998.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-197-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this