Rules and Regulations

Federal Register

Vol. 63, No. 164

Tuesday, August 25, 1998

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 94-SW-29-AD; Amendment 39-10717; AD 98-18-01]

RIN 2120-AA64

Airworthiness Directives; Bell Helicopter Textron, Inc. Model 214B, 214B–1, and 214ST Helicopters

AGENCY: Federal Aviation Administration, DOT.
ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to Bell Helicopter Textron, Inc. (BHTI) Model 214B, 214B-1, and 214ST helicopters, that currently establishes a retirement life of 60,000 high-power events for the main rotor trunnion (trunnion). This amendment requires changing the method of calculating the retirement life for the trunnion from high-power events to a maximum accumulated Retirement Index Number (RIN). This amendment is prompted by fatigue analyses and tests that show certain trunnions fail sooner than originally anticipated because of the unanticipated higher number of lifts or takeoffs (torque events) performed with those trunnions. The actions specified by this AD are intended to prevent fatigue failure of the trunnion, which could result in loss of the main rotor and subsequent loss of control of the helicopter.

EFFECTIVE DATE: September 29, 1998. **FOR FURTHER INFORMATION CONTACT:** Mr. Harry Edmiston, Aerospace Engineer, FAA, Rotorcraft Certification Office, Rotorcraft Directorate, Fort Worth, Texas 76193–0170, telephone (817) 222–5158, fax (817) 222–5959.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal

Aviation Regulations (14 CFR part 39) by superseding AD 94–15–14, Amendment 39–8985 (59 FR 40798, August 10, 1994), which is applicable to BHTI Model 214B, 214B–1, and 214ST helicopters, was published in the **Federal Register** on December 12, 1996 (61 FR 65367). That action proposed to require creation of a component history card using the RIN system; a system for tracking increases to the accumulated RIN; and proposed to establish a maximum accumulated RIN for the trunnion of 120,000 at which time the trunnion must be removed from service.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule, with one non-substantive change. The model 214B–1 has been added to paragraph (b)(1) of the AD to explicitly state that the accumulated RIN is calculated the same for both Model 214B and 214B-1 helicopters. The FAA has determined that this change will neither increase the economic burden on any operator nor increase the scope of the AD.

The FAA estimates that 8 helicopters of U.S. registry will be affected by this AD, that it will take approximately (1) 10 work hours to replace the affected trunnion due to the new method of determining the retirement life required by this AD; (2) 2 work hours per helicopter to create the component history card or equivalent record (record); and (3) 10 work hours per helicopter to maintain the record each year, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$11,000 per helicopter. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$17,360 for the first year and \$16,520 for each subsequent year. These costs assume replacement of the trunnion in one helicopter each year, creation and maintenance of the records for all the fleet the first year, and creation of one helicopter's records and maintenance of the records for all the fleet each subsequent year.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39–8985 (59 FR 40798, August 10, 1994), and by adding a new airworthiness directive (AD), Amendment 39–10717 to read as follows:

AD 98-18-01 Bell Helicopter Textron, Inc. (BHTI): Amendment 39-10717. Docket No. 94-SW-29-AD. Supersedes AD 94-15-14, Amendment 39-8985, Docket No. 93-SW-20-AD.

Applicability: Model 214B, 214B–1, and 214ST helicopters, with main rotor trunnion (trunnion), part number (P/N) 214–010–230–101, installed, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (e) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any helicopter from the applicability of this AD.

Compliance: Required within 25 hours time-in-service (TIS) after the effective date of this AD, unless accomplished previously.

To prevent fatigue failure of the trunnion, which could result in loss of the main rotor and subsequent loss of control of the helicopter, accomplish the following:

- (a) Create a component history card or an equivalent record for the trunnion, P/N 214–040–230–101.
- (b) Determine and record on a component history card or equivalent record the accumulated Retirement Index Number (RIN) to-date on the trunnion by multiplying the accumulated high-power event total to-date by 2 or as follows:
- (1) For Model 214B and 214B-1, multiply the flight hour total to-date by 24 (round-up any resulting fraction to the next higher whole number); or
- (2) For Model 214ST, multiply the factored flight hour total to-date by 24 (round-up any resulting fraction to the next higher whole number).

Note 2: BHTI Alert Service Bulletin (ASB) No. 214–94–55, which is applicable to Model 214B and 214 B–1 helicopters, and ASB No. 214ST–94–70, which is applicable to Model 214ST helicopters, both dated November 7, 1994, pertain to this AD.

- (c) After complying with paragraphs (a) and (b) of this AD, during each operation thereafter, maintain a count of the number and type of external load lifts and the number of takeoffs performed and, at the end of each day's operations, increase the accumulated RIN on the component history card as follows:
- (1) For the Model 214B and 214B-1 helicopters,
 - (i) Increase the RIN by 1 for each takeoff.
- (ii) Increase the RIN by 1 for each external load lift operation, or increase the RIN by 2 for each external load lift operation in which the load is picked up at a higher elevation and released at a lower elevation, and the difference in elevation between the pickup point and the release point is 200 feet or greater.
 - (2) For the Model 214ST helicopters,
- (i) Increase the RIN by 2 for each takeoff.
- (ii) Increase the RIN by 2 for each external load lift operation, or increase the RIN by 4 for each external load lift operation in which the load is picked up at a higher elevation

and released at a lower elevation, and the difference in elevation between the pickup point and the release point is 200 feet or greater.

- (d) Remove the trunnion, P/N 214–010–230–101, from service on or before attaining an accumulated RIN of 120,000. The trunnion is no longer retired based upon flight hours. This AD revises the Airworthiness Limitation section of the maintenance manual by establishing a new retirement life for the trunnion of 120,000 RIN
- (e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Rotorcraft Certification Office, FAA, Rotorcraft Directorate. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Rotorcraft Certification Office.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Rotorcraft Certification Office.

- (f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.
- (g) This amendment becomes effective on September 29, 1998.

Issued in Fort Worth, Texas on August 17, 1998.

Henry A. Armstrong,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 98-22698 Filed 8-24-98; 8:45 am] BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-SW-18-AD; Amendment 39-10126; AD 97-19-06]

RIN 2120-AA64

Airworthiness Directives; Sikorsky Aircraft Corporation Model S-61A, D, E, L, N, NM, R, and V Helicopters; Correction

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document corrects the amendment number in airworthiness directive (AD) 97–19–06 that was incorrectly published in the **Federal Register** on September 19, 1997 (62 FR 49132). This AD is applicable to Sikorsky Aircraft Corporation Model S–61A, D, E, L, N, NM, R, and V helicopters and requires, before further

flight, inspecting certain main rotor blades to determine the anodizing date for certain pocket assemblies installed on the blade, and if a blade has a pocket assembly that was anodized by Poly-Metal Company during the period of October 1, 1996, through December 31, 1996, replacing it with an airworthy blade.

DATES: Effective October 6, 1997.

The incorporation by reference of certain publications listed in the regulations was previously approved by the Director of the Federal Register as of October 6, 1997 (62 FR 49132, September 19, 1997).

FOR FURTHER INFORMATION CONTACT: Mr. Shep Blackman, Aerospace Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222–5296, fax (817) 222–5961.

SUPPLEMENTARY INFORMATION:

Airworthiness Directive (AD) 97–19–06, amendment 39–10126, applicable to Sikorsky Aircraft Corporation Model S–61A, D, E, L, N, NM, R, and V helicopters was published in the **Federal Register** on September 19, 1997 (62 FR 49132). That AD requires, before further flight, inspecting certain main rotor blades to determine the anodizing date for certain pocket assemblies installed on the blade, and if a blade has a pocket assembly that was anodized by Poly-Metal Company during the period of October 1, 1996, through December 31, 1996, replacing it with an airworthy blade.

As published, the amendment number given throughout the AD is incorrect.

Since no other part of the regulatory information has been changed, the final rule is not being republished.

The effective date of the AD remains October 6, 1997.

In rule FR Doc. 97–24075 published on September 19, 1997 (62 FR 49132), make the following corrections:

§39.13 [Corrected]

- (1) On page 49132, in the first column, correct "Amendment 39–10026" to read "Amendment 39–10126."
- (2) On page 49133, in the first column, paragraph 2., correct the two recitations of "Amendment 39–10026" to read "Amendment 39–10126".

Issued in Fort Worth, Texas, on August 18, 1998.

Henry A. Armstrong,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 98–22699 Filed 8–24–98; 8:45 am] BILLING CODE 4910–13–P