

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39****[Docket No. 99-NM-103-AD]****RIN 2120-AA64****Airworthiness Directives; Airbus Model A319, A320, A321, A330, and A340 Series Airplanes****AGENCY:** Federal Aviation Administration, DOT.**ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Airbus Model A319, A320, A321, A330, and A340 series airplanes. This proposal would require repetitive inspections to detect missing and incorrectly installed parts of the footrest actuator assembly, and replacement of discrepant parts with new parts. This AD also would provide for optional terminating action for the repetitive inspections. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent detachment of the footrest assembly actuator, which could result in partial blockage of the rudder pedals and reduced controllability of the airplane.

DATES: Comments must be received by August 13, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-103-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-103-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-103-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on all Airbus Model A319, A320, A321, A330, and A340 series airplanes. The DGAC advises that retaining rings (also called retaining clips) used to secure the pins of the footrest actuator installation, if missing or broken, can result in detachment of the footrest actuator. One operator reported such an occurrence on a Model A320 series airplane. Subsequent inspections conducted on the operator's fleet of Airbus Model A320 and A340 series airplanes revealed 7 broken or missing retaining rings on Model A320 series airplanes and 2 broken or missing retaining rings on Model A340 series airplanes. The footrest assembly is of similar design on Model A319, A320,

A321, A330, and A340 series airplanes. A detached footrest actuator can hang down into the rudder pedals, partially blocking their movement. This condition, if not corrected, could result in reduced controllability of the airplane.

Explanation of Relevant Service Information

Airbus has issued All Operator Telex (AOT) 25-14 (for Model A319, A320, and A321 series airplanes), and AOT 25-13 (for Model A330 and A340 series airplanes); both dated December 17, 1998; which describe procedures for repetitive inspections to detect missing and incorrectly installed parts of the footrest actuator assembly, and replacement of discrepant parts with new parts. The AOT's also describe procedures for the removal of the footrest assembly, which would eliminate the need for the repetitive inspections. The DGAC classified these AOT's as mandatory and issued French airworthiness directives 1999-047-110(B) (for Model A340 series airplanes) and 1999-048-090(B) (for Model A330 series airplanes), both dated February 10, 1999; and 1999-074-127(B), dated February 24, 1999 (for Model A319, A320, and A321 series airplanes); in order to assure the continued airworthiness of these airplanes in France.

FAA's Conclusions

These airplane models are manufactured in France and are type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the AOT's described previously. This proposed AD also would provide for optional terminating action for the repetitive inspections.

Interim Action

This is considered to be interim action. The manufacturer has advised that it currently is developing a modification that will positively address the unsafe condition addressed by this AD and allow for the footrest assembly to remain installed. Once this modification is developed, approved, and available, the FAA may consider further rulemaking.

Cost Impact

The FAA estimates that 208 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 3 work hours per airplane to accomplish the proposed inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$37,440, or \$180 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Airplane, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Airbus: Docket 99–NM–103–AD.

Applicability: All Model A319, A320, A321, A330, and A340 series airplanes; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent detachment of the footrest assembly actuator, which could result in partial blockage of the rudder pedals and reduced controllability of the airplane, accomplish the following:

(a) Within 500 flight hours after the effective date of this AD, perform a detailed visual inspection of the footrest actuator assembly for discrepancies (including bent pins and missing or incorrectly installed retaining rings and pins), in accordance with All Operator Telex (AOT) 25–14, paragraph 4.2.1 (for Model A319, A320 and A321 series airplanes), and AOT 25–13, paragraph 4.2.1 (for Model A330 and A340 series airplanes); both dated December 17, 1998.

(1) If no discrepancy is detected: Repeat the inspection thereafter at intervals not to exceed 15 months.

(2) If any discrepancy is detected: Accomplish the actions of paragraphs (a)(2)(i) and (a)(2)(ii).

(i) Prior to further flight, remove the actuator system from the footrest assembly and conduct a detailed visual inspection of the pins for damage, distortion, or wear, in accordance with paragraph 4.2.2 of the applicable AOT. If any damage, distortion, or wear of the pin, or any discrepancy of the pin or the ring is detected, prior to further flight, replace that pin or ring with a new part, in

accordance with paragraph 4.2.3 of the applicable AOT. And

(ii) Repeat the detailed visual inspection of the footrest actuator assembly to detect discrepancies at intervals not to exceed 15 months.

(b) Removal of the footrest assembly constitutes terminating action for the repetitive inspection requirements of this AD.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc. may be used. Surface cleaning and elaborate access procedures may be required."

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 4: The subject of this AD is addressed in French airworthiness directives 1999–047–110(B) (for Model A340 series airplanes) and 1999–048–090(B) (for Model A330 series airplanes), both dated February 10, 1999; and 1999–074–127(B), dated February 24, 1999 (for Model A319, A320, and A321 series airplanes).

Issued in Renton, Washington, on July 7, 1999.

D.L. Riggins,

Acting Manager, Transport Airplane Directorate, Airplane Certification Service.
[FR Doc. 99–17861 Filed 7–13–99; 8:45 am]

BILLING CODE 4910–13–U