

will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

99-27-09 Airbus Industrie: Amendment 39-11490. Docket 99-NM-327-AD.

Applicability: Model A300 B4-203 series airplanes, certificated in any category, equipped with La Guardia main landing gears (MLG) and Messier Bugatti steel brakes.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent detachment of the brake bar from the MLG strut, which could result in failure of the MLG to extend, accomplish the following:

(a) Within 500 flight hours after the effective date of this AD, perform a detailed visual inspection to detect missing brake bar attachment bolts on the left and right MLG, in accordance with Airbus Service Bulletin A300-32-0430, dated January 29, 1999.

(1) If no attachment bolt is missing, prior to further flight, remove the attachment bolts,

and perform a detailed visual inspection to detect damage, as specified by Figure 1 of the service bulletin. Accomplish the actions in accordance with the service bulletin.

(i) If no damage is detected, repeat the detailed visual inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 500 flight hours.

(ii) If any damage is detected, prior to further flight, replace the two attachment bolts with new bolts in accordance with the service bulletin. Repeat the detailed visual inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 500 flight hours.

(2) If any attachment bolt is missing, prior to further flight, replace the two attachment bolts with new bolts, in accordance with the service bulletin. Repeat the detailed visual inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 500 flight hours.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The actions shall be done in accordance with Airbus Service Bulletin A300-32-0430, dated January 29, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in French airworthiness directive 1999-284-290(B), dated July 13, 1999.

(e) This amendment becomes effective on January 19, 2000.

Issued in Renton, Washington, on December 23, 1999.

Vi L. Lipski,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-8 Filed 1-3-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-130-AD; Amendment 39-11488; AD 99-27-07]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300 B4-600R and A300 F4-600R Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to all Airbus Model A300 B4-600R and A300 F4-600R series airplanes, that currently requires a one-time visual inspection for damage of the center tank fuel pumps and fuel pump canisters, and replacement of damaged fuel pumps and fuel pump canisters with new or serviceable parts. This amendment also requires repetitive visual inspections of the fuel pumps and repetitive eddy current inspections of the fuel pump canisters, and replacement of damaged fuel pumps and fuel pump canisters with new or serviceable parts. This amendment also reduces the applicability to include only those airplanes that have a trim tank system installed. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to detect damage to the fuel pump and fuel pump canister, which could result in loss of flame trap capability and could provide a fuel ignition source in the center fuel tank.

DATES: Effective February 8, 2000.

The incorporation by reference of Airbus Alert Service Bulletin A300-28A6061, dated February 19, 1999, as listed in the regulations, is approved by the Director of the Federal Register as of February 8, 2000.

The incorporation by reference of Airbus All Operators Telex (AOT) 28-

09, dated November 28, 1998, as listed in the regulations, was approved previously by the Director of the Federal Register as of December 28, 1998 (63 FR 70639, December 22, 1998).

ADDRESSES: The service information referenced in this AD may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 98-25-53, amendment 39-10956 (63 FR 70639, December 22, 1998), which is applicable to all Airbus Model A300 B4-600R and A300 F4-600R series airplanes, was published in the **Federal Register** on October 27, 1999 (64 FR 57800). The action proposed to require a one-time visual inspection for damage of the center tank fuel pumps and fuel pump canisters, and replacement of damaged fuel pumps and fuel pump canisters with new or serviceable parts. The action also proposed to require repetitive visual inspections of the fuel pumps and repetitive eddy current inspections of the fuel pump canisters, and replacement of damaged fuel pumps and fuel pump canisters with new or serviceable parts. The action also proposed to reduce the applicability to include only those airplanes that have a trim tank system installed.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 67 airplanes of U.S. registry that will be affected by this AD.

The inspection that is currently required by AD 98-25-53, and retained in this AD, takes approximately 2 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the currently required actions on U.S. operators is estimated to be \$120 per airplane.

The new inspections that are required in this AD action will take approximately 2 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of this requirement of this AD on U.S. operators is estimated to be \$8,040, or \$120 per airplane, per inspection cycle.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the current or proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-10956 (63 FR 70639, December 22, 1998), and by adding a new airworthiness directive (AD), amendment 39-11488, to read as follows:

99-27-07 Airbus Industrie: Amendment 39-11488. Docket 99-NM-130-AD.

Supersedes AD 98-25-53, Amendment 39-10956.

Applicability: Model A300 B4-600R and A300 F4-600R series airplanes, on which Airbus Modification 4801 (trim tank system) has been accomplished, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect damage to the fuel pump and fuel pump canister, which could result in loss of flame trap capability and could provide a fuel ignition source in the center fuel tank, accomplish the following:

Inspections

(a) Prior to the accumulation of 5,000 total hours time-in-service, or within 250 hours time-in-service after the effective date of this AD, whichever occurs later, perform a detailed visual inspection for damage of the center tank fuel pumps and fuel pump canisters, in accordance with Airbus All Operators Telex (AOT) 28-09, dated November 28, 1998. Repeat the inspection prior to the accumulation of 12,000 total hours time-in-service, or within 250 hours time-in-service after accomplishment of the initial inspection, whichever occurs later. Thereafter, repeat the inspection at intervals not to exceed 250 hours time-in-service, until accomplishment of the initial inspection required by paragraph (b) of this AD.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by

the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(b) At the applicable time specified in paragraph (b)(1), (b)(2), or (b)(3) of this AD: Perform a detailed visual inspection to detect damage of the center tank fuel pumps and perform an eddy current inspection to detect damage of the fuel pump canisters, in accordance with Airbus Alert Service Bulletin A300-28A6061, dated February 19, 1999. Repeat the inspections thereafter at intervals not to exceed 1,500 flight cycles. Accomplishment of the initial inspections required by this paragraph constitutes terminating action for the requirements of paragraph (a) of this AD.

(1) For airplanes that have accumulated 11,000 or more total flight cycles as of the effective date of this AD: Inspect within 300 flight cycles after the effective date of this AD.

(2) For airplanes that have accumulated 8,500 or more total flight cycles, but fewer than 11,000 total flight cycles, as of the effective date of this AD: Inspect within 750 flight cycles after the effective date of this AD.

(3) For airplanes that have accumulated fewer than 8,500 total flight cycles as of the effective date of this AD: Inspect prior to the accumulation of 7,000 flight cycles, or within 1,500 flight cycles after the effective date of this AD, whichever occurs later.

(c) If any damage is detected during any inspection required by this AD, prior to further flight, replace the damaged fuel pump or fuel pump canister with a new or serviceable part in accordance with Airbus Alert Service Bulletin A300-28A6061, dated February 19, 1999.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) The actions shall be done in accordance with Airbus All Operators Telex (AOT) 28-09, dated November 28, 1998; and Airbus Alert Service Bulletin A300-28A6061, dated February 19, 1999.

(1) The incorporation by reference of Airbus Alert Service Bulletin A300-

28A6061, dated February 19, 1999, is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of Airbus All Operators Telex (AOT) 28-09, dated November 28, 1998, was approved previously by the Director of the Federal Register as of December 28, 1998 (63 FR 70639, December 22, 1998).

(3) Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the **Federal Register**, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in French airworthiness directive 1999-149-280(B), dated April 7, 1999.

(g) This amendment becomes effective on February 8, 2000.

Issued in Renton, Washington, on December 23, 1999.

D.L. Riffin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 00-6 Filed 1-3-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 301

[TD 8854]

RIN 1545-AX70

Disclosures of Return Information to Officers and Employees of the Department of Agriculture for Certain Statistical Purposes and Related Activities

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Temporary regulation.

SUMMARY: This document provides a temporary regulation relating to the disclosure of return information to officers and employees of the Department of Agriculture for certain statistical purposes and related activities. The temporary regulation would permit the IRS to disclose return information to the Department of Agriculture to structure, prepare, and conduct the Census of Agriculture. The text of this temporary regulation also serves as the text of the proposed regulation set forth in the notice of proposed rulemaking on this subject in the Proposed Rules section of this issue of the **Federal Register**.

DATES: *Effective Date:* This regulation is effective January 4, 2000.

Applicability Date: For dates of applicability of this regulation, see, § 301.6103(j)(5)-1T(d).

FOR FURTHER INFORMATION CONTACT: Jennifer S. McGinty, (202) 622-4570 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

Section 6103(j) of the Internal Revenue Code (Code) provides for the disclosure of tax information for statistical purposes. Prior to the Census of Agriculture Act of 1997 (Pub. L. 105-113), the Bureau of Census had responsibility for preparing the Census of Agriculture. Section 6103(j)(1) authorized the Bureau of Census to receive tax information as prescribed in the regulations in structuring censuses. Treasury regulations implemented such authority with respect to the Census of Agriculture. The Census of Agriculture Act transferred responsibility for that Census from the Bureau of Census to the Department of Agriculture. In 1998, the Tax and Trade Relief Extension Act of 1998 (Pub. L. 105-277) added section 6103(j)(5) to provide disclosure authority for the Department of Agriculture to receive tax information to structure, prepare, and conduct the Census of Agriculture. By letter dated May 21, 1999, the Secretary of Agriculture requested that the regulations be amended so that the Department of Agriculture can begin to receive return information for purposes of the Census of Agriculture. This document contains a temporary regulation which authorizes the IRS to disclose return information to the Department of Agriculture for purposes of the Census of Agriculture.

Explanation of Provisions

This temporary regulation will allow the IRS to disclose return information to the Department of Agriculture for purposes of the Census of Agriculture.

The disclosure of the specific items of return information identified in this regulation is necessary in order for the Department of Agriculture to accurately identify, locate, and classify, as well as properly process, information from agricultural businesses to be surveyed for the statutorily mandated Census of Agriculture.

Special Analyses

It has been determined that this Treasury decision is not a significant regulatory action as defined in Executive Order 12866. Therefore, a regulatory assessment is not required. It has also been determined that section 553(b) of the Administrative Procedure Act (5 U.S.C. chapter 5) does not apply