

in § 567.1 of this part (other than purchased credit card relationships described under paragraph (b)(2) of this section and core deposit intangibles described at paragraph (g)(3) of this section), are deducted in computing tangible and core capital.

(2) Purchase card relationships may be included (that is not deducted) in computing core capital subject to the restrictions of this section, but must be deducted in computing tangible capital.

(3) Mortgage servicing assets may be included (that is not deducted) in computing core capital subject to the restrictions in this section, and may be included in tangible capital in the same amount.

(4) Nonmortgage servicing assets may be included (that is not deducted) in computing core capital subject to the restrictions in this section. All nonmortgage servicing assets must be deducted in computing tangible capital.

(5) Residual interests may be included (that is not deducted) in computing core capital subject to the restrictions of this section, and may be included in tangible capital in the same amount.

* * * * *

(e) *Core capital limitation.* (1) *Aggregate limit.* The maximum aggregate amount of servicing assets, purchased credit card relationships, and residual interests that may be included in core capital shall be limited to the lesser of:

(i) 100 percent of the amount of core capital computed before the deduction of any disallowed servicing assets, disallowed purchased credit card relationships, and disallowed residual interests; or

(ii) The amount of servicing assets and purchased credit card relationships determined in accordance with paragraph (d) of this section plus the amount of residual interests.

(2) *Reduction by deferred tax liability.* Associations may elect to deduct disallowed servicing assets and residual interests on a basis that is net of any associated deferred tax liability.

(3) *Sublimit for purchased credit card relationships, non mortgage-related servicing assets, and residual interests.* In addition to the aggregate limitation in paragraph (e)(1) of this section, a sublimit shall apply to purchased credit card relationships, non mortgage-related servicing assets, and residual interests. The maximum allowable amount of these three types of assets combined shall be limited to the lesser of:

(i) 25 percent of the amount of core capital computed before the deduction of any disallowed servicing assets, purchased credit card relationships, and residual interests; or

(ii) The amount of purchased credit card relationships and non mortgage-related servicing assets determined in accordance with paragraph (d) of this section plus the amount of residual interests.

(f) [Reserved]

* * * * *

Dated: August 4, 2000.

By the Office of Thrift Supervision.

Ellen Seidman,

Director.

[FR Doc. 00-24203 Filed 9-26-00; 8:45 am]

BILLING CODES 4810-33-P, 6210-01-P, 6714-01-P, 6720-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-15-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model DHC-8-100, -200, and -300 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Bombardier Model DHC-8-100, -200, and -300 series airplanes. This proposal would require inspecting the endcaps of the main landing gear selector valve for leaks of hydraulic oil and, if leaks are detected, replacing the leaking endcaps or the entire selector valve. This proposal would also require eventual replacement or rework of certain selector valves, which would terminate the repetitive inspections. This action is prompted by a report of the collapse of the main landing gear due to an external leak of hydraulic oil in the landing gear selector valve, resulting from a fracture of the endcap. This action is intended to prevent leaks of hydraulic oil from the main landing gear selector valve, which could result in the collapse of the main landing gear.

DATES: Comments must be received by October 27, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-15-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this

location between 9:00 am and 3:00 pm, Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-15-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington, or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York.

FOR FURTHER INFORMATION CONTACT:

James E. Delisio, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7521; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact

concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 2000-NM-15-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-15-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, notified the FAA that an unsafe condition may exist on certain Bombardier Model DHC-8-100, -200, and -300 series airplanes. TCCA advises that an investigation of the collapse of the main landing gear of a model DHC-8 series airplane identified the cause as an external hydraulic oil leak in the landing gear selector valve due to a fracture of the endcap. TCCA further advises that main landing gear selector valves that have not been upgraded to part number (P/N) 57420-5 configuration are more susceptible to internal leaks and that excessive internal leaks can also contribute to the collapse of the main landing gear.

Explanation of Relevant Service Information

Bombardier has issued Alert Service Bulletin A8-32-145, Revision 'A', dated December 3, 1999, which describes procedures for inspection of the endcaps of the main landing gear selector valve for leaks of hydraulic oil and replacement of either the endcaps or the complete main landing gear selector valve, if necessary. The service bulletin also describes procedures for replacement or rework of certain selector valves, which will eliminate the need for the repetitive inspections. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. TCCA classified this service bulletin as mandatory and issued Canadian airworthiness directive CF-99-22, dated August 30, 1999, in order to assure the continued airworthiness of these airplanes in Canada.

FAA's Conclusions

This airplane model is manufactured in Canada and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, TCCA has kept the FAA informed of the situation described above. The FAA has examined the findings of TCCA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

The FAA estimates that 235 airplanes of U.S. registry would be affected by this proposed AD, that it would take 9 work hours per airplane to accomplish the proposed inspection and replacement of the main landing gear selector valve (if a leak of hydraulic oil is detected at the first inspection), and that the average labor rate is \$60 per work hour. If the operator chooses to replace the endcaps and do repetitive inspections prior to replacing the main landing gear selector valve, the number of work hours will be greater. Required parts would be provided at no charge to operators. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$126,900, or \$540 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct

effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Bombardier: Docket 2000-NM-15-AD.

Applicability: Model DHC-8-100, -200, and -300 series airplanes, serial numbers 003 through 182 inclusive and 184 through 531 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not

been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the collapse of the main landing gear due to leaks of hydraulic oil from the main landing gear selector valve, accomplish the following:

Inspection

(a) Within 100 flight cycles after the effective date of this AD, perform a general visual inspection of the endcaps of the main landing gear selector valve for the presence of hydraulic oil, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A8-32-145, Revision 'A', dated December 3, 1999. Repeat the inspection thereafter at intervals not to exceed 400 flight hours until the requirements of paragraph (c) are accomplished.

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light, and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Replacement or Modification

(b) If any hydraulic oil is detected on either endcap during any inspection required by paragraph (a) of this AD: Prior to further flight, perform the actions specified in either paragraph (b)(1) or (b)(2) of this AD.

(1) Replace the existing aluminum endcaps, part number (P/N) 34629, with new stainless steel endcaps having P/N 52982, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin S.B. A8-32-145, Revision 'A', dated December 3, 1999. Repeat the inspections required by paragraph (a) at intervals not to exceed 400 flight hours until the requirements of paragraph (c) are met.

(2) Replace the main landing gear selector valve with a valve having P/N 57420-5A, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A8-32-145, Revision 'A', dated December 3, 1999. This action terminates the inspections required by paragraph (a) of this AD.

Note 3: Use care when removing the endcaps, so that the internal components do not fall on the ground and get damaged.

(c) Within 12 months after the effective date of this AD: Perform the actions specified in either paragraph (c)(1) or (c)(2) of this AD as applicable, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A8-32-145, Revision 'A', dated December 3, 1999.

Accomplishment of either paragraph (c)(1) or (c)(2) terminates the repetitive inspection requirements of this AD.

(1) If a main landing gear selector valve having P/N 57420, P/N 57420-1, or P/N 57420-3 is installed, remove it and replace it with a valve having P/N 57420-5A.

(2) If a main landing gear selector valve having P/N 57420-5 is installed, remove it and replace it with a valve having P/N 57420-5A or modify the valve to the P/N 57420-5A configuration (ModSum 8Q100802).

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 5: The subject of this AD is addressed in Canadian airworthiness directive CF-99-22, dated August 30, 1999.

Issued in Renton, Washington, on September 21, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-24752 Filed 9-26-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-79-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A330 and A340 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A330 and A340 series airplanes. This proposal would require modification of the rib 1/wing center spar attachment. This action is necessary to prevent fatigue cracking at the rib 1/center spar angle and bottom corner fitting, which could result in reduced structural capability of the wing. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by October 27, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-79-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-79-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic,