

develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

The FAA estimates that 3 Model SAAB 2000 series airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would be provided by the vendor at no charge to operators. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$180, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Saab Aircraft AB: Docket 2000–NM–221–AD.

Applicability: Model Saab 2000 series airplanes, certificated in any category, having serial numbers –004 through –063 inclusive.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent separation of the self-seal couplings, which could result in loss of engine oil pressure and a flight-crew-commanded engine shutdown, accomplish the following:

(a) Within 3 months after the effective date of this AD, perform a one-time general visual inspection to ensure correct installation of the air-cooled oil cooler (ACOC) self-seal couplings in each nacelle, and install a new clamp to the self-seal couplings, in accordance with Saab Service Bulletin 2000–79–005, dated May 22, 2000. If any coupling is installed incorrectly, prior to further flight, perform the corrective actions specified in the service bulletin in accordance with the procedures specified in the service bulletin.

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light, and may require removal or opening of

access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 4: The subject of this AD is addressed in Swedish airworthiness directive 1–158, dated May 23, 2000.

Issued in Renton, Washington, on September 25, 2000.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00–24983 Filed 9–28–00; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000–CE–48–AD]

RIN 2120–AA64

Airworthiness Directives; S.N. CENTRAIR Model 201B Sailplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to adopt a new airworthiness directive (AD) that would apply to all S.N. CENTRAIR Model 201B sailplanes. The proposed AD would require you to modify the rear canopy emergency release system. The proposed AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for France. The actions specified in the proposed AD are intended to prevent the rear canopy retaining strap from not

releasing properly during the emergency egress procedure because of the current design of the rear canopy emergency release system. This condition, if not corrected, will not allow the rear canopy to completely separate from the sailplane and could result in potential injury to the pilot during an emergency egress.

DATES: The Federal Aviation Administration (FAA) must receive any comments on this proposed rule by October 31, 2000.

ADDRESSES: Send comments in triplicate to the FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-CE-48-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. You may inspect comments at this location between 8 a.m. and 4 p.m., Monday through Friday, except holidays.

You may get service information that applies to the proposed AD from S.N. CENTRAIR, Aerodome—36300 Le Blanc, France; telephone: 02.54.37.07.96; facsimile: 02.54.37.48.64. You may read this information at the Rules Docket at the above address.

FOR FURTHER INFORMATION CONTACT: Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Comments Invited

How do I comment on the proposed AD? The FAA invites comments on this proposed rule. You may submit whatever written data, views, or arguments you choose. You need to include the rule's docket number and submit your comments in triplicate to the address specified under the caption **ADDRESSES**. The FAA will consider all comments received on or before the closing date. We may amend the proposed rule in light of comments received. Factual information that supports your ideas and suggestions is extremely helpful in evaluating the effectiveness of the proposed AD action and determining whether we need to take additional rulemaking action.

Are there any specific portions of the proposed AD I should pay attention to? The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of the proposed rule that might suggest a need to modify the rule. You may examine all comments we receive before and after the closing date of the rule in the Rules Docket. We will file a report in the Rules Docket that summarizes

each FAA contact with the public that concerns the substantive parts of the proposed AD.

We are re-examining the writing style we currently use in regulatory documents, in response to the Presidential memorandum of June 1, 1998. That memorandum requires Federal agencies to communicate more clearly with the public. We are interested in your comments on whether the style of this document is clearer, and any other suggestions you might have to improve the clarity of FAA communications that affect you. You can get more information about the Presidential memorandum and the plain language initiative at <http://www.plainlanguage.gov>.

How can I be sure FAA receives my comment? If you want us to acknowledge the receipt of your comments, you must include a self-addressed, stamped postcard. On the postcard, write "Comments to Docket No. 2000-CE-48-AD." We will date stamp and mail the postcard back to you.

Discussion

What events have caused this proposed AD? The Direction Generale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, recently notified the FAA that an unsafe condition may exist on all S.N. CENTRAIR Model 201B sailplanes. The DGAC reports an incident where a Model 201B rear canopy strap did not properly release during an actual emergency egress.

The DGAC advises that the problem is related to the unreliability of the rear canopy from completely separating from the sailplane during an emergency egress procedure.

What are the consequences if the condition is not corrected? If the rear canopy retaining strap does not release properly during the emergency egress procedure, the rear canopy will not completely separate from the sailplane. This could result in potential injury to the pilot during an emergency egress.

Relevant Service Information

Is there service information that applies to this subject? S.N. CENTRAIR has issued Service Bulletin No. 201-16, Revision 1, dated December 12, 1999.

What are the provisions of this service bulletin? The service bulletin:

- Specifies the installation of a mechanism that automatically releases the rear canopy strap when the emergency canopy lever is actuated;
- Includes Process Sheet for Fitment of the Release Unit for the Rear Canopy Strap on Glider Centrair 201

"Marianne", dated March 17, 1999. This document includes procedures for incorporating the modification; and

- Specifies an inspection to assure that this modification is accomplished correctly.

What actions did the DGAC take? The DGAC classified this service bulletin as mandatory and issued French AD Number 1995-055(A) R1, dated February 5, 2000, in order to assure the continued airworthiness of these sailplanes in France.

Was this in accordance with the bilateral airworthiness agreement? This sailplane model is manufactured in France and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept FAA informed of the situation described above.

The FAA's Determination and an Explanation of the Provisions of the Proposed AD

What has FAA decided? The FAA has examined the findings of the DGAC; reviewed all available information, including the service information referenced above; and determined that:

- The unsafe condition referenced in this document exists or could develop on other S.N. CENTRAIR Model 201B sailplanes of the same type design;
- The actions specified in the previously-referenced service information should be accomplished on the affected sailplanes, except for requiring an inspection to ensure that the modification is accomplished correctly and;

- AD action should be taken in order to correct this unsafe condition.

What does the proposed AD require? This proposed AD would require you to install a mechanism that automatically releases the rear canopy strap when the emergency canopy lever is actuated. Accomplishment of the proposed modification would be in accordance with the procedures in S.N. Centrair Process Sheet for Fitment of the Release Unit for the Rear Canopy Strap on Glider Centrair 201 "Marianne", dated March 17, 1999 (or the instructions provided with the modification kit).

Cost Impact

How many sailplanes does the proposed AD impact? We estimate that the proposed AD affects 41 sailplanes in the U.S. registry.

What is the cost impact of the proposed AD on owners/operators of the affected sailplanes? We estimate the

following costs to accomplish the proposed modification:

Labor cost	Parts cost per sailplane	Total cost per sailplane	Total cost on U.S. sailplane operators
4 workhours × \$60 per hour = \$240	\$150	\$390	\$15,990

Compliance Time of the Proposed AD

What is the compliance time of the proposed AD? The compliance time of this proposed AD is “within the next 3 months after the effective date of this AD.”

Why is the compliance time presented in calendar time instead of hours time-in-service (TIS)? Although the rear canopy retaining strap not releasing properly during the emergency egress procedure occurs during flight, the condition is not a direct result of sailplane operation. The chance of this situation occurring is the same for a sailplane with 10 hours TIS as it would be for a sailplane with 500 hours TIS. A calendar time for compliance will assure that the unsafe condition is addressed on all sailplanes in a reasonable time period.

What are the differences between the French AD and the proposed AD? The French AD requires installation of a mechanism that automatically releases the rear canopy strap when the emergency canopy lever is actuated. The French AD also requires a visual inspection to ensure that the modification is incorporated correctly.

The FAA does not require this inspection because we believe that the procedures are adequate to allow the maintenance personnel to accomplish the action correctly.

Regulatory Impact

Does this proposed AD impact various entities? The regulations proposed

herein would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposed rule would not have federalism implications under Executive Order 13132.

Does this proposed AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this proposed action (1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration

proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

S.N. CENTRAIR: Docket No. 2000–CE–48–AD.

(a) *What sailplanes are affected by this AD?* This AD applies to Model 201B sailplanes, all serial numbers, certificated in any category.

(b) *Who must comply with this AD?* Anyone who wishes to operate any of the above sailplanes on the U.S. Register must comply with this AD.

(c) *What problem does this AD address?* The actions specified in this AD are intended to prevent the rear canopy retaining strap from not releasing properly during the emergency egress procedure because of the current design of the rear canopy emergency release system. This condition, if not corrected, will not allow the rear canopy to completely separate from the sailplane and could result in potential injury to the pilot during an emergency egress.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Actions	Compliance times	Procedures
(1) Install a mechanism that automatically releases the rear canopy strap when the emergency canopy lever is actuated.	Within the next 3 months after the effective date of this AD.	(i) Follow the procedures in S.N. Centrair Process Sheet for Fitment of the Release Unit for the Rear Canopy Strap on Glider Centrair 201 “Marianne”, dated March 17, 1999 (or the instructions provided with the modification kit). (ii) The document specified above is referenced in S.N. CENTRAIR Service Bulletin No. 201–16, Revision 1, dated December 12, 1999. (iii) The inspection referenced in the service bulletin is not required by this AD.
(2) Do not install a rear canopy emergency release system without incorporating the modification referenced in paragraph (d)(1) of this AD.	As of the effective date of this AD	Not Applicable.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Small Airplane Directorate approves your alternative. Send your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106.

Note 1: This AD applies to each sailplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For sailplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. You should include in the request an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* You can contact Mike Kiesow, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; facsimile: (816) 329-4090.

(g) *What if I need to fly the sailplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your sailplane to a location where you can accomplish the requirements of this AD.

(h) *How do I get copies of the documents referenced in this AD?* You may obtain copies of the documents referenced in this AD from S.N. CENTRAIR, Aerodome—36300 Le Blanc, France; telephone: 02.54.37.07.96; facsimile: 02.54.37.48.64. You may read these documents at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Note 2: The subject of this AD is addressed in French AD 1999-055(A)R1, dated February 5, 2000.

Issued in Kansas City, Missouri, on September 22, 2000.

Michael K. Dahl,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-24982 Filed 9-28-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00-AWP-11]

Proposed Revision of Class D Airspace; Laughlin/Bullhead International Airport, AZ

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to revise Class D airspace at Laughlin/Bullhead International Airport, AZ, by including that airspace within a 4.2-mile radius of the Laughlin/Bullhead international Airport west of a line 1.8-miles west of and parallel to the north/south runway. Additional Class D airspace is required to contain circling instrument approaches to the west of the airport. A review of airspace classification and air traffic procedures has made this action necessary.

DATES: Comments must be received on or before November 13, 2000.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Attn: Manager, Airspace Branch, AWP-520, Docket No. 00-AWP-11, Air Traffic Division, P.O. Box 92007, Worldway Postal Center, Los Angeles, California 90009.

The official docket may be examined in the Office of the Assistant Chief Counsel, Western Pacific Region, Federal Aviation Administration, Room 6007, 15000 Aviation Boulevard, Lawndale, California 92061.

An informational docket may also be examined during normal business hours at the Office of the Manager, Airspace Branch, Air Traffic Division at the above address.

FOR FURTHER INFORMATION CONTACT:

Richard V. Coffin Jr., Airspace Specialist Airspace Branch, AWP-520.9, Air Traffic Division, Western-Pacific Region, Federal Aviation Administration, 15000 Aviation Boulevard, Lawndale, California 92061, telephone (310) 725-6533.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with the comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 00-AWP-11." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the Airspace Branch, Air Traffic Division, at 15000 Aviation Boulevard, Lawndale, California 92061, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM

The FAA is considering a revision to part 71 of the Federal Aviation Regulations (14 CFR part 71) to establish Class D airspace at Laughlin/Bullhead International Airport, AZ. This action establishes additional controlled airspace required for circling instrument approaches to the west of the Laughlin/Bullhead International Airport, AZ. A review of airspace classification and air traffic procedures has made this action necessary. Class D airspace is published in Paragraph 5000 of FAA Order 7400.9H, Airspace Designations and Reporting Points, dated September 1, 2000, and effective September 16, 2000, through September 15, 2001, which is incorporated by reference in 14 CFR 71.1. The Class D airspace designation listed in this document would be published subsequently in this Order.

The FAA has determined that this proposed regulation only involves an established body of technical