

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000–20–05 Empresa Brasileira de**Aeronautica S.A. (EMBRAER):**

Amendment 39–11916. Docket 99–NM–356–AD.

Applicability: Model EMB–120 series airplanes as listed in EMBRAER Service Bulletin 120–32–0077, Change 02, dated December 23, 1997; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the landing gear doors from becoming blocked from opening during application of emergency procedures in the

event of a loss of hydraulics, accomplish the following:

Airplane Flight Manual (AFM) Revision

(a) Within 10 flight hours after the effective date of this AD, revise the “Emergency Procedures” and “Abnormal Procedures” sections of the FAA-approved AFM by inserting into the AFM a copy of EMB–120 AFM 120/794, Revision 45, dated October 14, 1996.

(b) For airplanes on which the check valve has been installed in accordance with EMBRAER Service Bulletin 120–32–0077, dated February 7, 1997: Within 100 hours after the effective date of this AD, conduct a visual inspection to detect the check valve flow direction in accordance with Service Bulletin 120–32–0077, Change 02, dated December 23, 1997. If the check valve is installed incorrectly, prior to further flight, reinstall the check valve in the proper position in accordance with Change 02 of the service bulletin.

(c) For airplanes on which the check valve has not been installed in accordance with EMBRAER Service Bulletin 120–32–0077, dated February 7, 1997; or Change 01, dated September 25, 1997; or Change 02, dated December 23, 1997: Within 2,000 flight hours after the effective date of this AD, install hydraulic tube assemblies incorporating a check valve in accordance with Service Bulletin 120–32–0077, Change 02, dated December 23, 1997.

Note 2: Accomplishment of the installation in accordance with EMBRAER Service Bulletin 120–32–0077, Change 01, dated

September 25, 1997, prior to the effective date of this AD, is acceptable for compliance with this paragraph.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) Except as provided by paragraph (a) of this AD, the actions shall be done in accordance with EMBRAER Service Bulletin 120–32–0077, Change 02, dated December 23, 1997. EMBRAER Service Bulletin 120–32–0077, Change 02, dated December 23, 1997 contains the following list of effective pages:

Page No.	Revision level shown on page	Date shown on page
1, 2, 11, 12	02	December 23, 1997.
3–10	01	September 25, 1997.

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in Brazilian airworthiness directive 97–05–03R2, dated March 16, 1998.

Effective Date

(g) This amendment becomes effective on November 13, 2000.

Issued in Renton, Washington, on September 26, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00–25150 Filed 10–5–00; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 99–NM–26–AD; Amendment 39–11902; AD 2000–19–01]

RIN 2120–AA64

Airworthiness Directives; Bombardier Model CL–600–1A11 (CL–600) and CL–600–2A12 (CL–601) Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document corrects a typographical error that appeared in airworthiness directive (AD) AD 2000–19–01 that was published in the **Federal Register** on September 20, 2000 (65 FR 56780). The typographical error resulted in failure to reference an acceptable method of compliance for a certain requirement. This AD is applicable to certain Bombardier Model CL–600–1A11 (CL–600) and CL–600–2A12 (CL–601) series airplanes. This AD requires modification of the main landing gear (MLG) brake units and inboard MLG wheels; and a revision to the Airplane Flight Manual (AFM) to include the increased cooling times for the modified brakes. This AD allows, for certain cases, removal of the inboard and/or outboard wheel discs by installation of a placard to limit airplane operation on the ground and a revision to the AFM to include information for operating the airplane with the wheel discs removed. Additionally, this AD provides for an

acceptable method of compliance that involves installation of a new revision to the AFM.

DATES: Effective October 25, 2000.

FOR FURTHER INFORMATION CONTACT:

James E. Delisio, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7521; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION:

Airworthiness Directive (AD) 2000-19-01, amendment 39-11902, applicable to certain Bombardier Model CL-600-1A11 (CL-600) and CL-600-2A12 (CL-601) series airplanes, was published in the **Federal Register** on September 20, 2000 (65 FR 56780). That AD requires modification of the main landing gear (MLG) brake units and inboard MLG wheels; and a revision to the Airplane Flight Manual (AFM) to include the increased cooling times for the modified brakes. That AD allows, for certain cases, removal of the inboard and/or outboard wheel discs by installation of a placard to limit airplane operation on the ground and a revision to the AFM to include information for operating the airplane with the wheel discs removed. Additionally, that AD provides for an acceptable method of compliance that involves installation of a new revision to the AFM.

As published, paragraph (d) of the existing AD specifies that installation of a specific AFM revision is acceptable for compliance with the requirements of paragraphs (a) and (b) of that AD. The FAA inadvertently did not specify that installation of a specific AFM revision is also acceptable for compliance with the requirements of paragraph (c) of that AD.

Since no other part of the regulatory information has been changed, the final rule is not being republished.

The effective date of this AD remains October 25, 2000.

§ 39.13 [Corrected]

On page 56782, in the second column, paragraph (d) of AD 2000-19-01 is corrected to read as follows:

* * * * *

(d) For all airplanes: Installation of the AFM revision specified in either paragraph (d)(1) or (d)(2) of this AD, as applicable, is acceptable for compliance with the requirements of paragraphs (a), (b), and (c) of this AD, as applicable.

(1) Bombardier Model CL-600-1A11 (CL-600) AFM Revisions A84 and 76, both dated February 7, 2000; or

(2) Bombardier Model CL600-2A12 (CL-601) AFM Revisions 45, 48, 50, and 86, all dated February 7, 2000.

* * * * *

Issued in Renton, Washington, on October 2, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-25684 Filed 10-5-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00-ASO-28]

Amendment of Class E Airspace; Picayune, MS

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends Class E airspace at Picayune, MS. Picayune—Pearl River County Airport has closed and a new airport has been established approximately 3.5 miles southeast of the Picayune—Pearl River County Airport site. The name of the new airport is Picayune Municipal Airport. Area Navigation (RNAV) Runway (RWY) 18 and RWY 36 Standard Instrument Approach Procedures (SIAPs) have been developed for Picayune Municipal Airport. As a result, controlled airspace extending upward from 700 feet Above Ground Level (AGL) is needed to accommodate the SIAPs at Picayune Municipal Airport. This action also changes the name of the airport in the airspace description from Picayune—Pearl River County to Picayune Municipal Airport.

EFFECTIVE DATE: 0901 UTC, January 25, 2001.

FOR FURTHER INFORMATION CONTACT:

Nancy B. Shelton, Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5586.

SUPPLEMENTARY INFORMATION:

History

On August 18, 2000, the FAA proposed to amend part 71 of the Federal Aviation Regulations (14 CFR part 71) by amending Class E airspace at Picayune, MS, (65 FR 50470) to contain the RNAV RWY 18 and 39 SIAPs developed for the Picayune Municipal Airport. Class E airspace designations are published in Paragraph

6005 of FAA Order 7400.9H, dated September 1, 2000, and effective September 16, 2000, which is incorporated by reference in 15 CFR 71.1, dated September 1, 1999. The Class E airspace designations listed in this document will be published subsequently in the Order.

Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No comments objecting to the proposal were received.

The Rule

This amendment to Part 71 of the Federal Aviation Regulations (14 CFR part 71) amends Class E airspace at Picayune, MS. This action also changes the name of the airport in the airspace description from Picayune—Pearl River County to Picayune Municipal Airport.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR Part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; EO 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389; 14 CFR 11.69.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation