

Part nomenclature	Part No. (P/N)	Inspect per engine manual chapter
HPTR Disk, Stage 1	All	72-53-02-200-001-002 Fluorescent Penetrant Inspection (subtask 72-53-02-160-051), and 72-53-02-200-001-002 Eddy Current Inspection of the Bore.
HPTR Disk, Stage 2	All	72-53-04-200-001-004 Fluorescent Penetrant Inspection (subtask 72-53-04-230-052), and 72-53-04-200-001-004 Eddy Current Inspection of the Bore.
LPTR Cone Shaft	All	72-56-07-200-001-001 Fluorescent Penetrant Inspection.
LPTR Fan Mid Shaft	All	72-58-01-200-001-001 Magnetic Particle Inspection.
LPTR Disk, Stage 1	All	72-56-02-200-001-001 Fluorescent Penetrant Inspection.
LPTR Disk, Stage 2	All	72-56-02-200-001-001 Fluorescent Penetrant Inspection.
LPTR Disk, Stage 3	All	72-56-02-200-001-001 Fluorescent Penetrant Inspection.
LPTR Disk, Stage 4	All	72-56-02-200-001-001 Fluorescent Penetrant Inspection.
LPTR Disk, Stage 5	All	72-56-02-200-001-001 Fluorescent Penetrant Inspection.
LPTR Disk, Stage 6	All	72-56-02-200-001-001 Fluorescent Penetrant Inspection.
Fan Shaft, Forward	All	72-22-01-200-001-001 Fluorescent Penetrant Inspection.

(2) For the purposes of these mandatory inspections, piece-part opportunity means:

(i) The part is considered completely disassembled when accomplished in accordance with the disassembly instructions in the manufacturer's engine manual; and

(ii) The part has accumulated more than 100 cycles in service since the last piece-part opportunity inspection, provided that the part was not damaged or related to the cause for its removal from the engine."

(b) Except as provided in paragraph (c) of this AD, and notwithstanding contrary provisions in section 43.16 of the Federal Aviation Regulations (14 CFR 43.16), these mandatory inspections must be performed only in accordance with the Life Limits Section of the manufacturer's ICA.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Engine Certification Office (ECO). Operators must submit their requests through an appropriate FAA Principal Maintenance Inspector (PMI), who may add comments and then send it to the ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Continuous Airworthiness Maintenance Program

(e) FAA-certificated air carriers that have an approved continuous airworthiness maintenance program in accordance with the recordkeeping requirement of § 121.369(c) of the Federal Aviation Regulations [14 CFR 121.369(c)] of this chapter must maintain records of the mandatory inspections that result from revising the Life Limits Section of the ICA and the air carrier's continuous airworthiness program. Alternatively, certificated air carriers may establish an approved system of record retention that

provides a method for preservation and retrieval of the maintenance records that include the inspections resulting from this AD, and include the policy and procedures for implementing this alternate method in the air carrier's maintenance manual required by § 121.369(c) of the Federal Aviation Regulations [14 CFR 121.369(c)]; however, the alternate system must be accepted by the appropriate PMI and require the maintenance records be maintained either indefinitely or until the work is repeated. Records of the piece-part inspections are not required under § 121.380(a)(2)(vi) of the Federal Aviation Regulations [14 CFR 121.380 (a)(2)(vi)]. All other Operators must maintain the records of mandatory inspections required by the applicable regulations governing their operations.

Note 3: The requirements of this AD have been met when the engine manual changes are made and air carriers have modified their continuous airworthiness maintenance plans to reflect the requirements in the engine manuals.

Issued in Burlington, Massachusetts, on September 26, 2001.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 01-25400 Filed 10-9-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-ANE-47-AD]

RIN 2120-AA64

Airworthiness Directives; Pratt & Whitney JT9D Series Turbofan Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness

directive (AD), applicable to certain Pratt & Whitney JT9D series turbofan engines, that currently requires revisions to the Airworthiness Limitations Section (ALS) of the manufacturer's Instructions for Continued Airworthiness (ICA) to include required enhanced inspection of selected critical life-limited parts at each piece-part exposure. This action would add additional critical life-limited parts for enhanced inspection. An FAA study of in-service events involving uncontained failures of critical rotating engine parts has indicated the need for mandatory inspections. The mandatory inspections are needed to identify those critical rotating parts with conditions, which if allowed to continue in service, could result in uncontained failures. The actions specified by this proposed AD are intended to prevent critical life-limited rotating engine part failure, which could result in an uncontained engine failure and damage to the airplane.

DATES: Comments must be received by November 9, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-ANE-47-AD, 12 New England Executive Park, Burlington, MA 01803-5299. Comments may also be sent via the Internet using the following address: "9-ane-adcomment@faa.gov". Comments sent via the Internet must contain the docket number in the subject line. Comments may be inspected at this location by appointment between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Tara Goodman, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-

5299; telephone (781) 238-7130, fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-ANE-47-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRM's

Any person may obtain a copy of this NPRM by submitting a request to the FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-ANE-47-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

Discussion

On January 19, 2000, the FAA issued AD 2000-01-13, Amendment 39-11511 (65 FR 2864, January 19, 2000), to require revisions to the Time Limits section in the Engine Manual (EM) for certain Pratt & Whitney (PW) JT9D series turbofan engines to include required enhanced inspection of selected critical life-limited parts at each piece-part exposure.

Additional Inspection Procedures

Since the issuance of that AD, an FAA study of in-service events involving uncontained failures of critical rotating engine parts has indicated the need for additional mandatory inspections. The

mandatory inspections are needed to identify those critical rotating parts with conditions, which if allowed to continue in service, could result in uncontained failures. This proposal would modify the airworthiness limitations section of the manufacturer's manual and an air carrier's approved continuous airworthiness maintenance program to incorporate additional inspection requirements.

In this proposal, the mandatory manual and inspection references in Table (a)(1) have also been revised to more accurately describe the required FPI inspection of HPT disks.

Proposed Action

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would supersede AD 2000-01-13 to require the additional critical life-limited rotating engine parts to be subject to focused inspection at each piece-part opportunity.

Economic Analysis

The FAA estimates that 837 engines installed on airplanes of US registry would be affected by this proposed AD, that it would take approximately 1 work hour per engine to accomplish the proposed actions. The average labor rate is \$60 per work hour. Based on these figures the total cost impact of the proposed AD on U.S. operators is estimated to be \$903,960.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the

location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-11511 (65 FR 2864, January 19, 2000), and by adding a new airworthiness directive, to read as follows:

Pratt & Whitney: Docket No. 98-ANE-47-AD. Supersedes AD 2000-01-13, Amendment 39-11511.

Applicability: Pratt & Whitney (PW) JT9D-3A, -7, -7A, -7H, -7AH, -7F, -7J, -20J, -59A, -70A, -7Q, -7Q3, -7R4D, -7R4D1, -7R4E, -7R4E1, -7R4E4, -7R4G2, and -7R4H1 series turbofan engines, installed on but not limited to Boeing 747 and 767 series, McDonnell Douglas DC-10 series, and Airbus Industrie A300 and A310 airplanes.

Note 1: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance

Compliance with this AD is required as indicated, unless already done.

To prevent critical life-limited rotating engine part failure, which could result in an uncontained engine failure and damage to the airplane, accomplish the following:

Inspections

(a) Within the next 30 days after the effective date of this AD, revise the manufacturer's Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness (ICA), and for air carrier operations revise the approved

continuous airworthiness maintenance program, by adding the following:
“MANDATORY INSPECTIONS

(1) Perform inspections of the following parts at each piece-part opportunity in

accordance with the instructions provided in the applicable manual provisions:

Engine model	Engine manual part No.	Part nomenclature	FPI per manual section	Inspection
7/7A/7AH/7F, 7H/7J/20/20J.	646028 (or the equivalent customized versions, 770407 and 770408).	All Fan Hubs	72-31-04	02
		All HPC Stage 5-15 Disks	72-35-00	03
		All HPT Stage 1-2 Disks and Hubs	72-51-00	03
		All LPT Stage 3-6 Disks and	72-52-00	03
59A/70A	754459	All Fan Hubs	72-31-00	Heavy Maintenance Check
		All HPC Stage 5-15 Disks	72-35-00	Heavy Maintenance Check
		All HPT Stage 1-2 Disks and Hubs	72-51-00	Heavy Maintenance Check-3
		All LPT Stage 3-6 Disks	72-52-00	Heavy Maintenance Check-3
7Q/7Q3	777210	All Fan Hubs	72-31-00	03
		All HPC Stage 5-15 Disks	72-35-00	03
		All HPT Stage 1-2 Disks and Hubs	72-51-00	03
		All LPT Stage 3-6 Disks	72-52-00	03
7R4	785058, 785059, and 789328	All Fan Hubs	72-31-00	03
		All HPC Stage 5-15 Disks	72-35-00	03
		All HPT Stage 1-2 Disks and Hubs	72-51-00	03
		All LPT Stage 3-6 Disks	72-52-00	03

* P/N 770407 and 770408 are customized versions of P/N 646028 engine manual.

(2) For the purposes of these mandatory inspections, piece-part opportunity means:

(i) The part is considered completely disassembled when accomplished in accordance with the disassembly instructions in the manufacturer's engine manual; and

(ii) The part has accumulated more than 100 cycles in service since the last piece-part opportunity inspection, provided that the part was not damaged or related to the cause for its removal from the engine.”

(b) Except as provided in paragraph (c) of this AD, and notwithstanding contrary provisions in section 43.16 of the Federal Aviation Regulations (14 CFR 43.16), these mandatory inspections shall be performed only in accordance with the ALS of the manufacturer's ICA.

Alternative Method of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Engine Certification Office (ECO). Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector (PMI), who may add comments and then send it to the ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Continuous Airworthiness Maintenance Program

(e) FAA-certificated air carriers that have an approved continuous airworthiness maintenance program in accordance with the record keeping requirement of § 121.369 (c) of the Federal Aviation Regulations [14 CFR 121.369 (c)] of this chapter must maintain records of the mandatory inspections that result from revising the Time Limits section of the Instructions for Continuous Airworthiness (ICA) and the air carrier's continuous airworthiness program. Alternately, certificated air carriers may establish an approved system of record retention that provides a method for preservation and retrieval of the maintenance records that include the inspections resulting from this AD, and include the policy and procedures for implementing this alternate method in the air carrier's maintenance manual required by § 121.369 (c) of the Federal Aviation Regulations [14 CFR 121.369 (c)]; however, the alternate system must be accepted by the appropriate PMI and require the maintenance records be maintained either indefinitely or until the work is repeated. Records of the piece-part inspections are not required under § 121.380 (a) (2) (vi) of the Federal Aviation Regulations [14 CFR 121.380 (a) (2) (vi)]. All other Operators must maintain the records of mandatory inspections required by the applicable regulations governing their operations.

Note 3: The requirements of this AD have been met when the engine manual changes are made and air carriers have modified their continuous airworthiness maintenance plans to reflect the requirements in the Engine Manuals.

Issued in Burlington, Massachusetts, on September 28, 2001.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 01-25399 Filed 10-9-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-CE-30-AD]

RIN 2120-AA64

Airworthiness Directives; Pilatus Aircraft Ltd. Model PC-7 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to adopt a new airworthiness directive (AD) that would apply to certain Pilatus Aircraft Ltd. (Pilatus) Model PC-7 airplanes. This proposed AD would require you to inspect the landing-gear emergency-extension cable for damage and replace if necessary; verify the correct installation of the bowden-cable conduit clamp and correct if necessary; and modify the temperature-control lever mechanism. This proposed AD is the result of mandatory continuing airworthiness information (MCAI)