# **Proposed Rules**

## Federal Register

Vol. 67, No. 56

Friday, March 22, 2002

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

# **SMALL BUSINESS ADMINISTRATION**

## 13 CFR Part 134

RIN 3245-AE71

Small Business Size Regulations; 8(a) Business Development/Small Disadvantaged Business Status Determinations; Rules of Procedure Governing Cases Before the Office of Hearings and Appeals; Correction

**AGENCY:** Small Business Administration. **ACTION:** Proposed rule; correction.

SUMMARY: This document corrects the text of the proposed rule published in the Federal Register on March 12, 2002, (67 FR 11057) and corrected in the Federal Register on March 21, 2002. The rule proposes to amend SBA's regulations governing proceedings before the Office of Hearings and Appeals and to make conforming changes to several sections of the regulations governing the Small Business Size Determination program and the 8(a) Business Development (8(a) BD) program.

FOR FURTHER INFORMATION CONTACT: Michael J. Wolter, 202–401–1420.

## Correction

In notice of proposed rulemaking document 02–5613 beginning on page 11057 in the issue of Tuesday, March 12, 2002, make the following corrections:

1. On page 11067, in the third column, correct § 134.313 to read as follows:

# § 134.313 Applicability of subpart B provisions.

Except where inconsistent with this subpart C, the provisions of subpart B of this part apply to appeals from size determinations and NAICS code designations.

# §134.406 [Corrected]

2. On page 11067, in the third column, correct amendatory instruction 50.c. to read as follows:

50. c. In paragraph (c), revise the first and fourth sentences; and add a new sentence at the end.

Dated: March 19, 2002.

## Gloria E. Blazsik,

Acting Assistant Administrator for Office of Hearings and Appeals.

[FR Doc. 02–6993 Filed 3–21–02; 8:45 am]

BILLING CODE 8025-01-P

# **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

# 14 CFR Part 39

[Docket No. 2000-NE-18-AD]

RIN 2120-AA64

Airworthiness Directives; Dowty Aerospace Propellers, Models R354, R375, R389, and R390 Propellers

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The Federal Aviation Administration (FAA) proposes to adopt a new airworthiness directive (AD) that is applicable to Dowty Aerospace Propellers, R354/4-123-F/13, R354/4-123-F/20, R375/4-123-F/21, R389/4-123-F/25, R389/4-123-F/26, and R390/ 4-123-F/27 propellers. This proposal would require a one-time inspection of the hub joint mating surfaces for fretting. This proposal is prompted by reports of fretting on the joint mating faces of propeller hubs. The actions specified by the proposed AD are intended to prevent failure of the hub due to loose hub through bolts.

**DATES:** Comments must be received by May 21, 2002.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000–NE–18–AD, 12 New England Executive Park, Burlington, MA 01803–5299. Comments may be inspected, by appointment, at this location between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. Comments may also be sent via the Internet using the following address: "9-ane-adcomment@faa.gov". Comments sent via the Internet must contain the docket

number in the subject line. The service information referenced in the proposed rule may be obtained from Dowty Aerospace Propellers, Anson Business Park, Cheltenham Road, East Gloucester GL2 9QN, UK; telephone 44 (0) 1452 716000; fax 44 (0) 1452 716001. This information may be examined, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

# FOR FURTHER INFORMATION CONTACT:

Frank Walsh, Aerospace Engineer, Boston Aircraft Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803–5299; telephone (781) 238–7158; fax (781) 238–7199.

#### SUPPLEMENTARY INFORMATION:

## **Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000–NE–18–AD." The postcard will be date stamped and returned to the commenter.

## Availability of NPRM's

Any person may obtain a copy of this NPRM by submitting a request to the

FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000–NE–18–AD, 12 New England Executive Park, Burlington, MA 01803–5299.

#### Discussion

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom (UK), recently notified the FAA that an unsafe condition may exist on certain Dowty propellers. The CAA advises that it has received a number of reports of fretting damage on the joint mating faces of certain Dowty propeller hubs. The CAA believes that the cause of the damage is excessive use of joint sealant during reassembly of the hub after repair or rework of the hub.

#### Manufacturer's Service Information

Dowty Aerospace Propellers has issued service bulletin (SB) SF340–61–96, dated April 18, 2000, that specifies procedures for inspecting certain propeller hubs for loose hub bolts, and if found, inspecting the mating faces of the hub joint for wear. The CAA classified this SB as mandatory and issued AD 005–04–2000 in order to assure the airworthiness of these Dowty propellers in the UK.

# **Bilateral Agreement Information**

This propeller model is manufactured in the UK and is type certificated for operation in the United States under the provisions of Section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. The FAA has examined the findings of the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

## Proposed Requirements of the AD

Since an unsafe condition has been identified that is likely to exist or develop on other Dowty Aerospace Propellers, R354/4-123-F/13, R354/4-123-F/20, R375/4-123-F/21, R389/4-123-F/25, R389/4-123-F/26, and R390/ 4–123–F/27 propellers of the same type design that are used on airplanes registered in the United States, the proposed AD would require inspection of hubs that have been disassembled since being delivered from Dowty Aerospace Propellers for loose hub through bolts within 1,800 flying hours after the effective date of the proposed AD. The proposed AD would also

require inspection of the mating faces of the hub joint for wear if any loose through bolts are found. These actions would be required to be done in accordance with the service bulletin described previously.

# **Economic Analysis**

There are approximately 418 propellers of the affected design in the worldwide fleet. The FAA estimates that 169 propellers installed on airplanes of U.S. registry would be affected by this proposed AD. The FAA also estimates that it would take approximately 6 work hours per propeller to do the proposed actions, and that the average labor rate is \$60 per work hour. There are no required parts per propeller. Based on these figures, the total cost of the proposed AD on U.S. operators is estimated to be \$60,840.

# **Regulatory Analysis**

This proposed rule does not have federalism implications, as defined in Executive Order 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this proposed rule.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Dowty Aerospace Propellers:** Docket No. 2000–NE–18–AD.

# Applicability

This airworthiness directive (AD) is applicable to Dowty Aerospace Propellers, R354/4–123–F/13, R354/4–123–F/20, R375/4–123–F/21, R389/4–123–F/25, R389/4–123–F/26, and R390/4–123–F/27 propellers. These propellers are installed on, but not limited to, SAAB 340A and 340B airplanes.

Note 1: This airworthiness directive (AD) applies to each propeller identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For propellers that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

### Compliance

Compliance with this AD is required within 1,800 flying hours after the effective date of this AD, unless already done.

To prevent failure of the hub due to loose

To prevent failure of the hub due to loose hub through bolts, do the following:

## One-time Inspection of the Propeller Hub

- (a) If the propeller hub has not been disassembled since it was received from Dowty Aerospace Propellers, no further action is required. Otherwise, do the following:
- (1) Within 1,800 flying hours after the effective date of this AD, perform a one-time inspection of the hub for loose hub through bolts in accordance with 3.A.(1) through 3.A.(10) of the Accomplishment Instructions of Dowty Aerospace Propellers service bulletin (SB) SF340–61–96, dated April 18, 2000.
- (2) If wear exceeds the limits specified in 3.A.(8) of the Accomplishment Instructions of Dowty Aerospace Propellers service bulletin (SB) SF340–61–96, dated April 18, 2000, replace the hub with a serviceable part.

# **Alternative Methods of Compliance**

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Boston Aircraft Certification Office (ACO). Operators must submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Boston ACO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Boston ACO.

## **Special Flight Permits**

(c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be done.

**Note 3:** The subject of this AD is addressed in CAA airworthiness directive 005–04–2000.

Issued in Burlington, Massachusetts, on March 14, 2002.

#### Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service. [FR Doc. 02–6914 Filed 3–21–02; 8:45 am] BILLING CODE 4910–13–U

# **DEPARTMENT OF TRANSPORTATION**

#### 14 CFR Part 71

[Airspace Docket No. 01-AGL-08]

Proposed Modification of Class E Airspace; Frankfort, MI; Correction

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking; correction.

**SUMMARY:** This action corrects the docket number and four errors in the legal description of a NPRM that was published in the **Federal Register** on Monday, January 7, 2002 (67 FR 705). The NPRM proposed to modify Class E Airspace at Frankfort, MI.

## FOR FURTHER INFORMATION CONTACT:

Denis C. Burke, Air Traffic Division, Airspace Branch, AGL–520, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, IL 60018, telephone: (847) 294–7477.

# SUPPLEMENTARY INFORMATION:

# History

Federal Register document 02–250 published on Monday, January 7, 2002 (67 FR 705), proposed to modify Class E Airspace at Frankfort, MI. An incorrect Airspace Docket No. 00–AGL–08 was assigned to the proposal, and in addition, the following errors were contained in the legal description: Incorrect longitude for the Frankfort Dow Memorial Field Airport, an incorrect MBL VOR/DME radial was used to describe the extension, and the latitude and longitude for the MBL

VOR/DME was omitted. This action corrects these errors.

Accordingly, pursuant to the authority delegated to me, the errors for the Class E Airspace, Frankfort, MI, as published in the **Federal Register** Monday, January 7, 2002 (67 FR 705), (FR Doc. 02–250), are corrected as follows:

1. On page 705, column 2, in the heading, and column 3, under "Comments Invited", correct the Airspace Docket No. to read "01–AGL–08"

# §71.1 [corrected]

- 2. On page 706, column 2, correct the legal description of the airspace designation as follows:
- a. Add the following immediately below "AGL MI E5 Frankfort, MI [REVISED]": Manistee VOR/DME (Lat. 44°16′14″ N., long 86°15′14″ W.)
- b. Correct the Frankfort Dow Memorial Field Airport longitude to read:

"Long. 86°12′02" W."

c. Correct "Manistee VOR/DME 186° radial" to read "Manistee VOR/DME 006° radial."

Issued in Des Plaines, Illinois on February 6, 2002

### Richard K. Petersen,

Assistant Manager, Air Traffic Division, Great Lakes Region.

[FR Doc. 02–5119 Filed 3–21–02; 8:45 am] **BILLING CODE 4910–13–M** 

## **DEPARTMENT OF THE INTERIOR**

## **National Indian Gaming Commission**

### 25 CFR Part 502

RIN 3141-AA10

Definitions: Electronic or Electromechanical Facsimile; Games Similar to Bingo; Electronic, Computer or Other Technologic Aid to Class II Games

**AGENCY:** National Indian Gaming Commission, Interior.

**ACTION:** Proposed Rule for Final Comment.

**SUMMARY:** The National Indian Gaming Commission (Commission) proposes to clarify the regulatory definitions of three key terms in the Indian Gaming Regulatory Act, "electronic and electromechanical facsimile", "games similar to bingo" and "electronic, computer or other technologic aid to Class II gaming". The Commission believes that these amendments may simplify the classification of games.

**DATES:** Comments may be submitted on or before April 22, 2002.

#### FOR FURTHER INFORMATION CONTACT:

Penny Coleman, at 202/632–7003 or, by fax, at 202/632–7066 (these are not toll-free numbers).

SUPPLEMENTARY INFORMATION: The Indian Gaming Regulatory Act (IGRA) 25 U.S.C. 2701-2721, enacted on October 17, 1988, established the Commission. Under the Act, the Commission is charged with regulating gaming by Indian tribes. On April 9, 1992, the Commission issued a final rule defining several key terms that were not fully defined in the statute. In light of the experience that it has developed in the past ten years in working with these definitions, the Commission believes that it may be time to reevaluate some of these definitions. Accordingly, on June 22, 2001, the Commission published a Proposed Rule seeking public comment on the proposed removal of the existing definition of "electronic or electromechanical facsimile" from the Commission's regulations and using instead the plain language interpretation that seems to have been preferred by the courts.

The Commission received numerous comments to this proposed rule, a majority of which indicated support for the proposal. However, even many of the supportive comments expressed the view that removing the current definition was merely a first step in addressing the questions at issue. Several comments indicated that the Commission should remove the definition and replace it with another definition providing additional substantive guidance.

The Commission addresses these comments by proposing a new definition of "electronic or electromechanical facsimile." In light of the comments, the Commission also proposes changes to two related definitions for which it seeks additional comment.

## **Regulatory Flexibility Act**

To the extent that tribal gaming operations may be considered small businesses and therefore small entities under the Regulatory Flexibility Act, 5 U.S.C. 601 *et seq.*, this rule will not have a significant economic effect on a substantial number of small entities. Indian Tribes are not considered to be small entities for the purposes of the Regulatory Flexibility Act.

# **Small Business Regulatory Enforcement Fairness Act**

This rule is not a major rule under 5 U.S.C. 804(2), the Small Business