

DEPARTMENT OF TRANSPORTATION
Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-CE-10-AD; Amendment 39-12644; AD 2002-03-03]

RIN 2120-AA64

Airworthiness Directives; SOCATA—Groupe AEROSPATIALE Model TBM 700 Airplanes

AGENCY: Federal Aviation Administration, DOT.
ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to certain SOCATA—Groupe AEROSPATIALE (SOCATA) Model TBM 700 airplanes. This AD requires you to install a new strainer draining system in the cabin fuselage. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for France. The actions specified by this AD are intended to prevent water from accumulating in the fuselage, then freezing and interfering with or causing the elevator controls to seize. This could result in loss of elevator control with consequent loss of airplane control.

DATES: This AD becomes effective on March 29, 2002.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of March 29, 2002.

ADDRESSES: You may get the service information referenced in this AD from SOCATA—Groupe AEROSPATIALE, Customer Support, Aerodrome Tarbes-Ossun-Lourdes, BP 930-F65009 Tarbes Cedex, France; telephone: (33) (0)5.62.41.73.00; facsimile: (33) (0)5.62.41.76.54; or the Product Support Manager, SOCATA—Groupe AEROSPATIALE, North Perry Airport,

7501 Pembroke Road, Pembroke Pines, Florida 33023; telephone: (954) 893-1400; facsimile: (954) 964-4191. You may view this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2001-CE-10-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

What Events Have Caused This AD?

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, recently notified FAA that an unsafe condition may exist on certain SOCATA Model TBM 700 airplanes. The DGAC reports an incident in which the elevator controls jammed on one of the affected airplanes.

Jamming of the elevator controls occurred because water accumulated in the fuselage and froze. Water had accumulated in the fuselage because the strainer and draining hole became clogged.

What Is the Potential Impact if FAA Took No Action?

If this condition is not corrected, water may accumulate in the fuselage, freeze and interfere with or cause the elevator controls to seize. This could result in loss of elevator control.

Has FAA Taken Any Action to This Point?

We issued a proposal to amend part 39 of the Federal Aviation Regulations

(14 CFR part 39) to include an AD that would apply to certain SOCATA Model TBM 700 airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on November 14, 2001 (66 FR 57007). The NPRM proposed to require you to install a new strainer draining system in the cabin fuselage.

Was the Public Invited To Comment?

The FAA encouraged interested persons to participate in the making of this amendment. We did not receive any comments on the proposed rule or on our determination of the cost to the public.

FAA's Determination

What Is FAA's Final Determination on This Issue?

After careful review of all available information related to the subject presented above, we have determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. We have determined that these minor corrections:

—provide the intent that was proposed in the NPRM for correcting the unsafe condition; and

—do not add any additional burden upon the public than was already proposed in the NPRM.

Cost Impact

How Many Airplanes Does This AD Impact?

We estimate that this AD affects 79 airplanes in the U.S. registry.

What Is the Cost Impact of This AD on Owners/Operators of the Affected Airplanes?

We estimate the following costs to accomplish the modification:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
2 workhours × \$60 = \$120	\$114	\$234	\$18,486

Compliance Time of This AD

What Is the Compliance Time of This AD?

The compliance time of this AD is “within the next 3 months after the effective date of this AD”.

Why Is the Compliance Time Presented in Calendar Time Instead of Hours Time-in-Service (TIS)?

Although water in the cabin fuselage could interfere with the elevator controls and become unsafe during flight, the condition is not a direct result of airplane operation. The chance of this situation occurring is the same for an airplane with 10 hours time-in-service (TIS) as it would be for an airplane with

500 hours TIS. A calendar time for compliance will assure that the unsafe condition is addressed on all airplanes in a reasonable time period.

Regulatory Impact

Does This AD Impact Various Entities?

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States,

or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

Does This AD Involve a Significant Rule or Regulatory Action?

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy

of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

Actions	Compliance	Procedures
Incorporate Kit No. OPT70 K072-53	Within the next 3 months after March 29, 2002 (the effective date of this AD), unless already accomplished.	In accordance with the Technical Instructions supplied with Kit No. OPT70 K072-53, as specified in Socata Service Bulletin SB 70-082 53, dated June 2000.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and
(2) The Manager, Standards Office, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standards Office, Small Airplane Directorate.

Note 1: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; facsimile: (816) 329-4090.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location

where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with the Technical Instructions supplied with Kit No. OPT70 K072-53, as specified in Socata Service Bulletin SB 70-082 53, dated June 2000. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from SOCATA—Groupe AEROSPATIALE, Customer Support, Aerodrome Tarbes-Ossun-Lourdes, BP 930—F65009 Tarbes Cedex, France; or the Product Support Manager, SOCATA—Groupe AEROSPATIALE, North Perry Airport, 7501 Pembroke Road, Pembroke Pines, Florida 33023. You can look at copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Note 2: The subject of this AD is addressed in French AD 2000-373(A), dated October 18, 2000.

(i) *When does this amendment become effective?* This amendment becomes effective on March 29, 2002.

Issued in Kansas City, Missouri, on February 4, 2002.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-3167 Filed 2-13-02; 8:45 am]

BILLING CODE 4910-13-U

§ 39.13 [Amended]

2. FAA amends § 39.13 by adding a new AD to read as follows:

2002-03-03 Socata—Groupe Aerospatiale:
Amendment 39-12644; Docket No. 2001-CE-10-AD.

(a) *What airplanes are affected by this AD?* This AD affects Model TBM 700 airplanes, serial numbers 1 through 164, that are certificated in any category.

(b) *Who must comply with this AD?* Anyone who wishes to operate any of the airplanes identified in paragraph (a) of this AD must comply with this AD.

(c) *What problem does this AD address?* The actions specified by this AD are intended to prevent water from accumulating in the fuselage, then freezing and interfering with or causing the elevator controls to seize. This could result in loss of elevator control with consequent loss of airplane control.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-266-AD; Amendment 39-12651; AD 2002-03-10]

RIN 2120-AA64

Airworthiness Directives; BAE Systems (Operations) Limited Model BAe 146 Series Airplanes and Model Avro 146-RJ Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ series airplanes, that requires repetitive inspections to detect cracking of the oleo strut of the nose landing gear (NLG), and corrective actions if necessary. This AD also provides for optional terminating action for the repetitive inspections. This action is necessary to detect and correct fatigue cracking of the oleo strut of the NLG, which could result in failure of the NLG. This action is intended to address the identified unsafe condition.

DATES: Effective March 21, 2002.

The incorporation by reference of certain publications listed in the