

Proposed Rules

Federal Register

Vol. 68, No. 17

Monday, January 27, 2003

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF AGRICULTURE

Animal and Plant Health Inspection Service

9 CFR Part 71

[Docket No. 99-017-2]

RIN 0579-AB13

Blood and Tissue Collection at Slaughtering Establishments

AGENCY: Animal and Plant Health Inspection Service, USDA.

ACTION: Proposed rule; extension of comment period.

SUMMARY: We are extending the comment period for our proposed rule regarding the collection of blood and tissue samples at slaughtering establishments. In that document, we proposed, among other things, to establish requirements for the collection of blood and tissue samples from livestock (horses, cattle, bison, captive cervids, sheep and goats, swine, and other farm animals) and poultry at slaughtering establishments when it is necessary for disease surveillance. This action will allow interested persons additional time to prepare and submit comments.

DATES: We will consider all comments that we receive on or before March 28, 2003.

ADDRESSES: You may submit comments by postal mail/commercial delivery or by e-mail. If you use postal mail/commercial delivery, please send four copies of your comment (an original and three copies) to: Docket No. 99-017-1, Regulatory Analysis and Development, PPD, APHIS, Station 3C71, 4700 River Road Unit 118, Riverdale, MD 20737-1238. Please state that your comment refers to Docket No. 99-017-1. If you use e-mail, address your comment to regulations@aphis.usda.gov. Your comment must be contained in the body of your message; do not send attached files. Please include your name and address in your message and "Docket No. 99-017-1" on the subject line.

You may read any comments that we receive on Docket No. 99-017-1 in our reading room. The reading room is located in room 1141 of the USDA South Building, 14th Street and Independence Avenue SW., Washington, DC. Normal reading room hours are 8 a.m. to 4:30 p.m., Monday through Friday, except holidays. To be sure someone is there to help you, please call (202) 690-2817 before coming.

APHIS documents published in the **Federal Register**, and related information, including the names of organizations and individuals who have commented on APHIS dockets, are available on the Internet at <http://www.aphis.usda.gov/ppd/rad/webpor.html>.

FOR FURTHER INFORMATION CONTACT: Dr. Adam Grow, National Animal Health Programs, VS, APHIS, 4700 River Road Unit 43, Riverdale, MD 20737-1231; (301) 734-4363.

SUPPLEMENTARY INFORMATION:

Background

On November 27, 2002, we published in the **Federal Register** (67 FR 70864-70875, Docket No. 99-017-1) a proposal to amend the regulations in 9 CFR part 71 to establish requirements for the collection of blood and tissue samples from livestock (horses, cattle, bison, captive cervids, sheep and goats, swine, and other farm animals) and poultry at slaughtering establishments when it is necessary for disease surveillance. We also proposed to require that livestock or poultry moved interstate for slaughter be moved only to a slaughtering establishment that has been listed by the Administrator and provided proposed criteria for the listing of establishments.

Comments on the proposed rule were required to be received on or before January 27, 2003. We are extending the comment period on Docket No. 99-017-1 for an additional 60 days, ending March 28, 2003. This action will allow interested persons additional time to prepare and submit comments.

Authority: 7 U.S.C. 8304-8306, 8308, 8310, 8313, and 8315; 7 CFR 2.22, 2.80, and 371.4.

Done in Washington, DC, this 21st day of January 2003.

Kevin Shea,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 03-1752 Filed 1-24-03; 8:45 am]

BILLING CODE 3410-34-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-CE-44-AD]

RIN 2120-AA64

Airworthiness Directives; The New Piper Aircraft, Inc. Models PA-23, PA-23-160, PA-23-235, PA-23-250, and PA-E23-250 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to adopt a new airworthiness directive (AD) that would apply to certain The New Piper Aircraft, Inc. (Piper) Models PA-23, PA-23-160, PA-23-235, PA-23-250, and PA-E23-250 airplanes that do not incorporate a certain design flap control torque tube or torque tube assembly. This proposed AD would require you to repetitively inspect the flap control torque tube for cracks, corrosion, wear, or elongation of the attachment bolt holes (referred to as damage hereon); and would require you to replace any damaged torque tube with either an improved design flap control torque tube or flap control torque tube assembly. The repetitive inspections would no longer be necessary when the improved design torque tube or torque tube assembly is installed. This proposed AD is the result of several reports of damage found in the flap control torque tube on the affected airplanes. The actions specified by this proposed AD are intended to detect and correct damage to the flap control torque tube, which could result in failure of the flap operating system. If such failure occurred during landing or takeoff, then a split flap condition could occur with potential loss of control of the airplane.

DATES: The Federal Aviation Administration (FAA) must receive any

comments on this proposed rule on or before March 21, 2003.

ADDRESSES: Submit comments to FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2002-CE-44-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. You may view any comments at this location between 8 a.m. and 4 p.m., Monday through Friday, except Federal holidays. You may also send comments electronically to the following address: 9-ACE-7-Docket@faa.gov. Comments sent electronically must contain "Docket No. 2002-CE-44-AD" in the subject line. If you send comments electronically as attached electronic files, the files must be formatted in Microsoft Word 97 for Windows or ASCII text.

You may get service information that applies to this proposed AD from The New Piper Aircraft, Inc., Customer Services, 2926 Piper Drive, Vero Beach, Florida 32960; telephone: (561) 567-4361; facsimile: (772) 978-6573. You may also view this information at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Hassan Amini, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, Georgia 30349; telephone: (770) 703-6080; facsimile: (770) 703-6097.

SUPPLEMENTARY INFORMATION:

Comments Invited

How Do I Comment On This Proposed AD?

The FAA invites comments on this proposed rule. You may submit whatever written data, views, or arguments you choose. You need to include the rule's docket number and submit your comments to the address specified under the caption **ADDRESSES**. We will consider all comments received on or before the closing date. We may amend this proposed rule in light of comments received. Factual information that supports your ideas and suggestions is extremely helpful in evaluating the effectiveness of this proposed AD action and determining whether we need to take additional rulemaking action.

Are There Any Specific Portions of This Proposed AD I Should Pay Attention to?

The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this proposed rule that might suggest a need to modify the rule. You may view all comments we receive before and after the closing date of the rule in the Rules Docket. We will file a report in the Rules Docket that summarizes each contact we have with the public that concerns the substantive parts of this proposed AD.

How Can I Be Sure FAA Receives My Comment?

If you want FAA to acknowledge the receipt of your mailed comments, you must include a self-addressed, stamped postcard. On the postcard, write "Comments to Docket No. 2002-CE-44-AD." We will date stamp and mail the postcard back to you.

Discussion

What Events Have Caused This Proposed AD?

A review of FAA's service difficulty report (SDR) database shows several incidents of cracks and corrosion in the flap control torque tube on Piper PA-23 series airplanes. One incident of a broken flap control torque tube resulted in a split flap condition during approach.

What Are the Consequences If the Condition Is Not Corrected?

Cracked or corroded flap torque tubes, if not detected and corrected, could result in damage to the flap control torque tube and failure of the flap operating system. If such failure occurred during landing or takeoff, then a split flap condition could occur with potential loss of control of the airplane.

Is There Service Information That Applies to This Subject?

Piper has issued Mandatory Service Bulletin No. 1051B, dated November 5, 2002.

What Are the Provisions of This Service Information?

The service bulletin includes procedures for:

- Inspecting the flap control torque tube for cracks, corrosion, wear, or

elongation of the attachment bolt holes; and

- Installing a part number (P/N 17634-002 flap control torque tube; or a P/N 104622-002 or 104622-004 flap control torque tube assembly.

The FAA's Determination and an Explanation of the Provisions of This Proposed AD

What Has FAA Decided?

After examining the circumstances and reviewing all available information related to the incidents described above, we have determined that:

- The unsafe condition referenced in this document exists or could develop on other Models PA-23, PA-23-160, PA-23-235, PA-23-250, and PA-E23-250 airplanes of the same type design that do not incorporate a certain flap control torque tube or torque tube assembly;
- The actions specified in the previously-referenced service information should be accomplished on the affected airplanes; and
- AD action should be taken in order to correct this unsafe condition.

What Would This Proposed AD Require?

This proposed AD would require you to repetitively inspect the flap control torque tube for cracks, corrosion, wear, or elongation of the attachment bolt holes; and would require you to replace any damaged flap control torque tube with either an improved design flap control torque tube or flap control torque tube assembly. The repetitive inspections would no longer be necessary when the improved design flap control torque tube or flap control torque tube assembly is installed.

Cost Impact

How Many Airplanes Would This Proposed AD Impact?

We estimate that this proposed AD affects 3,733 airplanes in the U.S. registry.

What Would Be the Cost Impact of This Proposed AD on Owners/Operators of the Affected Airplanes?

We estimate the following costs to accomplish each proposed inspection:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
8 workhours × \$60 per hour = \$480	None for inspection	\$480	\$1,791,840

We estimate the following costs to accomplish any necessary replacement that would be required based on the results of the proposed inspection. We have no way of determining the number of airplanes that may need such repair/replacement:

Labor cost	Parts cost	Total cost per airplane
4 workhours × \$60 per hour = \$240	\$452 per airplane	\$692

Regulatory Impact

Would This Proposed AD Impact Various Entities?

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposed rule would not have federalism implications under Executive Order 13132.

Would This Proposed AD Involve a Significant Rule or Regulatory Action?

For the reasons discussed above, I certify that this proposed action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action has been placed in the Rules

Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends § 39.13 by adding a new airworthiness directive (AD) to read as follows:

The New Piper Aircraft, Inc.: Docket No. 2002-CE-44-AD.

(a) *What airplanes are affected by this AD?* This AD affects the following airplane

models and serial numbers that are certificated in any category and do not incorporate a part number (P/N) 17634-002 flap control torque tube; or a P/N 104622-002 or 104622-004 flap control torque tube assembly:

Model	Serial Nos.
PA-23 and PA-23-160.	23-1 through 23-2046.
PA-23-235 PA-23-250	27-505 through 27-622. 27-1 through 27-504 and 27-2000 through 27-8154030.
PA-E23-250	27-2505 through 27-4916 and 27-7304917 through 27-7554168.

(b) *Who must comply with this AD?*

Anyone who wishes to operate any of the airplanes identified in paragraph (a) of this AD must comply with this AD.

(c) *What problem does this AD address?*

The actions specified by this AD are intended to detect and correct damage to the flap control torque tube, which could result in failure of the flap operating system. If such failure occurred during landing or takeoff, then a split flap condition could occur with potential loss of control of the airplane.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Actions	Compliance	Procedures
(1) Inspect the flap control torque tube for cracks, corrosion, wear, or elongation of the attachment bolt holes (referred to as damage hereon).	Initially inspect upon accumulating 2,500 hours time-in-service (TIS) on the flap control torque tube or within the next 100 hours TIS after the effective date of this AD, whichever occurs later. Repetitively inspect thereafter at intervals not to exceed 500 hours TIS until one of the parts specified in paragraph (d) of this AD is installed.	In accordance with sections 3 through 10 of the ACCOMPLISHMENT INSTRUCTIONS section of Piper Mandatory Service Bulletin No. 1051B, dated November 5, 2002.
(2) Replace any damage flap control torque tube and replace any wooden end plugs with new plastic end plugs, P/N 17631-002. Replace the flap control torque tubes with either a P/N 17634-002 flap control torque tube or a P/N 104622-002 or 104622-004 flap control torque tube assembly. (i) The P/N 17631-002 end plugs are part of the P/N 104622-002 and 104622-004 flap control torque tube assemblies, but must be obtained for the P/N 17634-002 installation. (ii) You do not have to inspect the existing wooden end plugs as specified in the service bulletin since this AD requires the installation of plastic and plugs.	Prior to further flight after the inspection where damage is found.	In accordance with sections 3 through 10 of the ACCOMPLISHMENT INSTRUCTIONS section of Piper Mandatory Service Bulletin No. 1051B, dated November 5, 2002.
(3) The repetitive inspections required by this AD may be terminated after installation of a replacement flap control torque tube or flap control torque tube assembly as specified in paragraph (d) of this AD.	You may replace the flap control torque tube assembly at any time, but must replace prior to further flight if damage is found during an inspection.	In accordance with sections 3 through 10 of the ACCOMPLISHMENT INSTRUCTIONS section of Piper Mandatory Service Bulletin No. 1051B, dated November 5, 2002.

Actions	Compliance	Procedures
(4) Only install, on any affected airplane, a flap control torque tube or flap control torque tube assembly and end plugs that incorporate the part numbers specified in paragraph (d) of this AD.	As of the effective date of this AD	In accordance with sections 3 through 10 of the ACCOMPLISHMENT INSTRUCTIONS section of Piper Mandatory Service Bulletin No. 1051B, dated November 5, 2002.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Atlanta Aircraft Certification Office, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta Aircraft Certification Office.

Note: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Hassan Amini, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, Georgia 30349; telephone: (770) 703-6080; facsimile: (770) 703-6097.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *How do I get copies of the documents referenced in this AD?* You may get copies of the documents referenced in this AD from The New Piper Aircraft, Inc., Customer Services, 2926 Piper Drive, Vero Beach, Florida 32960; telephone: (561) 567-4361; facsimile: (772) 978-6573. You may view these documents at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on January 15, 2003.

Michael Gallagher,

Manager, Small Airplane Directorate, ,
Aircraft Certification Service.

[FR Doc. 03-1679 Filed 1-24-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 93-CE-37-AD]

RIN 2120-AA64

Airworthiness Directives; Raytheon Aircraft Company Beech Models C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, and V35B Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to revise Airworthiness Directive (AD) 94-20-04 R1, which currently requires ruddervator inspections and modifications on certain Raytheon Aircraft Company (Raytheon) Beech Models C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, and V35B airplanes. This proposed AD is the result of the need to add a repetitive inspection of the fuselage bulkheads and change other inspections from a repetitive to a one-time action. The proposed AD would make these changes to AD 94-20-04 R1. The actions specified by the proposed AD are intended to prevent structural failure of the V-tail, which could result in loss of control of the airplane.

DATES: The Federal Aviation Administration (FAA) must receive any comments on this proposed rule on or before March 3, 2003.

ADDRESSES: Submit comments in triplicate to FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 93-CE-37-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from the Raytheon Aircraft Company, PO Box 85, Wichita, Kansas 67201-0085; telephone: (800) 625-7043 or (316) 676-4556. This information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Mr. T.N. Baktha, Aerospace Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4155; facsimile: (316) 946-4407.

SUPPLEMENTARY INFORMATION:

Comments Invited

How Do I Comment on the Proposed AD?

The FAA invites comments on this proposed rule. You may submit whatever written data, views, or arguments you choose. You need to include the rule's docket number and submit your comments in triplicate to the address specified under the caption **ADDRESSES**. The FAA will consider all comments received on or before the closing date. We may amend the proposed rule in light of comments received. Factual information that supports your ideas and suggestions is extremely helpful in evaluating the effectiveness of the proposed AD action and determining whether we need to take additional rulemaking action.

Are There Any Specific Portions of the Proposed AD I Should Pay Attention to?

The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of the proposed rule that might suggest a need to modify the rule. You may examine all comments we receive before and after the closing date of the rule in the Rules Docket. We will file a report in the Rules Docket that summarizes each FAA contact with the public that concerns the substantive parts of the proposed AD.

How Can I Be Sure FAA Receives My Comment?

If you want us to acknowledge the receipt of your comments, you must include a self-addressed, stamped postcard. On the postcard, write "Comments to Docket No. 93-CE-37-AD." We will date stamp and mail the postcard back to you.