

(1) For Model A330 series airplanes: Inspect before the accumulation of 16,500 total flight cycles or 51,400 total flight hours, whichever occurs first.

(2) For Model A340 series airplanes, pre-Modification 41300: Inspect before the accumulation of 14,500 total flight cycles or 75,400 total flight hours, whichever occurs first.

(3) For Model A340 series airplanes, post-Modification 41300: Inspect before the accumulation of 13,400 total flight cycles or 70,000 total flight hours, whichever occurs first.

(b) A modification done before the effective date of this AD in accordance with Airbus Service Bulletin A330-57-3055 or A340-57-4062, both dated November 28, 2001, is acceptable for compliance with the applicable requirements of this AD.

#### Repair

(c) If any crack is found during an inspection required by paragraph (a) of this AD: Before further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the Direction Générale de l'Aviation Civile (or its delegated agent).

#### Alternative Methods of Compliance

(d) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, is authorized to approve alternative methods of compliance for this AD.

**Note 1:** The subject of this AD is addressed in French airworthiness directives 2001-578(B) and 2001-579(B), both dated November 28, 2001.

Issued in Renton, Washington, on November 21, 2003.

**Vi L. Lipski,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 03-29696 Filed 11-26-03; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2002-NM-14-AD]

RIN 2120-AA64

#### Airworthiness Directives; Boeing Model 777 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 777 series airplanes. This proposal would require replacement of the cargo control joysticks with new joysticks that

include a moisture seal and ventilated cover. This action is necessary to prevent water from being trapped inside the joystick covers, which could result in uncommanded movements of the power drive unit during ground handling of cargo and consequent possible injury to ground personnel. This action is intended to address the identified unsafe condition.

**DATES:** Comments must be received by January 12, 2004.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-14-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: [9-anm-nprmcomment@faa.gov](mailto:9-anm-nprmcomment@faa.gov). Comments sent via fax or the Internet must contain "Docket No. 2002-NM-14-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Clint Jones, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6471; fax (425) 917-6590.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.

- For each issue, state what specific change to the proposed AD is being requested.

- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-14-AD." The postcard will be date stamped and returned to the commenter.

#### Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-14-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

#### Discussion

The FAA has received reports of uncommanded movements of the power drive unit (PDU) after the joystick was returned to neutral position during cargo bay operations on certain Boeing Model 777 series airplanes. Investigation revealed that water trapped inside the joystick cover could lead to circuit board corrosion and leakage currents. This condition, if not corrected, could result in uncommanded movements of the PDU during ground handling of cargo and consequent possible injury to ground personnel.

#### Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Service Bulletin 777-25-0191, dated September 13, 2001, which describes procedures for replacement of the cargo control joysticks with new joysticks that include a moisture seal and ventilated cover. Accomplishment of the actions specified in the service

bulletin is intended to adequately address the identified unsafe condition.

### Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously, except as discussed below.

### Differences Between Proposed Rule and Service Bulletin

Operators should note that, although the service bulletin recommends accomplishing the replacement at the next normally scheduled maintenance period, the FAA has determined that such an imprecise compliance time would not address the identified unsafe condition in a timely manner. In developing an appropriate compliance time for this proposed AD, the FAA considered not only the manufacturer's recommendation, but the degree of urgency associated with addressing the subject unsafe condition, the average utilization of the affected fleet, and the time necessary to perform the inspection (three hours). In light of all of these factors, the FAA finds an 18-month compliance time for completing the required actions to be warranted, in that it represents an appropriate interval of time allowable for affected airplanes to continue to operate without compromising safety.

### Cost Impact

There are approximately 360 airplanes of the affected design in the worldwide fleet. The FAA estimates that 124 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 3 work hours per airplane to accomplish the proposed replacement, and that the average labor rate is \$65 per work hour. Required parts would cost approximately \$2,200 per airplane. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$296,980, or \$2,395 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time

required to gain access and close up, planning time, or time necessitated by other administrative actions. The manufacturer may cover the cost of replacement parts associated with this proposed AD, subject to warranty conditions. Manufacturer warranty remedies may also be available for labor costs associated with this proposed AD. As a result, the costs attributable to the proposed AD may be less than stated above.

### Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Boeing:** Docket 2002–NM–14–AD.

**Applicability:** Model 777 series airplanes, as listed in Boeing Service Bulletin 777–25–

0191, dated September 13, 2002, certificated in any category.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent uncommanded movements of the power drive unit during ground handling of cargo and consequent possible injury to ground personnel, accomplish the following:

### Replacement

(a) Within 18 months after the effective date of this AD, replace the cargo control joysticks with new joysticks, per the Accomplishment Instructions of Boeing Service Bulletin 777–25–0191, dated September 13, 2002.

### Parts Installation

(b) As of the effective date of this AD, no person shall install a cargo control joystick, part number S283W602–1 or S283W602–2, on any airplane.

### Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance for this AD.

Issued in Renton, Washington, on November 21, 2003.

**Vi L. Lipski,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 03–29697 Filed 11–26–03; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

### 14 CFR Part 39

[Docket No. 2003–NM–154–AD]

RIN 2120–AA64

### Airworthiness Directives; Bombardier Model DHC–8–102, –103, –106, –201, –202, –301, –311, and –315 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Bombardier Model DHC–8–102, –103, –106, –201, –202, –301, –311, and –315 series airplanes. This proposal would require repetitive inspections for discrepancies of certain rear spar fittings between the flex shaft of the flap secondary drive and the wing-to-fuselage structure, and corrective action if necessary. This proposal also provides for an optional modification of the flex shaft installation, which would terminate the repetitive inspections. This action is necessary to find and fix