

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2002-SW-25-AD]

RIN 2120-AA64

Airworthiness Directives; Schweizer Aircraft Corporation Model 269A, 269A-1, 269B, 269C, and TH-55A Helicopters**AGENCY:** Federal Aviation Administration, DOT.**ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD) that applies to Schweizer Aircraft Corporation (Schweizer) Model 269A, 269A-1, 269B, 269C, and TH-55A helicopters. That AD currently requires inspecting the lugs on certain aft cluster fittings, and each aluminum end fitting on certain tailboom struts. Modifying or replacing each strut assembly within a specified time period and serializing certain strut assemblies are also required by the existing AD. This proposed AD would require the same actions as the existing AD, would require a one-time inspection and repair, if necessary, of certain additional cluster fittings, and would require replacement and modification of certain cluster fittings within 150 hours time-in-service (TIS) or 6 months, whichever occurs first. This proposal is prompted by the need to expand the applicability to include certain Hughes-manufactured cluster fittings and to provide a terminating action for the repetitive-dye-penetrant inspections of the cluster fittings. The actions specified by the proposed AD are intended to prevent failure of a tailboom support strut or a cluster fitting, which could cause rotation of a tailboom into the main rotor blades, and subsequent loss of control of the helicopter.

DATES: Comments must be received on or before April 28, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 2002-SW-25-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. You may also send comments electronically to the Rules Docket at the following address: 9-asw-adcomments@faa.gov. Comments may be inspected at the Office of the Regional Counsel between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT:

George Duckett, Aviation Safety Engineer, FAA, New York Aircraft Certification Office, Airframe and Propulsion Branch, 10 Fifth Street, 3rd Floor, Valley Stream, New York, telephone (516) 256-7525, fax (516) 568-2716.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments will be considered before taking action on the proposed rule. The proposals contained in this document may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their mailed comments submitted in response to this proposal must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 2002-SW-25-AD." The postcard will be date stamped and returned to the commenter.

Discussion

On April 12, 2002, the FAA issued AD 2001-25-52, Amendment 39-12726 (67 FR 19646, April 23, 2002), to require the following:

- Within 10 hours TIS and thereafter at intervals not to exceed 50 hours TIS, dye-penetrant inspect and replace, if necessary, each cluster fitting, part number (P/N) 269A2234 and P/N 269A2235;
- At intervals not to exceed 50 hours TIS, visually inspect the strut aluminum end fittings for deformation or damage, dye-penetrant inspect the strut aluminum end fittings for a crack, and replace deformed, damaged, or cracked parts.
- Within 500 hours TIS or one year, whichever occurs first, modify or replace the strut assemblies.

- Within 100 hours TIS, for Model 269C helicopters, serialize each strut assembly, P/N 269A2015-5 and 269A2015-11.

That action was prompted by an accident in the United Kingdom involving the in-flight structural failure of a Model 269C helicopter. The requirements of that AD are intended to prevent failure of a lug on a cluster fitting, which could result in rotation of a tailboom into the main rotor blades, and subsequent loss of control of the helicopter. The existing AD, which superseded AD 76-18-01 (41 FR 37093, September 2, 1976), includes a reference to inspecting the center attachment fitting. However, AD 93-21-03 (58 FR 59944, November 12, 1993), Docket 91-ASW-11, addressed the unsafe conditions of the center attachment fitting and it is unnecessary to further address those issues in this proposed AD.

Since the issuance of the existing AD, the FAA has determined that the pool of cluster fittings that needs inspecting should be expanded to include certain Hughes-manufactured cluster fittings that were inadvertently omitted from the applicability of the existing AD because of the failure to include Hughes-manufactured P/N's, 269A2234-3 and 269A2235-3, in the applicability. Also, the manufacturer has completed the development of a modification kit for the cluster fitting that can serve as a terminating action for the repetitive 50-hour TIS dye-penetrant inspection.

The unsafe condition described previously is likely to exist or develop on other helicopters of the same type designs. Therefore, the proposed AD would supersede AD 2001-25-52 to require the following:

- Within 10 hours TIS and thereafter at intervals not to exceed 50 hours TIS, dye-penetrant inspect the lugs and replace any cracked cluster fitting.
- Within 150 hours TIS or 6 months, whichever occurs first, replace or modify, using kit, P/N SA-269K-106-1, each cluster fitting, P/N 269A2234 and P/N 269A2235.
- For strut assemblies, P/N 269A2015 or P/N 269A2015-5, at intervals not to exceed 50 hours TIS, visually inspect the strut aluminum end fittings for deformation or damage, dye-penetrant inspect the strut aluminum end fittings for a crack, and replace deformed, damaged, or cracked parts. Within 500 hours TIS or one year, whichever occurs first, modify or replace certain part-numbered strut assemblies.
- Within 100 hours TIS, for Model 269C helicopters, serialize each strut

assembly, P/N 269A2015-5 and 269A2015-11.

- Within 25 hours TIS or 60 days, whichever occurs first, inspect and repair cluster fittings, P/N 269A2234-3 and P/N 269A2235-3.

- Before further flight, replace any cluster fitting that is cracked or has a surface defect beyond rework limits.

The FAA estimates that 1,000 helicopters of U.S. registry would be affected by this proposed AD. It would take approximately 2.5 work hours for each dye-penetrant inspection, 12 work hours to replace one cluster fitting, 4 work hours to modify or replace the strut assembly, 0.25 work hours to serialize the strut assembly, and 16 work hours to modify a cluster fitting. The average labor rate is \$60 per work hour. Required parts would cost approximately \$5 for each fitting inspection, \$1,635 to replace a cluster fitting, \$1,500 to modify or replace the strut assembly, and \$1,688 for each cluster fitting modification kit (2 fittings). Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$2,260,320 (assuming 2,000 cluster fittings are inspected, 50 cluster fittings are replaced, 6 strut assemblies are modified or replaced, 6 strut assemblies

are serialized, and 1,010 cluster fittings are modified).

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-12726 (67 FR 19646, April 23, 2002), and by adding a new airworthiness directive (AD), to read as follows:

Schweizer Aircraft Corporation: Docket No. 2002-SW-25-AD. Supersedes AD 2001-25-52, Amendment 39-12726, Docket No. 2001-SW-58-AD.

Applicability: Model 269A, 269A-1, 269B, 269C, and TH-55A helicopters, certificated in any category, with a tailboom support strut (strut) assembly, part number (P/N) 269A2015 or 269A2015-5; or with a center frame aft cluster fitting, P/N 269A2234 or 269A2235, and an aft cluster fitting listed in the following table:

Helicopter model number	Helicopter serial number	With aft cluster fitting, P/N
Model 269C	0570 through 1165	269A2234-3
Model 269C	0500 through 1165	269A2235-3
Model 269A, A-1, B, or C, or TH-55A	All	269A2234-3 or 269A2235-3

Exception: For the Model 269A, A-1, B, or C or TH-55A helicopters with Hughes-manufactured cluster fittings, P/N 269A2234-3 or P/N 269A2235-3, installed, if there is written documentation in the aircraft or manufacturer's records that shows the cluster fitting was originally sold by Hughes after June 1, 1988, the requirements of this AD are not applicable.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified,

altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (h) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of a tailboom support strut or lug on a cluster fitting, which could


cause rotation of a tailboom into the main rotor blades, and subsequent loss of control of the helicopter, accomplish the following:

(a) Within 10 hours time-in-service (TIS), and thereafter at intervals not to exceed 50 hours TIS, for helicopters with cluster fittings, P/N 269A2234 or P/N 269A2235:

(1) Using paint remover, remove paint from the lugs on each cluster fitting. Wash with water and dry. The tailboom support strut must be removed prior to the paint stripping.

(2) Dye-penetrant inspect the lugs on each cluster fitting. See the following Figure 1:

BILLING CODE 4910-13-P

**Figure 1****BILLING CODE 4910-13-C**

(3) If a crack is found, before further flight, replace the cracked cluster fitting with an airworthy cluster fitting.

(b) Cluster fittings, P/N 269A2234 and P/N 269A2235, that have NOT been modified with Kit P/N SA-269K-106-1, are NOT eligible replacement parts.

(c) Within 150 hours TIS or 6 months, whichever occurs first, replace each cluster fitting, P/N 269A2234 and P/N 269A2235, with an airworthy cluster fitting or modify each cluster fitting, P/N 269A2234 and P/N 269A2235, with Kit, P/N SA-269K-106-1. Installing the kit is terminating action for the 50-hour TIS repetitive dye-penetrant inspection for these cluster fittings. Broken or cracked cluster fittings are not eligible for the kit modification.

(d) For helicopters with strut assemblies, P/N 269A2015 or 269A2015-5, accomplish the following:

(1) At intervals not to exceed 50 hours TIS:

(i) Remove the strut assemblies, P/N 269A2015 or P/N 269A2015-5.

(ii) Visually inspect the strut aluminum end fittings for deformation or damage and dye-penetrant inspect the strut aluminum end fittings for a crack in accordance with Step II of Schweizer Service Information Notice No. N-109.2, dated September 1, 1976 (SIN N-109.2).

(iii) If deformation, damage, or a crack is found, before further flight, modify the strut assemblies by replacing the aluminum end fittings with stainless steel end fittings, P/N 269A2017-3 and -5, and attach bolts in accordance with Step III of SIN N-109.2; or replace each strut assembly P/N 269A2015 with P/N 269A2015-9, and replace each strut

assembly P/N 269A2015-5 with P/N 269A2015-11.

(2) Within 500 hours TIS or one year, whichever occurs first, modify or replace the strut assemblies in accordance with paragraph (d)(1)(iii) of this AD.

(e) For the Model 269C helicopters, within 100 hours TIS, serialize each strut assembly, P/N 269A2015-5 and P/N 269A2015-11, in accordance with Schweizer Service Information Notice No. N-108, dated May 21, 1973.

(f) Within 25 hours TIS or 60 days, whichever occurs first, for cluster fittings, P/N 269A2234-3 and P/N 269A2235-3, perform a one-time inspection and repair, if required, in accordance with Procedures, Part II of Schweizer Service Bulletin No. B-277, dated January 25, 2002.

(g) Before further flight, replace any cluster fitting that is cracked or has surface defects

beyond rework limits with an airworthy cluster fitting.

(h) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (NYACO), FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, NYACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the NYACO.

(i) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished.

Issued in Fort Worth, Texas, on February 18, 2003.

Eric D. Bries,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 03-4479 Filed 2-25-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-124069-02]

RIN 1545-BA77

Section 6038—Returns Required With Respect to Controlled Foreign Partnerships

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Cancellation of notice of public hearing on proposed rulemaking.

SUMMARY: This document cancels the public hearing on proposed regulations relating to controlled foreign partnerships.

DATES: The public hearing originally scheduled for Wednesday, March 12, 2003, at 10 a.m., is cancelled.

FOR FURTHER INFORMATION CONTACT: LaNita Van Dyke of the Regulations Unit, Assistant Chief Counsel (Procedure and Administration), (202) 622-7190 (not a toll-free number).

SUPPLEMENTARY INFORMATION: A notice of proposed rulemaking and notice of public hearing that appeared in the **Federal Register** on Monday, December 23, 2002 (67 FR 78202), announced that a public hearing was scheduled for Wednesday, March 12, 2003, at 10 a.m., in room 4718, Internal Revenue Building, 1111 Constitution Avenue, NW., Washington, DC. The subject of

the public hearing is proposed regulations under section 6038 of the Internal Revenue Code. The outlines of topics to be addressed at the hearing were due on Wednesday, February 20, 2003.

The notice of proposed rulemaking and notice of public hearing, instructed those interested in testifying at the public hearing to submit a request to speak and an outline of the topics to be addressed. As of Friday, February 21, 2003, no one has requested to speak. Therefore, the public hearing scheduled for Wednesday, March 12, 2003, is cancelled.

Cynthia Grigsby,

Chief, Regulations Unit, Associate Chief Counsel (Procedure and Administration).

[FR Doc. 03-4545 Filed 2-25-03; 8:45 am]

BILLING CODE 4830-01-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-127380-02]

RIN 1545-BA79

Outbound Liquidations to Foreign Corporations; Hearing Cancellation

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Cancellation of notice of public hearing on proposed rulemaking.

SUMMARY: This document provides notice of cancellation of a public hearing on proposed regulations relating to outbound liquidations to foreign corporations under section 367 of the Internal Revenue Code.

DATES: The public hearing originally scheduled for Tuesday, March 4, 2003, at 10 a.m., is cancelled.

FOR FURTHER INFORMATION CONTACT: Guy R. Traynor of the Regulations Unit, Associate Chief Counsel, Procedure & Administration, at (202) 622-7180 (not a toll-free number).

SUPPLEMENTARY INFORMATION: A notice of proposed rulemaking and notice of public hearing that appeared in the **Federal Register** on Wednesday, November 20, 2002 (67 FR 70031), announced that a public hearing was scheduled for March 3, 2003 at 10 a.m., in room 4718 of the Internal Revenue Building, 1111 Constitution Avenue NW., Washington, DC. The subject of the public hearing is proposed regulations under section 367 of the Internal Revenue Code. The public comment period for these proposed

regulations expired on February 11, 2003.

The notice of proposed rulemaking and notice of public hearing instructed those interested in testifying at the public hearing to submit a request to speak and an outline of the topics to be addressed. As of February 21, 2003, no one has requested to speak. Therefore, the public hearing scheduled for March 3, 2003 is cancelled.

Cynthia E. Grigsby,

Chief, Regulations Unit, Associate Chief Counsel (Procedure and Administration).

[FR Doc. 03-4544 Filed 2-25-03; 8:45 am]

BILLING CODE 4830-01-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[CA262-0369b; FRL-7451-5]

Revisions to the California State Implementation Plan, Monterey Bay Unified Air Pollution Control District, San Joaquin Valley Unified Air Pollution Control District

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA is proposing to approve revisions to the Monterey Bay Unified Air Pollution Control District (MBUAPCD) and San Joaquin Valley Unified Air Pollution Control District (SJVUAPCD) portions of the California State Implementation Plan (SIP). These revisions concern volatile organic compound (VOC) emissions from organic liquid storage and VOC and nitrogen dioxide (Nox) from flare operations at industrial sites such as oil refineries, chemical manufacturers, and oil wells. We are proposing to approve local rules to regulate these emission sources under the Clean Air Act as amended in 1990 (CAA or the Act).

DATES: Any comments on this proposal must arrive by March 28, 2003.

ADDRESSES: Mail comments to Andy Steckel, Rulemaking Office Chief (AIR-4), U.S. Environmental Protection Agency, Region IX, 75 Hawthorne Street, San Francisco, CA 94105-3901.

You can inspect copies of the submitted SIP revisions and EPA's technical support documents (TSDs) at our Region IX office during normal business hours. You may also see copies of the submitted SIP revisions at the following locations:

California Air Resources Board,
Stationary Source Division, Rule