

Minneapolis/St. Paul, Minnesota
 Kansas City, Missouri
 Springfield, Missouri
 St. Louis, Missouri
 Cleveland, Ohio
 Cincinnati, Ohio
 Columbus, Ohio
 Dayton, Ohio
 Milwaukee, Wisconsin

Dallas Field Office

Little Rock, Arkansas
 Alexandria, Louisiana
 New Orleans, Louisiana
 Oklahoma City, Oklahoma
 Tulsa, Oklahoma
 Corpus Christi, Texas
 Dallas, Texas
 El Paso, Texas
 Houston, Texas
 San Antonio, Texas
 Temple, Texas
 Texarkana, Texas

Northeastern Regional Office

Hartford, Connecticut
 New Haven, Connecticut
 Dover, Delaware
 Bangor, Maine
 Portland, Maine
 Baltimore, Maryland
 Boston, Massachusetts
 Manchester, New Hampshire
 Portsmouth, New Hampshire
 Trenton, New Jersey
 Harrisburg, Pennsylvania
 Philadelphia, Pennsylvania
 Pittsburgh, Pennsylvania
 Wilkes-Barre, Pennsylvania
 Providence, Rhode Island
 Burlington, Vermont
 Charleston, West Virginia
 Morgantown, West Virginia

New York Field Office

Newark, New Jersey
 Albany, New York
 Buffalo, New York
 New York, New York
 Syracuse, New York
 San Juan, Puerto Rico

Washington Regional Office

Washington, DC
 Asheville, North Carolina
 Charlotte, North Carolina
 Raleigh, North Carolina
 Jacksonville, North Carolina
 Alexandria, Virginia
 Norfolk, Virginia
 Richmond, Virginia
 Roanoke, Virginia

Western Regional Office

Anchorage, Alaska
 Fresno, California
 Los Angeles, California
 Monterey, California
 Sacramento, California
 San Bernardino, California
 San Diego, California
 San Francisco, California
 Santa Ana, California
 Santa Barbara, California
 Honolulu, Hawaii
 Boise, Idaho
 Pocatello, Idaho

Las Vegas, Nevada
 Reno, Nevada
 Medford, Oregon
 Portland, Oregon
 Seattle, Washington
 Spokane, Washington
 Richland, Kennewick, and Pasco,
 Washington

Denver Field Office

Phoenix, Arizona
 Tucson, Arizona
 Grand Junction, Colorado
 Lakewood, Colorado
 Pueblo, Colorado
 Wichita, Kansas
 Billings, Montana
 Great Falls, Montana
 Missoula, Montana
 Omaha, Nebraska
 Albuquerque, New Mexico
 Bismarck, North Dakota
 Fargo, North Dakota
 Rapid City, South Dakota
 Sioux Falls, South Dakota
 Salt Lake City, Utah
 Casper, Wyoming

Dated: March 5, 2004.

Bentley M. Roberts, Jr.,

Clerk of the Board.

[FR Doc. 04-5417 Filed 3-10-04; 8:45 am]

BILLING CODE 7400-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-362-AD; Amendment 39-13515; AD 2004-05-20]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, MD-10-30F, MD-11, and MD-11F Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas transport category airplanes, that requires modification of the installation wiring for the electric motor operated auxiliary hydraulic pumps in the right wheel well area of the main landing gear, and repetitive inspections of the numbers 1 and 2 electric motors of the auxiliary hydraulic pumps for electrical resistance, continuity, mechanical rotation, and associated airplane wiring resistance/voltage; and corrective actions if necessary. This action is necessary to prevent failure of

the electric motors of the hydraulic pump and associated wiring, which could result in fire at the auxiliary hydraulic pump and consequent damage to the adjacent electrical equipment and/or structure. This action is intended to address the identified unsafe condition.

DATES: Effective April 15, 2004.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 15, 2004.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the FAA, Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Ken Sujishi, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone (562) 627-5353; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, MD-10-30F, MD-11, and MD-11F airplanes, was published in the **Federal Register** on October 15, 2003 (68 FR 59349). That action proposed to require modification of the installation wiring for the electric motor operated auxiliary hydraulic pumps in the right wheel well area of the main landing gear, and repetitive inspections of the numbers 1 and 2 electric motors of the auxiliary hydraulic pumps for electrical resistance, continuity, mechanical rotation, and associated airplane wiring resistance/voltage; and corrective actions if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

Requests To Extend Repetitive Inspection Interval

Two commenters state that they support the intent of the proposed rule, but they request that the proposed repetitive inspection interval of 2,500 flight hours be extended to every 18 months or 6,000 flight hours. One commenter states that it has been inspecting the affected pump installations every 18 months or 6,000 flight hours and that none of the affected airplanes or pumps removed from the affected airplanes exhibit signs of arcing, burnt wiring, or other conditions indicative of a fire.

The FAA does not agree that the repetitive interval should be extended. In the "Discussion" section of the preamble of the proposed AD we advised that investigation revealed that the unsafe condition had occurred on airplanes that had been in service several years and/or had the auxiliary hydraulic pump previously overhauled. In addition, two reports of short circuit failure of the motor electrical connector of the auxiliary hydraulic pump occurred even though the affected airplanes were being inspected at intervals of 18 months or 6,000 flight hours. Therefore, we have determined that an inspection interval of 2,500 flight hours will provide an adequate interval to detect and correct the identified unsafe condition.

Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 409 Model DC-10 airplanes of the affected design in the worldwide fleet. The FAA estimates that 322 airplanes of U.S. registry will be affected by this AD.

It will take approximately 9 work hours per airplane to do the modification specified in Boeing Alert Service Bulletin DC10-29A144, at an average labor rate of \$65 per work hour. Required parts will cost would be between \$4,886 and \$7,920 per airplane. Based on these figures, the cost impact of the modification is estimated to be between \$5,471 and \$8,505 per airplane.

It will take approximately 1 work hour per airplane to do the inspection specified in Boeing Alert Service Bulletin DC10-29A142, at an average labor rate of \$65 per work hour. Based on these figures, the cost impact of the inspection is estimated to be \$65 per airplane, per inspection cycle.

There are approximately 195 Model MD-11 airplanes of the affected design in the worldwide fleet. The FAA estimates that 74 airplanes of U.S. registry will be affected by this AD.

It will take approximately 13 work hours per airplane to do the modification specified in Boeing Alert Service Bulletin MD11-29A059, at an average labor rate of \$65 per work hour. Required parts will cost between \$5,183 and \$9,182 per airplane. Based on these figures, the cost impact of the modification is estimated to be between \$6,028 and \$10,027 per airplane.

It will take approximately 1 work hour per airplane to do the inspection specified in Boeing Alert Service Bulletin MD11-29A057, at an average labor rate of \$65 per work hour. Based on these figures, the cost impact of the inspection is estimated to be \$65 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2004-05-20 McDonnell Douglas:

Amendment 39-13515. Docket 2001-NM-362-AD.

Applicability: Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, MD-10-30F, MD-11, and MD-11F airplanes; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the electric motors of the hydraulic pump and associated wiring, which could result in fire at the auxiliary hydraulic pump and consequent damage to the adjacent electrical equipment and/or structure, accomplish the following:

Modification/Prior or Concurrent Actions

(a) For airplanes listed in Boeing Alert Service Bulletin DC10-29A144, Revision 2, dated August 1, 2003: Within 18 months after the effective date of this AD, do the actions specified in paragraphs (a)(1) and (a)(2) of this AD.

(1) Modify the installation wiring of the electric motor operated auxiliary hydraulic pumps in the right wheel well area of the main landing gear (MLG) (including removing existing clamps, ground wires, if required, and sleeving from the wire assemblies; inspecting for cracks and chafing, installing new support bracket, clips, and bracket assemblies, as applicable; installing sleeving; re-routing and attaching wire assemblies using new clamps and attachments; installing an additional routing clip on lower bracket of fuel motor control valve, if applicable; and doing a voltage check and a functional test), per the Accomplishment Instructions of Boeing Alert Service Bulletin DC10-29A144, Revision 2, dated August 1, 2003.

(2) Prior to or concurrent with accomplishment of paragraph (a)(1) of this AD: Do the actions specified in Boeing Alert Service Bulletin DC10-29A142, Revision 02, dated April 17, 2003 (including inspecting the numbers 1 and 2 electric motors of the auxiliary hydraulic pumps for electrical resistance, continuity, mechanical rotation,

and associated airplane wiring resistance/voltage; and replacing the auxiliary hydraulic pump with a serviceable pump and repairing the wiring if necessary), per the Accomplishment Instructions of the service bulletin. Repeat the actions after that at intervals not to exceed 2,500 flight hours.

(b) For airplanes listed in Boeing Alert Service Bulletin MD11-29A059, Revision 2, dated August 1, 2003: Within 18 months after the effective date of this AD, do the actions specified in paragraphs (b)(1) and (b)(2) of this AD.

(1) Modify the installation wiring of the electric motor auxiliary hydraulic pumps in the wheel well area of the right MLG (including removing and retaining wire assembly clamps, if applicable; retaining the existing ground wire assemblies; retaining or

replacing all other wire assemblies for both connectors; installing spiral wrap and sleeving; wrapping upper ends of individual wires with tape; installing new support bracket assemblies, if applicable; re-routing and attaching wire assemblies using new clamps and attachments, if applicable; and doing a voltage check and a functional test), per the Accomplishment Instructions of Boeing Alert Service Bulletin MD11-29A059, Revision 2, dated August 1, 2003.

(2) Prior to or concurrent with accomplishment of paragraph (b)(1) of this AD: Do the actions specified in Boeing Alert Service Bulletin MD11-29A057, Revision 02, dated April 17, 2003 (including inspecting the numbers 1 and 2 electric motors of the auxiliary hydraulic pumps for electrical resistance, continuity, mechanical rotation,

and associated airplane wiring resistance/voltage; and replacing the auxiliary hydraulic pump with a serviceable pump and repairing the wiring if necessary), per the Accomplishment Instructions of the service bulletin. Repeat the actions after that at intervals not to exceed 2,500 flight hours.

Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, Los Angeles Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

Incorporation by Reference

(d) The actions shall be done in accordance with the applicable service bulletins listed in the following table:

TABLE 1.—APPLICABLE SERVICE BULLETINS

Service bulletin	Revision level	Date
Boeing Alert Service Bulletin DC10-29A142	Revision 02	April 17, 2003.
Boeing Alert Service Bulletin DC10-29A144	Revision 2	August 1, 2003.
Boeing Alert Service Bulletin MD11-29A057	Revision 02	April 17, 2003.
Boeing Alert Service Bulletin MD11-29A059 including Appendix	Revision 2	August 1, 2003.

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). Copies may be inspected at the FAA, Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(e) This amendment becomes effective on April 15, 2004.

Issued in Renton, Washington, on February 26, 2004.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-4937 Filed 3-10-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Part 522

Implantation or Injectable Dosage Form New Animal Drugs; Lincomycin

AGENCY: Food and Drug Administration, HHS.

ACTION: Final rule.

SUMMARY: The Food and Drug Administration (FDA) is amending the animal drug regulations to reflect approval of an abbreviated new animal drug application (ANADA) filed by Phoenix Scientific, Inc. The ANADA provides for the use of lincomycin injectable solution in swine for the treatment of infectious arthritis and mycoplasma pneumonia.

DATES: This rule is effective March 11, 2004.

FOR FURTHER INFORMATION CONTACT:

Lonnie W. Luther, Center for Veterinary Medicine (HFV-104), Food and Drug Administration, 7519 Standish Pl., Rockville, MD 20855, 301-827-8549, e-mail: lluther@cvm.fda.gov.

SUPPLEMENTARY INFORMATION: Phoenix Scientific, Inc., 3915 South 48th St. Terrace, St. Joseph, MO 64503, filed ANADA 200-351 that provides for use of Lincomycin (lincomycin hydrochloride monohydrate) Injectable, USP in swine for the treatment of infectious arthritis and mycoplasma pneumonia. Phoenix Scientific's Lincomycin Injectable is approved as a generic copy of Pharmacia & Upjohn Co.'s LINCOMIX Injectable, approved under NADA 034-025. The ANADA is approved as of February 13, 2004, and the regulations are amended in 21 CFR 522.1260 to reflect the approval. The basis of approval is discussed in the freedom of information summary.

In accordance with the freedom of information provisions of 21 CFR part 20 and 21 CFR 514.11(e)(2)(ii), a summary of safety and effectiveness

data and information submitted to support approval of this application may be seen in the Division of Dockets Management (HFA-305), Food and Drug Administration, 5630 Fishers Lane, rm. 1061, Rockville, MD 20852, between 9 a.m. and 4 p.m., Monday through Friday.

The agency has determined under 21 CFR 25.33(a)(1) that this action is of a type that does not individually or cumulatively have a significant effect on the human environment. Therefore, neither an environmental assessment nor an environmental impact statement is required.

This rule does not meet the definition of "rule" in 5 U.S.C. 804(3)(A) because it is a rule of "particular applicability." Therefore, it is not subject to the congressional review requirements in 5 U.S.C. 801-808.

List of Subjects in 21 CFR Part 522

Animal drugs.

■ Therefore, under the Federal Food, Drug, and Cosmetic Act and under authority delegated to the Commissioner of Food and Drugs and redelegated to the Center for Veterinary Medicine, 21 CFR part 522 is amended as follows:

PART 522—IMPLANTATION OR INJECTABLE DOSAGE FORM NEW ANIMAL DRUGS

■ 1. The authority citation for 21 CFR part 522 continues to read as follows:

Authority: 21 U.S.C. 360b.