receive reasonable compensation for so acting, under any written trust instrument or custodial agreement created or organized in the United States and forming part of a taxadvantaged savings plan which qualifies or qualified for specific tax treatment under sections 223, 401(d), 408, 408A and 530 of the Internal Revenue Code (26 U.S.C. 223, 401(d), 408, 408A and 530), for its members or groups of its members, provided the funds of such plans are invested in share accounts or share certificate accounts of the Federal credit union. Federal credit unions located in a territory, including the trust territories, or a possession of the United States, or the Commonwealth of Puerto Rico, are also authorized to act as trustee or custodian for such plans, if authorized under sections 223, 401(d), 408, 408A and 530 of the Internal Revenue Code as applied to the territory or possession under similar provisions of territorial law. * * *

■ 6. Amend § 724.2 by revising the section heading and the introductory text to read as follows:

amendment as an interim final rule, the Board established a sixty-day comment period in which interested members of

§724.2 Self-Directed Plans.

A federal credit union may facilitate transfers of plan funds to assets other than share and share certificates of the credit union, provided the conditions of § 724.1 are met and the following additional conditions are met: * * *

[FR Doc. 04–17259 Filed 7–28–04; 8:45 am] BILLING CODE 7535–01–P

NATIONAL CREDIT UNION ADMINISTRATION

12 CFR Part 745

Share Insurance; Living Trust Accounts

AGENCY: National Credit Union Administration (NCUA). ACTION: Final rule.

SUMMARY: NCUA is adopting as a final rule without change the interim rule amending Part 745 of its regulations concerning share insurance coverage for beneficial interests in living trust accounts. NCUA published the interim rule with a sixty-day comment period at 69 FR 8798, on February 26, 2004.

DATES: This final rule is effective on July 29, 2004.

FOR FURTHER INFORMATION CONTACT: Ross Kendall, Staff Attorney, Office of General Counsel, at the above address or telephone: (703) 518–6562.

SUPPLEMENTARY INFORMATION: Effective April 1, 2004, NCUA revised its living trust account rules to provide for

insurance coverage of up to \$100,000 per qualifying beneficiary who, as of the date of a credit union's failure, would become entitled to the living trust assets upon the owner's death, regardless of the existence of a defeating contingency affecting the beneficiary's interest. The NCUA Board determined that elimination of the defeating contingency provisions in the rule was beneficial to credit unions and their members because the operation of the rule was complex and not widely understood. The amendment also clarified that a credit union need not maintain records disclosing the names and interests of beneficiaries of living trusts. In addition, the amendment preserved parity between the NCUA and the Federal Deposit Insurance Corporation (FDIC), which administers the insurance fund that protects bank depositors and which had, in January of 2004, adopted a similar amendment to its rules.

Even though NCUA issued the amendment as an interim final rule, the period in which interested members of the public could comment on any aspect of the amendment. We received five comments, all of which were fully supportive of the amendment. The commenters uniformly indicated the changes would result in elimination of confusion by credit unions and their members and an enhanced understanding of the scope and operation of the share insurance rules for beneficial interests in living trust accounts. The commenters also cited the benefit of having uniformity of insurance coverage between living trust accounts and other types of revocable trust accounts, as well as the benefit of parity between the NCUA and the FDIC.

In view of the comments and the benefits described herein and in the preamble to the interim rule, the NCUA Board has determined to adopt the rule as final without change.

List of Subjects in 12 CFR Part 745

Credit unions, Share insurance.

By the National Credit Union Administration Board on July 22, 2004.

Becky Baker,

Secretary of the Board.

PART 745—SHARE INSURANCE AND APPENDIX

■ Accordingly, the interim final rule amending 12 CFR 745.4, which was published at 69 FR 8798 on February 26, 2004, is adopted as a final rule without change.

[FR Doc. 04–17258 Filed 7–28–04; 8:45 am] BILLING CODE 7535–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-215-AD; Amendment 39-13747; AD 2004-15-13]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and Model MD-88 Airplanes

AGENCY: Federal Aviation Administration, DOT. **ACTION:** Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and Model MD-88 airplanes, that requires replacement of certain freeze protection ribbon heaters in the lavatory water supply system, and flushing, cleaning, and sterilizing the potable water system; disconnecting, coiling, and stowing the wiring of the freeze protection ribbon heater; or removal of freeze protection heaters. This action is necessary to prevent failure of freeze protection ribbon heaters, which could result in the charring, scorching, smoking, and shorting out of freeze protection ribbon heaters in the lavatory water supply system. This condition, if not corrected, could also result in electrical arcing of freeze protection ribbon heaters, leading to fire and damage to water lines and components under the lavatory sink. This action is intended to address the identified unsafe condition.

DATES: Effective September 2, 2004. The incorporation by reference of a certain publication listed in the regulations is approved by the Director of the Federal Register as of September 2, 2004.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the National Archives

and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

FOR FURTHER INFORMATION CONTACT:

Cheyenne Del Carmen, Aerospace Engineer, Systems and Equipment Branch, ANM–130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712–4137; telephone (562) 627–5338; fax (562) 627–5210.

SUPPLEMENTARY INFORMATION: A

proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and Model MD-88 airplanes was published in the Federal Register on December 5, 2003 (68 FR 67978). That action proposed to require replacement of certain freeze protection ribbon heaters in the lavatory water supply system, and flushing, cleaning, and sterilizing the potable water system; disconnecting, coiling, and stowing the wiring of the freeze protection ribbon heater; or removal of freeze protection heaters.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

Request for Credit for Actions Accomplished per Alternative Service Bulletin

One commenter requests that the FAA give credit for actions accomplished in accordance with McDonnell Douglas

MD-80 Service Bulletin 38–56, dated September 20, 1991. The commenter states that the McDonnell Douglas service bulletin refers to Jamco Corporation Service Bulletin MD080– 25–829 as an additional source of service information for "instructions to replace the modular lavatory potable water supply hose and ribbon heater."

We agree, since we find that both Boeing Alert Service Bulletin MD80-25A381, dated August 5, 2002; and McDonnell Douglas MD-80 Service Bulletin 38-56, dated September 20, 1991, as revised by McDonnell Douglas MD-80 Service Bulletin Change Notification 38-56 CN1, dated June 11, 1992; refer to Jamco Corporation Service Bulletin MD080-25-829 as an additional source of service information for instructions on replacing the existing freeze protection ribbon heater in the lavatory water supply system with a new, reidentified heater hose assembly. Therefore, we have determined that completion of all the steps in the Accomplishment Instructions of McDonnell Douglas MD-80 Service Bulletin 38-56, dated September 20, 1991, is acceptable for compliance with the corresponding actions specified in paragraph (a)(1) of this final rule. We have added new paragraph (b) to this final rule to give credit for accomplishment of the alternative service bulletin.

Request To Use Latest Revision of Jamco Service Bulletin

Another commenter requests that we revise the proposed AD to reference Revision 6 of Jamco Corporation Service Bulletin MD080–25–829 as an additional source of service information. The commenter states that Revision 6 is "in the approval cycle," and that if it is approved "... and the AD restates the version of the Jamco service bulletin,

there will be a problem." The commenter provided no justification for the request.

We agree with the commenter's request to reference Jamco Corporation Service Bulletin MD080–25–829, Revision 6, dated March 10, 2003. We find that Revision 6 of the Jamco service bulletin describes procedures that are essentially the same as the procedures described in Revision 5 of the Jamco service bulletin. Therefore, we have revised Note 1 of this final rule to reference Revision 6 of the Jamco service bulletin as an additional source of service information.

Explanation of Change to Proposed Rule

In Note 1 of the proposed AD, we inadvertently omitted the revision level for Jamco Corporation Service Bulletin MD080–25–829. We have revised this final rule to specify Revision 6.

Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the changes previously described. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Cost Impact

There are approximately 1,180 airplanes of the affected design in the worldwide fleet. The FAA estimates that 724 airplanes of U.S. registry will be affected by this AD, and that each airplane has approximately 3 lavatories, and that the average labor rate is \$65 per work hour. Table 1 shows the estimated cost impact, based upon the action taken, for airplanes affected by this AD.

TABLE 1.—COST IMPACT

Action	Work hours per lavatory	Parts cost per lavatory	Cost per lavatory	Total cost
Replace the existing freeze protection ribbon heater with a new, reidentified heater hose assembly; and flush, clean, and sterilize the potable water system; or	6	\$2,344 to \$3,208 (Depending on lavatory module configuration).	\$2,734 to \$3,598 (Depending on lavatory module configuration).	\$5,938,248 to \$7,814,856 (Depending on lavatory configuration) or \$8,202 to \$10,794 per airpalne.
Disconnect, coil, and stow the wiring of the freeze protection ribbon heater: or	2	\$0	\$130	\$282,360 or \$390 per airpalne.
Remove the freeze protection ribbon heater	3	\$0	\$195	\$423,540 or \$585 per airpalne.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2004-15-13 McDonnell Douglas:

Amendment 39–13747. Docket 2002–NM–215–AD.

Applicability: Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88 airplanes, as listed in Boeing Alert Service Bulletin MD80-25A381, dated August 5, 2002; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of freeze protection ribbon heaters, which could result in the charring, scorching, smoking, and shorting out of freeze protection ribbon heaters in the lavatory water supply system and could also result in electrical arcing of freeze protection ribbon heaters, leading to fire and damage to water lines and components under the lavatory sink; accomplish the following:

Corrective Actions

- (a) Within 18 months of the effective date of this AD, do the actions specified in paragraph (a)(1), (a)(2), or (a)(3) of this AD per the Accomplishment Instructions of Boeing Alert Service Bulletin MD80–25A381, dated August 5, 2002.
- (1) Replace the existing freeze protection ribbon heater in the lavatory water supply system with a new, reidentified heater hose assembly. Flush, clean, and sterilize the potable water system; or
- (2) Disconnect, coil, and stow the wiring of the freeze protection ribbon heater in the lavatory water supply system; or
- (3) Remove the freeze protection ribbon heater from the lavatory water supply system.

Note 1: Boeing Alert Service Bulletin MD80–25A381 refers to Jamco Corporation Service Bulletin MD080–25–829, Revision 6, dated March 10, 2003, as an additional source of service information for instructions on replacing the existing freeze protection ribbon heater with a new, reidentified heater hose assembly for Model DC–9–81 (MD–81), DC–9–82 (MD–82), DC–9–83 (MD–83), DC–9–87 (MD–87), and Model MD–88 airplanes.

Credit for Actions Accomplished per Alternative Service Bulletin

(b) Actions accomplished before the effective date of this AD per McDonnell Douglas MD–80 Service Bulletin 38–56, dated September 20, 1991, as revised by McDonnell Douglas MD–80 Service Bulletin Change Notification 38–56 CN1, dated June 11, 1992, are acceptable for compliance with the requirements of paragraph (a)(1) of this AD.

Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, Los Angeles Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

Incorporation by Reference

(d) Unless otherwise specified in this AD, the actions shall be done in accordance with Boeing Alert Service Bulletin MD80–25A381, dated August 5, 2002. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be

obtained from Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to: http:// www.archives.gov/federal_register/ code_of_federal_regulations/ibr_locations.html.

Effective Date

(e) This amendment becomes effective on September 2, 2004.

Issued in Renton, Washington, on July 15, 2004.

Kalene C. Yanamura,

Acting Manager, Transport Airplane
Directorate, Aircraft Certification Service.
[FR Doc. 04–16916 Filed 7–28–04; 8:45 am]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NM-272-AD; Amendment 39-13746; AD 2004-15-12]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A330–202, –203, –223, and –243 Airplanes, and A330–300 Series Airplanes

AGENCY: Federal Aviation Administration, DOT. **ACTION:** Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Airbus Model A330-202, -203, -223, and -243 airplanes, and A330-300 series airplanes, that requires modification of the control box of the auxiliary power unit (APU). This action is necessary to prevent uncommanded in-flight shutdown of the APU, which could result in loss of critical electrical systems when the airplane is operated in emergency electrical configuration, and consequent reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective September 2, 2004. The incorporation by reference of a certain publication listed in the regulations is approved by the Director of the Federal Register as of September 2, 2004.