

approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Related Information

(k) Canadian airworthiness directive CF-2006-17R1, dated May 30, 2007, also addresses the subject of this AD.

Material Incorporated by Reference

(l) You must use Bombardier Service Bulletin 601R-24-122, Revision A, dated July 13, 2006; and Bombardier Service Bulletin 601R-24-123, Revision B, dated February 16, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Bombardier Service Bulletin 601R-24-123, Revision B, dated February 16, 2007, in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On August 9, 2006 (71 FR 45364, August 9, 2006), the Director of the Federal Register approved the incorporation by reference of Bombardier Service Bulletin 601R-24-122, Revision A, dated July 13, 2006.

(3) Contact Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 25, 2008.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E8-3982 Filed 3-3-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-0338; Directorate Identifier 2007-NM-139-AD; Amendment 39-15396; AD 2008-05-02]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135BJ, -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to all EMBRAER Model EMB-135BJ, -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. That AD currently requires reviewing the airplane maintenance records for recent reports of vibration from the tail section or rudder pedals. The existing AD also currently requires repetitively inspecting the skin, attachment fittings, and control rods of rudder II to detect cracking, loose parts, wear, or damage; and related investigative/corrective actions if necessary. This new AD requires the existing repetitive inspection to be done with new service information. This new AD also requires replacing the locking tab washers on the control rods of the rudder II and installing springs on the hinge assemblies of the rudder II, which would terminate the repetitive inspection requirements. This AD results from reports of rudder vibration due to wear. We are issuing this AD to prevent failure of multiple hinge fittings, which could result in severe vibration, and to prevent failure of the rudder control rods, which could result in jamming of the rudder II; and possible structural failure and reduced controllability of the airplane.

DATES: This AD becomes effective April 8, 2008.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of April 8, 2008.

On December 23, 2005 (70 FR 72902, December 8, 2005), the Director of the Federal Register approved the incorporation by reference of EMBRAER Alert Service Bulletin 145LEG-55-

A010, dated August 26, 2005; and EMBRAER Alert Service Bulletin 145-55-A036, Revision 01, dated September 5, 2005.

ADDRESSES: For service information identified in this AD, contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149.

hinge assemblies of the rudder II, which would terminate the repetitive inspection requirements.

Comments

We provided the public the opportunity to participate in the development of this AD. No comments

have been received on the NPRM or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air

safety and the public interest require adopting the AD as proposed.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Records review (required by AD 2005-25-04)	1	\$80	None	\$80	463	\$37,040
Terminating action (new action)	5	80	\$644	1,044	463	483,372

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39-14397 (70 FR 72902, December 8, 2005) and by adding the following new airworthiness directive (AD):

2008-05-02 Empresa Brasileira de Aeronautica S.A. (EMBRAER): Amendment 39-15396. Docket No. FAA-2007-0338; Directorate Identifier 2007-NM-139-AD.

Effective Date

(a) This AD becomes effective April 8, 2008.

Affected ADs

(b) This AD supersedes AD 2005-25-04.

Applicability

(c) This AD applies to all EMBRAER Model EMB-135BJ, -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes; certificated in any category.

Unsafe Condition

(d) This AD results from reports of rudder vibration due to wear. We are issuing this AD to prevent failure of multiple hinge fittings, which could result in severe vibration, and

to prevent failure of the rudder control rods, which could result in jamming of the rudder II; and possible structural failure and reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

REQUIREMENTS OF

Note 1: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as a mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

(h) If any vibration from the tail section or rudder pedals is reported after December 23, 2005, do the inspection specified in paragraph (g) of this AD before the next flight. Repeat the inspection thereafter at intervals not to exceed 2,500 flight hours.

Note 2: EMBRAER Alert Service Bulletins 145LEG-55-A010, dated August 26, 2005; and 145-55-A036, Revision 01, dated September 5, 2005; refer to EMBRAER Service Bulletins 145LEG-55-0008, Revision 01, dated January 14, 2005; 145LEG-55-0009, dated June 21, 2004; and 145-55-0034, Revision 01, dated January 14, 2005; as additional sources of service information for installing washers in the rudder II hinge fittings and control rod assembly.

Exceptions to Service Bulletin Specifications

(i) Where EMBRAER Alert Service Bulletins 145LEG-55-A010 and 145-55-A036 specify to contact EMBRAER for repair instructions, operators must perform the repair before further flight using a method approved by either the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the Departamento de Aviação Civil (or its delegated agent).

(j) Although EMBRAER Alert Service Bulletins 145LEG-55-A010 and 145-55-A036 recommend sending a report of the inspection results to the manufacturer, this AD does not require a report.

Credit for Prior Accomplishment of Earlier Service Bulletin

(k) For Model -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes: Accomplishment of the inspection and

applicable related investigative/corrective actions before December 23, 2005, in accordance with EMBRAER Alert Service Bulletin 145-55-A036, dated August 20, 2005, is acceptable for compliance with the corresponding requirements of this AD.

NEW REQUIREMENTS OF THIS AD

New Revision to Service Bulletins

(l) As of the effective date of this AD, use only the Accomplishment Instructions of EMBRAER Alert Service Bulletin 145LEG-55-A010, Revision 02, dated May 16, 2006 (for Model EMB-135BJ airplanes); or 145-55-A036, Revision 03, dated May 16, 2006 (for all other airplanes); as applicable; to do the actions required by paragraphs (g) and (h) of this AD, until the actions required by paragraph (m) of this AD are done.

Note 3: EMBRAER Alert Service Bulletin 145LEG-55-A010, Revision 02, dated May 16, 2006 (for Model EMB-135BJ airplanes) refers to EMBRAER Service Bulletins 145LEG-55-0008, Revision 02, dated May 26, 2006; and 145LEG-55-0009, Revision 01, dated November 23, 2005; as additional sources of service information for installing washers in the rudder II hinge fittings and control rod assembly.

Note 4: EMBRAER Alert Service Bulletin 145-55-A036, Revision 03, dated May 16, 2006 (for EMB-135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes), refers to EMBRAER Service Bulletins 145-55-0034, Revision 02, dated May 25, 2006; and 145-55-0035, Revision 02, dated March 28, 2006; as additional sources of service information for installing washers in the rudder II hinge fittings and control rod assembly.

Terminating Action

(m) Within 5,500 flight hours or 36 months after the effective date of this AD, whichever occurs first, replace the locking tab washers on the control rods of the rudder II and install springs on the hinge assemblies of the rudder II, in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145LEG-55-0011, Revision

01, dated January 23, 2007 (for Model EMB-135BJ airplanes); or 145-55-0038, Revision 01, dated January 23, 2007 (for all other airplanes); as applicable. Accomplishment of the replacement and installation constitutes terminating action for the requirements of this AD.

Credit for Prior Accomplishment of Earlier Service Bulletins

(n) Actions done before the effective date of this AD in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145LEG-55-0011, dated May 12, 2006 (for Model EMB-135BJ airplanes); or 145-55-0038, dated May 12, 2006 (for all other airplanes); as applicable; are acceptable for compliance with the requirements of paragraph (m) of this AD.

Alternative Methods of Compliance (AMOCs)

(o)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) AMOCs approved previously in accordance with AD 2005-25-04 are approved as AMOCs for the corresponding provisions of this AD.

Related Information

(p) Brazilian airworthiness directive 2005-09-02R2, effective May 10, 2007, also addresses the subject of this AD.

Material Incorporated by Reference

(q) You must use the service information identified in Table 1 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise.

TABLE 1.—ALL MATERIAL INCORPORATED BY REFERENCE

EMBRAER Service Bulletin	Revision level	Date
Alert Service Bulletin 145LEG-55-A010	1	August 26, 2005.
Alert Service Bulletin 145LEG-55-A010	02	

TABLE 2.—NEW MATERIAL INCORPORATED BY REFERENCE—Continued

EMBRAER Service Bulletin	Revision level	Date
Alert Service Bulletin 145–55–A036	03	May 16, 2006.
Service Bulletin 145LEG–55–0011	01	January 23, 2007.
Service Bulletin 145–55–0038	01	January 23, 2007.

(2) On December 23, 2005 (70 FR 72902, December 8, 2005), the Director of the Federal Register approved the incorporation by reference of EMBRAER Alert Service Bulletin 145LEG–55–A010, dated August 26, 2005; and EMBRAER Alert Service Bulletin 145–55–A036, Revision 01, dated September 5, 2005.

(3) Contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 20, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8–3748 Filed 3–3–08; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2007–0204; Directorate Identifier 2007–NM–083–AD; Amendment 39–15397; AD 2008–05–03]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 747–100, –100B, –100B SUD, –200B, –200C, –200F, –300, 747SP, and 747SR Series Airplanes Powered by General Electric (GE) CF6–45/50 and Pratt & Whitney (P&W) JT9D–70, JT9D–3 or JT9D–7 Series Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Boeing Model 747–100, –100B, –100B SUD, –200B, –200C, –200F, –300, 747SP, and 747SR series airplanes powered by General Electric (GE) CF6–45/50 and Pratt & Whitney (P&W) JT9D–70, JT9D–3, or JT9D–7 series engines. This AD requires repetitive inspections to find cracks and broken fasteners of

the rear engine mount bulkhead of the inboard and outboard nacelle struts, and repair if necessary. For certain airplanes, this AD mandates a terminating modification for certain inspections of the inboard and outboard nacelle struts. This AD results from reports of web and frame cracks and sheared attachment fasteners on the inboard and outboard nacelle struts. We are issuing this AD to detect and correct cracks and broken fasteners of the inboard and outboard nacelle struts, which could result in possible loss of the rear engine mount bulkhead load path and consequent separation of the engine from the airplane.

DATES: This AD is effective April 8, 2008.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 8, 2008.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800–647–5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tamara Anderson, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 917–6421; fax (425) 917–6590.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an airworthiness directive (AD) that would apply to

certain Boeing Model 747–100, –100B, –100B SUD, –200B, –200C, –200F, –300, 747SP, and 747SR series airplanes powered by General Electric (GE) CF6–45/50 and Pratt & Whitney (P&W) JT9D–70, JT9D–3, or JT9D–7 series engines. That NPRM was published in the **Federal Register** on November 19, 2007 (72 FR 64961). That NPRM proposed to require repetitive inspections to find cracks and broken fasteners of the rear engine mount bulkhead of the inboard and outboard nacelle struts, and repair if necessary. For certain airplanes, that NPRM proposed to mandate a terminating modification for certain inspections of the inboard and outboard nacelle struts.

Comments