

low-pressure (LP) turbine rear frames, part numbers 338-171-703-0; 338-171-704-0; 338-171-705-0; and 338-171-706-0, installed. These engines are installed on, but not limited to, Airbus A318, A319, A320, and A321 series airplanes.

Unsafe Condition

(d) This AD results from a refined lifing analysis by the engine manufacturer that shows the need to identify initial and repetitive inspection thresholds for inspecting certain LP turbine rear frames. We are issuing this AD to detect low-cycle-fatigue cracks in the LP turbine rear frame, which could result in engine separation from the airplane, possibly leading to loss of control of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Initial Inspection

(f) Perform an initial eddy current inspection (ECI) of the LP turbine rear frame using paragraphs 3.A. through 3.A.(7)(d) of the Accomplishment Instructions of CFM International, S.A. Service Bulletin (SB) No. CFM56-5B S/B 72-0620, Revision 1, dated December 20, 2007, at the following compliance times:

(1) For commercial engine applications, within 25,000 cycles-since-new (CSN) on the LP turbine rear frame.

(2) For corporate engine applications, within 19,000 CSN on the LP turbine rear frame.

(3) For engines with unknown LP turbine rear frame CSN, within 300 cycles from the effective date of this AD.

Repetitive Inspections

(g) Perform repetitive ECIs of the LP turbine rear frame using paragraphs 3.A. through 3.A.(7)(d) of the Accomplishment Instructions of CFM International, S.A. SB No. CFM56-5B S/B 72-0620, Revision 1, dated December 20, 2007. Use the inspection intervals in paragraph 3.A.(8) of the Accomplishment Instructions of CFM International, S.A. SB No. CFM56-5B S/B 72-0620, Revision 1, dated December 20, 2007.

LP Turbine Rear Frame Removal Criteria

(h) Remove LP turbine rear frames from service that have a single crack length of 2.56 inches (65 mm) or longer, or multiple cracks with accumulated crack length of 2.56 inches (65 mm) or longer.

Alternative Methods of Compliance

(i) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(j) European Aviation Safety Agency AD 2007-0221, dated August 13, 2007, also addresses the subject of this AD.

(k) Contact Stephen Sheely, Aerospace Engineer, Engine Certification Office, FAA,

Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: stephen.k.sheely@faa.gov; telephone (781) 238-7750; fax (781) 238-7199, for more information about this AD.

Issued in Burlington, Massachusetts, on April 29, 2008.

Peter A. White,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E8-10050 Filed 5-6-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0520; Directorate Identifier 2008-NM-018-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 777-200 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Boeing Model 777-200 series airplanes. This proposed AD would require repetitive inspections for any wrinkle in certain external skin panels, and for cracking at the fuselage bulkhead shear tie end fastener locations at certain stations of section 48 of the fuselage; and doing related investigative and corrective actions if necessary. This proposed AD results from a report of cracks found in the external skin on the left and right sides of the Section 48 panel of the fuselage on two airplanes with skin wrinkles found at two of the external crack locations. We are proposing this AD to detect and correct wrinkles and cracks in certain external skin panels of Section 48, which could join together and result in reduced structural integrity of support structure for the vertical and horizontal stabilizers and inability of the airplane to sustain limit loads.

DATES: We must receive comments on this proposed AD by June 23, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Duong Tran, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6452; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0520; Directorate Identifier 2008-NM-018-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received a report of cracks found in the external skin on the left and right sides of the section 48 panel of the fuselage on two airplanes. There were ten external skin cracks on one airplane with 22,732 total flight hours and 20,286 total flight cycles; the cracks were 0.20 to 0.50 inch in length at

Stations 2195.75 and 2221.65, between Stringers 6 to 10 on the left and right sides. In addition, skin wrinkles 4.5 and 5.0 inches long and 1.0 inch wide and 0.014 inch deep were found at two of the external skin crack locations. A second report indicated that three external skin cracks, 0.12 to 0.20 inches in length were found at Station 2195.75, above Stringer 7 on the left side, on an airplane with 22,147 total flight hours and 19,281 total flight cycles. This condition, if not corrected, could result in reduced structural integrity of support structure for the vertical and horizontal stabilizers and inability of the airplane to sustain limit loads.

Relevant Service Information

We have reviewed Boeing Alert Service Bulletin 777-53A0051, dated November 8, 2007. The alert service bulletin describes procedures for repetitive general visual inspections for any wrinkle of the external skin at Stations 2195.75, 2221.65, and 2245.70 of the Section 48 panel of the fuselage, between stringers 5 and 10 on the left and right sides. The service bulletin also describes procedures for repetitive high frequency eddy current (HFEC) and detailed inspections for cracking at the fuselage bulkhead shear tie end fastener locations of the external skin at Stations 2195.75, 2221.65, and 2245.70 of the section 48 panel of the fuselage; between stringers 5 and 10 on the left and right sides. In addition, the service bulletin describes performing related investigative and corrective actions if necessary. The corrective actions include removing any skin wrinkle, repairing any skin crack, and installing a skin repair if any wrinkle or crack is found. The related investigative actions include an internal HFEC inspection of the repair doubler edge row fasteners for cracking if a skin repair is installed. The service bulletin also recommends contacting Boeing for repair data if any crack is found that is 1.0 or more inches in length.

The compliance times for the inspections specified in the service bulletin are as follows:

- General visual and external HFEC inspections for any wrinkle and cracking of the skin panels and bulkhead shear tie end fastener locations at Stations 2195.75, 2221.65, and 2245.70 of the Section 48 panel of the fuselage, between stringers 5 and 10: Before 16,000 total flight cycles or within 2,300 flight cycles after the date on the service bulletin, whichever occurs later. If no wrinkle or skin crack is found, the service bulletin specifies repeating the inspections thereafter at

intervals not to exceed 4,500 flight cycles.

- Internal HFEC inspection of the repair doubler shear tie end fasteners and external and internal detailed inspection of the tripler, doubler, skin, shear tie, stringer, or fuselage bulkhead (fastener locations): Within 30,000 flight cycles after installation of the repair.

- Internal HFEC inspection of the repair doubler edge row fasteners and external and internal detailed inspection of the tripler, doubler, skin, shear tie, stringer or fuselage bulkhead within the repair area: Before 30,000 total flight cycles, or within 16,000 flight cycles after installation of the repair, whichever occurs first. If no cracking is found, the service bulletin describes repeating the inspections thereafter at intervals not to exceed 16,000 flight cycles. If any crack is found, the service bulletin recommends contacting Boeing for repair data and repairing.

FAA's Determination and Requirements of This Proposed AD

We are proposing this AD because we evaluated all relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design. This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under "Difference Between the Proposed AD and Service Information."

Difference Between the Proposed AD and Service Information

The alert service bulletin specifies to contact the manufacturer for instructions on how to repair certain conditions, but this proposed AD would require repairing those conditions in one of the following ways:

- Using a method that we approve; or
- Using data that meet the certification basis of the airplane, and that have been approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization whom we have authorized to make those findings.

Costs of Compliance

We estimate that the inspections in this proposed AD would affect 13 airplanes of U.S. registry. We also estimate that it would take about 15 work-hours per product to comply with this proposed AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of this proposed AD to the U.S. operators

to be \$15,600, or \$1,200 per product, per inspection cycle.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866,
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Boeing: Docket No. FAA-2008-0520;
Directorate Identifier 2008-NM-018-AD.

Comments Due Date

(a) We must receive comments by June 23, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 777-200 series airplanes, certificated in any category; as identified in Boeing Alert Service Bulletin 777-53A0051, dated November 8, 2007.

Unsafe Condition

(d) This AD results from a report of cracks found in the external skin on the left and right sides of the section 48 fuselage panel on two airplanes with skin wrinkles found at two of the external crack locations. We are issuing this AD to detect and correct wrinkles and cracks in certain external skin panels of section 48, which could join together and result in reduced structural integrity of support structure for the vertical and horizontal stabilizers and inability of the airplane to sustain limit loads.

Compliance

(e) Comply with this AD within the compliance times specified, unless already done.

Repetitive Inspections/Investigative and Corrective Actions

(f) At the applicable compliance times specified in paragraph 1.E., "Compliance" of Boeing Alert Service Bulletin 777-53A0051, dated November 8, 2007, except as provided by paragraph (g) of this AD: Do the applicable inspections for any wrinkle of the external skin and for cracking at the fuselage bulkhead shear tie end fastener locations at Stations 2195.75, 2221.65, and 2245.70 of the section 48 panel of the fuselage, between stringers 5 and 10 on the left and right sides; and do all the applicable investigative and corrective actions; by doing all of the applicable actions in accordance with the Accomplishment Instructions of the service bulletin, except as provided by paragraph (h) of this AD. Do all applicable investigative and corrective actions before further flight. Repeat the applicable inspections thereafter at the applicable intervals specified in paragraph 1.E. of the service bulletin.

Exception to Compliance Times

(g) Where Boeing Alert Service Bulletin 777-53A0051, dated November 8, 2007, specifies counting the compliance time from " * * the date on this service bulletin," this AD requires counting the compliance time from the effective date of this AD.

Exception to Corrective Actions

(h) If any damage beyond the repair limits specified in Boeing Alert Service Bulletin 777-53A0051, dated November 8, 2007, is

found during any inspection required by this AD, and the service bulletin specifies to contact Boeing for appropriate action: Before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, ATTN: Duong Tran, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle ACO, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6452; fax (425) 917-6590 has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane.

Issued in Renton, Washington, on April 25, 2008.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E8-10059 Filed 5-6-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-0043; Directorate Identifier 2007-NM-058-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747SR, and 747SP Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: The FAA is revising an earlier NPRM for an airworthiness directive (AD) that applies to certain Boeing Model 747 series airplanes. The original

NPRM would have superseded an existing AD that currently requires inspecting to detect cracking in certain lower lobe fuselage skin lap joints, doing repetitive inspections for cracking at certain fastener locations having countersunk fasteners, and replacing countersunk fasteners with protruding head fasteners at certain fastener locations. The original NPRM proposed to replace a previous high-frequency eddy current (HFEC) inspection method with a new HFEC inspection method, add a one-time inspection for cracking of certain airplanes, and terminate the adjustment factor for the inspection compliance times based on cabin differential pressure. The original NPRM also included an inspection at an additional lap joint. The original NPRM resulted from reports of fuselage skin cracks found at certain countersunk fastener locations in the upper row of lap joints near the wing-to-body fairings, and from a report that the presence of Alodine-coated rivets could cause faulty results during the required inspections using the optional sliding probe HFEC inspection method specified in the existing AD. This new action revises the original NPRM by including inspections at additional lap joint locations and by removing inspections at certain other lap joint locations. We are proposing this supplemental NPRM to prevent reduced structural integrity of the fuselage.

DATES: We must receive comments on this supplemental NPRM by June 2, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9