

burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

#### (l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and the approval must specifically refer to this AD.

#### (m) Related Information

(1) For more information about this AD, contact Nancy Marsh, Aerospace Engineer, Airframe Branch, ANM-120S, Seattle Aircraft Certification Office (ACO), FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: 425-917-6440; fax: 425-917-6590; email: [Nancy.Marsh@faa.gov](mailto:Nancy.Marsh@faa.gov).

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; phone: 206-544-5000, extension 1; fax: 206-766-5680; email: [me.boecom@boeing.com](mailto:me.boecom@boeing.com); Internet: <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on May 18, 2012.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2012-13055 Filed 5-31-12; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2011-0115; Directorate Identifier 2010-NE-40-AD]

RIN 2120-AA64

#### Airworthiness Directives; Turbomeca S.A. Turboshaft Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to supersede an existing airworthiness directive (AD) that applies to certain Turbomeca S.A. Arriel 2B and 2B1 turboshaft engines. The existing AD currently requires accomplishment of the TU166 modification. Since we issued that AD, we became aware of an accident involving an engine in-flight shutdown on a twin-engine helicopter powered by two Arriel 2S2 engines. This proposed AD would add the Arriel 2S2 engine to the applicability of engines requiring the TU166 modification with a different compliance time. We are proposing this AD to prevent rupture of a gas generator (GG) turbine blade, which could result in an uncommanded in-flight shutdown and a forced landing or accident.

**DATES:** We must receive comments on this proposed AD by July 31, 2012.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Turbomeca, 40220 Tarnos, France; phone: 33 (0)5 59 74 40 00; telex: 570 042; fax: 33 (0)5 59 74 45 15. You may review copies of the referenced service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Rose Len, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7772; fax: 781-238-7199; email: [rose.len@faa.gov](mailto:rose.len@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2011-0115; Directorate Identifier 2010-NE-40-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

On June 14, 2011, we issued AD 2011-13-05, Amendment 39-16728 (76 FR 40222, July 8, 2011) for Turbomeca S.A. Arriel 2B and 2B1 turboshaft engines not modified by the TU166 modification. That AD requires accomplishment of the TU166 modification when the GG turbine is replaced or when the engine or Module M03 is going through overhaul or repair, or within 1,300 cycles-in-service after the effective date of that AD, whichever occurs first. That AD resulted from several cases of GG turbine blade rupture occurring in service on Arriel 2 twin-engine powered helicopters, and one case on a single-engine powered helicopter. We issued that AD to prevent rupture of a GG turbine blade,

which could result in an uncommanded in-flight shutdown and an emergency autorotation landing or accident on single-engine powered helicopters.

#### Actions Since Existing AD Was Issued

Since we issued AD 2011–13–05, Amendment 39–16728 (76 FR 40222, July 8, 2011), an accident occurred on a Sikorsky S–76C++ twin-engine helicopter following an uncommanded in-flight shutdown of one of its Arriel 2S2 turboshaft engines. That engine did not have the TU166 modification incorporated. The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has superseded EASA AD 2010–0198, dated October 1, 2010, which we reference in AD 2011–13–05. The EASA superseding AD, AD 2012–0054, dated April 2, 2012, adds the Arriel 2S2 turboshaft engine to the applicability for incorporating the TU166 modification with its own compliance time. This AD adds the Arriel 2S2 engine with a compliance time different than the Arriel 2B and 2B1 engines.

#### Relevant Service Information

We reviewed Turbomeca S.A. Alert Mandatory Service Bulletin (MSB) No. A292 72 3166 Version B, dated September 20, 2010, and Alert MSB No. A292 72 4166 Version A, dated March 23, 2012. The Alert MSBs describe procedures for accomplishing the TU166 modification.

#### FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

#### Proposed AD Requirements

This proposed AD would retain all of the requirements of AD 2011–13–05, Amendment 39–16728 (76 FR 40222, July 8, 2011) except it would reduce the compliance time for the Arriel 2B and 2B1 engines to account for the effective date of that AD. This proposed AD would add the Arriel 2S2 turboshaft engine to the AD applicability and would add accomplishing the TU166 modification to those engines with a compliance time different from the compliance time for the Arriel 2B and 2B1 engines.

#### Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 542 products of U.S. registry. We also estimate that it would

take about 60 work-hours per product to comply with this AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$3,900 per product. Based on these figures, we estimate the cost of the AD on U.S. operators to be \$4,878,000.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by removing airworthiness directive (AD) 2011–13–05, Amendment 39–16728 (76 FR 40222, July 8, 2011), and adding the following new AD:

**Turbomeca S.A.:** Docket No. FAA–2011–0115; Directorate Identifier 2010–NE–40–AD.

#### (a) Comments Due Date

The FAA must receive comments on this AD action by July 31, 2012.

#### (b) Affected ADs

This AD supersedes AD 2011–13–05, Amendment 39–16728 (76 FR 40222, July 8, 2011).

#### (c) Applicability

This AD applies to Turbomeca S.A. Arriel 2B, 2B1, and 2S2 turboshaft engines not modified by TU166 modification.

#### (d) Unsafe Condition

This AD was prompted by reports of an accident involving a twin-engine helicopter powered by two Arriel 2S2 engines. We are issuing this AD to prevent rupture of a gas generator (GG) turbine blade, which could result in an uncommanded in-flight shutdown and a forced landing or accident.

#### (e) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) For Arriel 2B and 2B1 turboshaft engines, accomplish the TU166 modification in accordance with the instructions specified within Turbomeca Alert Mandatory Service Bulletin (MSB) No. A292 72 3166 Version B, dated September 20, 2010, when the GG Turbine is replaced or when the engine or Module M03 is going through overhaul or repair, or within 676 cycles-in-service (CIS) after the effective date of this AD, whichever occurs first.

(2) For Arriel 2S2 turboshaft engines, accomplish the TU166 modification in accordance with the instructions specified within Turbomeca Alert MSB No. A292 72 4166 Version A, dated March 23, 2012, when the GG Turbine is replaced or when the engine or Module M03 is going through overhaul or repair, or within 500 CIS after the effective date of this AD, whichever occurs first.

#### (f) Credit for Previous Actions

For Arriel 2B and 2B1 turboshaft engines, if before the effective date of this AD, you performed the TU166 modification using Turbomeca Alert MSB No. A292 72 3166 Version A, dated August 17, 2010, you met the requirements of this AD.

**(g) Alternative Methods of Compliance (AMOCs)**

The Manager, Engine Certification Office, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

**(h) Related Information**

(1) For more information about this AD, contact Rose Len, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7772; fax: 781-238-7199; email: [rose.len@faa.gov](mailto:rose.len@faa.gov).

(2) European Aviation Safety Agency AD 2012-0054, dated April 2, 2012, also pertains to this AD.

(3) For service information identified in this AD, contact Turbomeca, 40220 Tarnos, France; phone: 33 (0)5 59 74 40 00; telex: 570 042; fax: 33 (0)5 59 74 45 15. You may review copies of the referenced service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. You may review copies of the referenced service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Issued in Burlington, Massachusetts, on May 25, 2012.

**Pete A. White,**

*Manager, Engine & Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 2012-13324 Filed 5-31-12; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2012-0496; Directorate Identifier 2011-NM-263-AD]

**RIN 2120-AA64**

**Airworthiness Directives; Bombardier Inc. Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to supersede an existing airworthiness directive (AD) that applies to certain Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. The existing AD currently requires revising the airworthiness limitations section (AWL) of the instructions for continued airworthiness (ICA) of the Canadian Regional Jet Maintenance Requirements Manual by incorporating new procedures for repetitive detailed and special detailed inspections for cracking of the aft pressure bulkhead. Since we

issued that AD, we have received multiple reports of cracks on the forward face of the rear pressure bulkhead (RPB) web. This proposed AD would require revising the maintenance program to incorporate a revised task specified in a certain temporary revision, which requires an improved non-destructive inspection procedure; and adds airplanes to the applicability. We are proposing this AD to detect and correct cracking in the RPB, which could result in reduced structural integrity and rapid decompression of the airplane.

**DATES:** We must receive comments on this proposed AD by July 16, 2012.

**ADDRESSES:** You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:**

Jeffrey Zimmer, Aerospace Engineer, Airframe & Mechanical Systems Branch, ANE-171, New York Aircraft

Certification Office (ACO), FAA, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7306; fax (516) 794-5531.

**SUPPLEMENTARY INFORMATION:****Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2012-0496; Directorate Identifier 2011-NM-263-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

**Discussion**

On October 31, 2005, we issued AD 2005-23-01, Amendment 39-14359 (70 FR 69073, November 14, 2005). That AD required actions intended to address an unsafe condition on the products listed above. Since we issued AD 2005-23-01, Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2011-30, dated August 11, 2011 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Cracks on the forward face of the Rear Pressure Bulkhead (RPB) web have been discovered on three CL-600-2B19 aeroplanes in-service. This indicates that the existing inspection requirements of Airworthiness Limitation (AWL) task 53-61-153 mandated by [TCCA] AD CF-2005-13R1 are not adequate. Failure of the RPB could result in rapid decompression of the aeroplane.

A Temporary Revision has been made to Part 2 of the Maintenance Requirements Manual (MRM) to revise the existing AWL task by introducing an improved Non-Destructive Inspection (NDI) procedure to ensure that fatigue cracking of the RPB is detected and corrected.

This [TCCA] directive mandates the incorporation of a new NDI procedure for AWL task number 53-61-153.

You may obtain further information by examining the MCAI in the AD docket.

**Relevant Service Information**

Bombardier Inc. has issued Temporary Revision 2B-2187, dated