

(P/N) 212–010–750 (all dash numbers), installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as fatigue cracking of a T/R blade, which could lead to failure of the T/R blade and subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective March 25, 2014.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 25 hours time-in-service (TIS) or 30 days, whichever occurs first, and thereafter at intervals not to exceed 25 hours TIS or 30 days, whichever occurs first:

(i) Clean each T/R blade by hand using a mild soap and cheesecloth on both sides of the blade in a spanwise direction and dry thoroughly.

(ii) Using a 3X or higher power magnifying glass and a light, visually inspect the T/R blade skin, leading edge spar, doublers, grip plates, and trailing edge on both sides of each blade for a crack, corrosion (which may be indicated by blistering, peeling, flaking, bubbling, or cracked paint), a nick, a scratch, a dent, or other damage. Pay particular attention to both sides of each T/R blade in the area located 16 to 32 inches from the T/R blade tip (blade station 20.00 to 35.00; the T/R blade tip is located at blade station 51) as depicted by the shaded area in Figure 2 of AgustaWestland Bollettino Tecnico No. 412–136, dated August 13, 2013 (BT). Also, pay particular attention to the inboard T/R blade butt area near the attachment of the external balance weight and screws and to any T/R blade surface that was snagged by cheesecloth, as this may be an indication of a crack or paint chip that could lead to corrosion.

(iii) Using a 10X or higher power magnifying glass and a light, visually inspect both sides of each T/R blade for a crack, corrosion (which may be indicated by blistering, peeling, flaking, bubbling, or cracked paint), a nick, a scratch, a dent or other damage between blade station 20.00 to 35.00 as depicted by the shaded area in Figure 2 of the BT.

(iv) If there is any blistering, peeling, flaking, bubbling, or cracked paint on a T/R blade, remove the paint from the affected area by sanding in a spanwise direction first with abrasive cloth or paper 240-grit or finer and then with abrasive cloth or paper 400-grit or finer. After paint removal, wipe area with a clean cloth dampened with alcohol and dry thoroughly and then visually inspect the affected area for any corrosion or a crack using a 10X or higher power magnifying glass and a light. If any corrosion is found, measure the depth of the damage.

(v) If there is a nick, scratch, or dent on the T/R blade, visually inspect for a crack using a 10X or higher power magnifying glass and a light. Measure the depth of the damage.

(2) Before further flight, remove from service any T/R blade that has a crack,

corrosion, a nick, a scratch, a dent, or other damage that exceeds any of the maximum repair damage limits.

(3) Before further flight, repair or remove from service any T/R blade that has corrosion, a nick, a scratch, a dent or other damage that is within the maximum repair damage limits.

(4) Do not install on any helicopter T/R blade P/N 212–010–750 (all dash numbers) unless it has been inspected in accordance with the requirements of this AD.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222–5110; email robert.grant@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

The subject of this AD is addressed in the European Aviation Safety Agency (EASA) AD. No. 2013–0185, dated August 14, 2013. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA–2014–0109.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6410, tail rotor blades.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) AgustaWestland Bollettino Tecnico No. 412–136, dated August 13, 2013.

(ii) Reserved.

(3) For Agusta service information identified in this AD, contact AgustaWestland, Product Support Engineering, Via del Gregge, 100, 21015 Lonate Pozzolo (VA) Italy, ATTN: Maurizio D'Angelo; telephone 39–0331–664757; fax 39–0331–664680; or at <http://www.agustawestland.com/technical-bulletins>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to: <http://>

www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued in Fort Worth, Texas, on February 20, 2014.

Lance T. Gant,

Acting Directorate Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2014–04274 Filed 3–7–14; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2013–0554; Directorate Identifier 2012–SW–009–AD; Amendment 39–17774; AD 2014–05–01]

RIN 2120–AA64

Airworthiness Directives; Eurocopter Deutschland GmbH Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for Eurocopter Deutschland GmbH (Eurocopter) Model EC135P1, EC135P2, EC135P2+, EC135T1, EC135T2, and EC135T2+ helicopters. This AD requires analyzing the main gearbox (MGB) oil for indications of metal chips or pieces, reviewing the MGB log or equivalent record, and inspecting certain teeth in the MGB after two chip indications. This AD was prompted by a partial tooth rupture found in an MGB that was returned to the manufacturer for repairs. The actions of this AD are intended to detect wear in the MGB that could lead to a gear tooth rupture, failure of the MGB, loss of power to the main rotor, and subsequent loss of control of the helicopter.

DATES: This AD is effective April 14, 2014.

The Director of the Federal Register approved the incorporation by reference of a certain document listed in this AD as of April 14, 2014.

ADDRESSES: For service information identified in this AD, contact American Eurocopter Corporation, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641–0000 or (800) 232–0323; fax (972) 641–3775; or at <http://www.eurocopter.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Aviation Safety Agency (EASA) AD, any incorporated-by-reference service information, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations Office, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Rao Edupuganti, Aviation Safety Engineer, Regulations and Policy Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email rao.edupuganti@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

On July 3, 2013, at 78 FR 40053, the **Federal Register** published our notice of proposed rulemaking (NPRM), which proposed to amend 14 CFR part 39 by adding an AD that would apply to Eurocopter Model EC135 P1, EC135 P2, EC135 P2+, EC135 T1, EC135 T2, and EC135 T2+ helicopters with an MGB, part number (P/N) 4649 010 003, 4649 010 005, 4649 010 006, 4649 010 006X, 4649 010 008, 4649 010 008X, 4649 001 007, 4649 010 010, or 4649 010 013 installed. The NPRM proposed to require analyzing the MGB oil for indications of metal chips or pieces, reviewing the MGB log or equivalent record, and inspecting certain teeth in the MGB after two chip indications. The proposed requirements were intended to detect wear in the MGB that could lead to a gear tooth rupture, failure of the MGB, loss of power to the main rotor, and subsequent loss of control of the helicopter.

The Required Actions section of the NPRM had a typographical error in some references to Eurocopter Alert Service Bulletin (ASB) EC135-63A-012, Revision 5, dated September 6, 2011. That error has been corrected in this AD.

The NPRM was prompted by AD No. 2009-0106R1, dated November 3, 2011, issued by EASA, which is the Technical Agent for the Member States of the European Union. EASA advises that an MGB was returned to the manufacturer for repair after "several chip indications." According to EASA, a

partial tooth rupture was detected after disassembly of the gearbox and removal of a drive pinion. EASA states the tooth rupture was determined to have been caused by wear. EASA AD No. 2009-0106R1 includes requirements and timetables for oil sampling and analysis; checking the gearbox log card for chip indications; and corrective measures for chip indications. It also states that a prescribed modification to the MGB would be terminating action for the AD.

Comments

We gave the public the opportunity to participate in developing this AD, but we received no comments on the NPRM (78 FR 40053, July 3, 2013).

FAA's Determination

These helicopters have been approved by the aviation authority of Germany and are approved for operation in the United States. Pursuant to our bilateral agreement with Germany, EASA, its technical representative, has notified us of the unsafe condition described in the EASA AD. We are issuing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs and that air safety and the public interest require adopting the AD requirements as proposed except for correcting the references to Eurocopter Alert Service Bulletin EC135-63A-012, Revision 5, dated September 6, 2011, in paragraphs (e)(2)(ii)(A), (e)(3), (e)(4)(i), and (e)(4)(ii). These corrections are consistent with the intent of the proposals in the NPRM (78 FR 40053, July 3, 2013) and will not increase the economic burden on any operator nor increase the scope of the AD.

Differences Between This AD and the EASA AD

The EASA AD applies to military EC635 helicopters. This AD does not apply to EC635 helicopters because they are not type certificated in the United States.

Related Service Information

Eurocopter issued ASB EC135-63A-012 on August 8, 2007, which was followed by five revisions, the most recent of which was issued September 6, 2011. The ASBs prescribe procedures to monitor and detect wear in time to prevent MGB tooth ruptures in main transmissions for EC135 and EC635 model helicopters. Revision 5 of the ASB prescribes procedures for taking and analyzing scheduled oil samples, identifying and addressing chip

indications, and inspecting certain teeth in gearboxes.

Costs of Compliance

We estimate that this AD affects 242 helicopters of U.S. Registry and that labor costs average \$85 per work-hour. Based on these estimates, we expect the following costs:

- Taking oil samples will take 1 work-hour. Assuming 2 samples per aircraft per year, we estimate a total cost of \$170. No parts are needed, so the total cost for the U.S. fleet is \$41,140.
- A laboratory analysis of 2 oil samples cost \$200 per helicopter for labor and equipment, for a total fleet cost of \$48,400.
- Inspecting the oil filter element for a chip requires about a half-hour of labor for a cost per helicopter of about \$43. No parts are needed.
- Inspecting certain teeth in the gearbox, performing a ground run, and inspecting for leaking oil takes 8 work-hours for a labor cost of \$680. Parts cost \$196, for a total cost per helicopter of \$876.
- If the oil sample analysis indicates metal chips, recording the results on the aircraft log card takes a half-hour for a labor cost of about \$43 per helicopter.
- The cost of examining the log card for any previously recorded chip indications is minimal.
- Inspecting the chip detector for deposits requires about 5 minutes of labor for a labor cost of about \$7.
- Replacing the MGB with an airworthy MGB requires 8 work-hours for a labor cost of \$680. Parts cost \$145,000 for total cost per helicopter of \$145,680.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on helicopters identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2014-05-01 Eurocopter Deutschland GmbH (Eurocopter): Amendment 39-17774; Docket No. FAA-2013-0554; Directorate Identifier 2012-SW-009-AD.

(a) Applicability

This AD applies to Model EC135P1, EC135P2, EC135P2+, EC135T1, EC135T2, and EC135T2+ helicopters with a main gearbox (MGB), part number (P/N) 4649 010 003, 4649 010 005, 4649 010 006, 4649 010 006X, 4649 010 008, 4649 010 008X, 4649 001 007, 4649 010 010, or 4649 010 013 installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as a tooth rupture in the MGB. This condition could result in failure of the MGB, loss of

power to the main rotor, and subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective April 14, 2014.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 100 hours time-in-service (TIS), and thereafter at intervals not to exceed 100 hours or 12 months, whichever occurs first, take an oil sample in accordance with the Accomplishment Instructions, Part 1, of Eurocopter Alert Service Bulletin EC135-63A-012, Revision 5, dated September 6, 2011 (ASB EC135-63A-012).

(2) Within 25 hours TIS after taking the oil sample in paragraph (e)(1) of this AD, analyze the oil sample in accordance with the Accomplishment Instructions, Part 2.A. through Part 2.C. of ASB EC135-63A-012, except that you are not required to contact Eurocopter.

(i) If the analysis indicates Stage II as specified by the Accomplishment Instructions, Part 2.B., of ASB EC135-63A-012, within 25 hours TIS, remove and inspect the oil filter element for a chip, defined as any solid piece of metal but not metallic fuzz or fine particles.

(A) If there are no chips, clean the oil filter element and chip detector, inspect the drive stage toothing, perform a ground run, and inspect for leaking oil in accordance with the Accomplishment Instructions, Part 4.A through 4.G, of ASB EC135-63A-012. Change the oil.

(B) If there is a chip, replace the MGB with an airworthy MGB before further flight.

(ii) If the analysis indicates Stage III as specified by the Accomplishment Instructions, Part 2.B., of ASB EC135-63A-012 and if the water content is between 0.1 and 0.5 percent, within 10 hours TIS, remove and inspect the oil filter element for a chip.

(A) If there are no chips, clean the oil filter element and chip detector, inspect the drive stage toothing, perform a ground run, and inspect for leaking oil in accordance with the Accomplishment Instructions, Part 4.A through 4.G, of ASB EC135-63A-012. Change the oil.

(B) If there is a chip, replace the MGB with an airworthy MGB before further flight.

(3) Before the MGB has accumulated 300 hours TIS, determine whether two or more chip indications have occurred. If two or more chip indications have occurred, inspect the drive stage toothing, perform a ground run, and inspect for leaking oil in accordance with the Accomplishment Instructions, Part 4.A through 4.G, of ASB EC135-63A-012.

(4) Any time there is a chip indication, remove and inspect the chip detector for deposits (fine particles or metallic fuzz) or chips, and remove and inspect the oil filter element for a chip.

(i) If there are no chips and a minimal amount of particles or metallic fuzz, corresponding to Figure 5, Stage A of ASB EC135-63A-012, clean the chip detector and the oil filter element and enter the chip

indication on the MGB log card before further flight.

(ii) If there are no chips and some particles or metallic fuzz, corresponding to Figure 5, Stage B of ASB EC135-63A-012, clean the chip detector and the oil filter element and enter the chip indication on the MGB log card before further flight, and within 10 hours TIS inspect the drive stage toothing, perform a ground run, and inspect for leaking oil in accordance with the Accomplishment Instructions, Part 4.A through 4.G, of ASB EC135-63A-012. Perform a ground run for 15 minutes at the flight-idle power setting, and then re-inspect the chip detector for a chip, particles, and metallic fuzz.

(iii) If there is a chip, replace the MGB with an airworthy MGB.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Rao Edupuganti, Aviation Safety Engineer, Regulations and Policy Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email rao.edupuganti@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

The subject of this AD is addressed in the European Aviation Safety Agency (EASA) AD No. 2009-0106R1, dated November 3, 2011. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA-2013-0554.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6320, Main Rotor Gearbox.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Eurocopter Alert Service Bulletin EC135-63A-012, Revision 5, dated September 6, 2011.

(ii) Reserved.

(3) For Eurocopter service information identified in this AD, contact American Eurocopter Corporation, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.eurocopter.com/techpub>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on February 24, 2014.

Bruce E. Cain,

Acting Directorate Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2014-04570 Filed 3-7-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2013-0642; Directorate Identifier 2011-SW-035-AD; Amendment 39-17777; AD 2014-05-04]

RIN 2120-AA64

Airworthiness Directives; Eurocopter Deutschland GmbH Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for Eurocopter Deutschland GmbH (Eurocopter) Model MBB-BK 117 C-2 helicopters with a jettisonable sliding door (door) installed. This AD requires inspecting the lock release assembly and the middle and upper lever locking bolts of each door, replacing any damaged parts with airworthy parts, and ensuring the door is correctly installed. This AD was prompted by the uncommanded detaching of a door from an MBB-BK 117 C-2 fuselage. The actions of this AD are intended to prevent the in-flight loss of the door, which could damage the helicopter and injure persons on the ground.

DATES: This AD is effective April 14, 2014.

The Director of the Federal Register approved the incorporation by reference of a certain document listed in this AD as of April 14, 2014.

ADDRESSES: For service information identified in this AD, contact American Eurocopter Corporation, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.eurocopter.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region,

2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the foreign authority's AD, any incorporated-by-reference service information, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations Office, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email matthew.fuller@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

On July 23, 2013, at 78 FR 44039, the **Federal Register** published our notice of proposed rulemaking (NPRM), which proposed to amend 14 CFR part 39 by adding an AD that would apply to Model MBB-BK 117 C-2 helicopters with a jettisonable door installed. The NPRM proposed to require inspecting the lock release assembly and the middle and upper lever locking bolts of each door, replacing any damaged parts with airworthy parts, and ensuring the door is correctly installed. The proposed requirements were intended to prevent the in-flight loss of the door, which could damage the helicopter and injure persons on the ground.

The NPRM was prompted by AD No. 2011-0107, dated June 7, 2011, issued by the European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union. AD No. 2011-0107 was issued to correct an unsafe condition for Eurocopter Model MBB-BK 117 C-2 helicopters with jettisonable sliding doors installed. EASA states that in early 2010 it received a report that the door guides of the jettison mechanism on an MBB-BK 117 C-2 helicopter released uncommanded while the door was being opened, resulting in the door detaching from the fuselage. EASA has determined that "this condition, if not detected and corrected, could result in cases of in-flight loss of the jettisonable

door, possibly resulting in damage to, or loss of control of, the helicopter, or injury to persons on the ground." As a result, EASA requires repetitive inspections for the correct installation of the doors, door guides, and release cables.

Comments

We gave the public the opportunity to participate in developing this AD, but we received no comments on the NPRM (78 FR 44039, July 23, 2013).

FAA's Determination

These helicopters have been approved by the aviation authority of Germany and are approved for operation in the United States. Pursuant to our bilateral agreement with Germany, EASA, its technical representative, has notified us of the unsafe condition described in the EASA AD. We are issuing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs and that air safety and the public interest require adopting the AD requirements as proposed.

Differences Between This AD and the EASA AD

This AD requires that the inspections be conducted within 50 hours time-in-service (TIS). The EASA AD requires that the inspections be conducted within 50 hours TIS or 60 days, whichever occurs first after the effective date of the EASA AD.

The EASA AD requires that you contact Eurocopter to determine corrective action, and this AD does not.

The EASA AD requires a repetitive inspection, each time when the installation of the door guides for the jettisonable sliding doors is accomplished. This AD does not require this repetitive inspection because that is considered normal maintenance.

Related Service Information

We reviewed Eurocopter Alert Service Bulletin MBB-BK117 C-2-52A-015, Revision 0, dated April 26, 2011 (ASB), for Model MBB-BK 117 C-2 helicopters with jettisonable sliding doors installed. The ASB calls for inspecting the lock release assembly for damage and correct installation and inspecting the middle lever and upper lever locking bolts for correct installation. The ASBs require the inspections to be conducted within 50 hours TIS or two months, whichever occurs first, and thereafter after every door guide installation.