

Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (k) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2015-0183, dated August 31, 2015, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-4203.

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Alert Operators Transmission A25L004-15, Rev 00, dated August 24, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email [airworthiness.A330-A340@airbus.com](mailto:airworthiness.A330-A340@airbus.com); Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 11, 2015.

**Jeffrey E. Duven,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2015-26603 Filed 10-16-15; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2015-0277; Directorate Identifier 2015-NE-05-AD; Amendment 39-18262; AD 2015-18-04]**

**RIN 2120-AA64**

#### Airworthiness Directives; CFM International S.A. Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** The FAA is correcting an airworthiness directive (AD) that published in the **Federal Register**. That AD applies to certain CFM International S.A. (CFM) CFM56-7B and CFM56-3 turbofan engines. Four headings in the Compliance section are incorrect. This document corrects the errors. In all other respects, the original document remains the same.

**DATES:** This final rule is effective on October 20, 2015. The effective date of AD 2015-18-04, Amendment 39-18262 (80 FR 55235, September 15, 2015) remains October 20, 2015.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Kyle Gustafson, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7183; fax: 781-238-7199; email: [kyle.gustafson@faa.gov](mailto:kyle.gustafson@faa.gov).

**SUPPLEMENTARY INFORMATION:** AD 2015-18-04, Amendment 39-18262 (80 FR 55235, September 15, 2015), requires AGB/transfer gearbox (TGB) magnetic

chip detector (MCD) inspection of the affected gearshafts until removal.

As published, four headings in the Compliance section are incorrect.

No other part of the final rule has been changed.

The effective date of AD 2015-18-04 remains October 20, 2015.

#### Correction of Regulatory Text

##### § 39.13 [Corrected]

■ 2. The FAA republishes airworthiness directive (AD) 2015-18-04, Amendment 39-18262 (80 FR 55235, September 15, 2015) as follows:

##### 2015-18-04 CFM International S.A.:

Amendment 39-18262; Docket No. FAA-2015-0277; Directorate Identifier 2015-NE-05-AD.

##### (a) Effective Date

This AD is effective October 20, 2015.

##### (b) Affected ADs

None.

##### (c) Applicability

This AD applies to CFM International S.A. (CFM) CFM56-7B and CFM56-3 engines with a 73-tooth or 41-tooth gearshaft installed in the accessory gearbox (AGB), that has a gearshaft serial number in Appendix A or Appendix B of CFM Service Bulletin (SB) No. CFM56-7B S/B 72-0964, Revision 1, dated December 15, 2014.

##### (d) Unsafe Condition

This AD was prompted by a report of an uncommanded in-flight shutdown on a CFM CFM56-7B engine following rupture of the 73-tooth gearshaft located in the engine AGB. We are issuing this AD to prevent failure of certain AGB gearshafts, which could lead to failure of one or more engines, loss of thrust control, and damage to the airplane.

##### (e) Compliance

Comply with this AD within the compliance times specified, unless already done.

##### (1) Initial AGB/Transfer Gearbox (TGB)/Magnetic Chip Detector (MCD) Inspection and Analysis for CFM56-7B Engines

(i) For affected 73-tooth gearshafts, perform an AGB/TGB MCD inspection within 250 flight hours (FHs) since last inspection, within 25 FHs from the effective date of this AD, or when the gearshaft accumulates 3,000 FHs since new, whichever comes later.

(ii) For affected 41-tooth gearshafts, perform an AGB/TGB MCD inspection within 250 FHs since last inspection, within 25 FHs from the effective date of this AD, or when the gearshaft accumulates 6,000 FHs since new, whichever comes later.

(iii) If any magnetic particles, including fuzz, are seen, determine with laboratory analysis if the particles are 73-tooth or 41-tooth gearshaft material.

(iv) If the particles are 73-tooth or 41-tooth gearshaft material, remove the affected gearshaft(s) within 75 FHs since the AGB/TGB MCD inspection.

## (2) Repetitive AGB/TGB MCD Inspection and Analysis for CFM56-7B Engines

(i) For affected 73-tooth gearshafts, perform an AGB/TGB MCD inspection and laboratory analysis within every 500 FHs since the last AGB/TGB MCD inspection until affected gearshaft is removed.

(ii) For affected 41-tooth gearshafts, perform an AGB/TGB MCD inspection and laboratory analysis within every 500 FHs since the last AGB/TGB MCD inspection until affected gearshaft is removed.

(iii) If any magnetic particles, including fuzz, are seen, determine with laboratory analysis if the particles are 73-tooth or 41-tooth gearshaft material.

(iv) If the particles are 73-tooth or 41-tooth gearshaft material, remove the affected gearshaft(s) within 75 FHs since the AGB/TGB MCD inspection.

## (f) Mandatory Terminating Action for CFM56-7B Engines

(1) Remove the affected 73-tooth gearshaft prior to the gearshaft accumulating 6,000 FHs since new or within 50 FHs after the effective date of this AD, whichever comes later.

(2) Remove the affected 41-tooth gearshaft prior to the gearshaft accumulating 9,000 FHs since new or within 50 FHs after the effective date of this AD, whichever comes later.

## (g) Installation Prohibition for CFM56-3 and CFM56-7B Engines

After the effective date of this AD, do not install an affected gearshaft into an AGB.

## (h) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: [ANE-AD-AMOC@faa.gov](mailto:ANE-AD-AMOC@faa.gov).

## (i) Related Information

For more information about this AD, contact Kyle Gustafson, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7183; fax: 781-238-7199; email: [kyle.gustafson@faa.gov](mailto:kyle.gustafson@faa.gov).

## (j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on October 20, 2015.

(i) CFM International Service Bulletin No. CFM56-7B S/B 72-0964, Revision 1, dated December 15, 2014.

(ii) Reserved.

(4) For CFM service information identified in this AD, contact CFM International Inc., Aviation Operations Center, 1 Neumann Way, M/D Room 285, Cincinnati, OH 45125; phone: 877-432-3272; fax: 877-432-3329; email: [aviation.fleetssupport@ge.com](mailto:aviation.fleetssupport@ge.com).

(5) You may view this service information at FAA, Engine & Propeller Directorate, 12

New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(6) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on October 6, 2015.

**Ann C. Mollica,**

*Acting Directorate Manager, Engine & Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 2015-26345 Filed 10-16-15; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2015-1835; Airspace Docket No. 14-AGL-7]

#### Establishment of Class E Airspace; Hart/Shelby, MI

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action establishes Class E airspace at Hart/Shelby, MI. Controlled airspace is necessary to accommodate new Standard Instrument Approach Procedures (SIAPs) at Oceana County Airport. The FAA is proposing this action to enhance the safety and management of Instrument Flight Rules (IFR) operations at the airport.

**DATES:** Effective 0901 UTC, December 10, 2015. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.9Z Airspace Designations and Reporting Points and subsequent amendments can be viewed on line at [http://www.faa.gov/air\\_traffic/publications](http://www.faa.gov/air_traffic/publications). For further information, you can contact the Airspace Policy and ATC Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 29591; telephone: 202-267-8783. The order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/>

[federalregister.gov/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.federalregister.gov/code_of_federal_regulations/ibr_locations.html).

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**FOR FURTHER INFORMATION CONTACT:** Rebecca Shelby, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone: 817-222-5857.

#### SUPPLEMENTARY INFORMATION:

##### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part, A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes Class E airspace at Oceana County Airport, Hart/Shelby, MI.

##### History

On July 28, 2015, the FAA published in the **Federal Register** a notice of proposed rulemaking (NPRM) to establish Class E airspace extending upward from 700 feet above the surface at Oceana County Airport, Hart/Shelby, MI., (80 FR 44895). Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9Z, dated August 6, 2015, and effective September 15, 2015, which is incorporated by reference in 14 CFR part 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

##### Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, and effective September 15, 2015. FAA Order 7400.9Z is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.9Z lists Class A, B, C, D, and E airspace areas,