

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2015-5809; Directorate Identifier 2015-NM-055-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to supersede Airworthiness Directive (AD) 2006-19-12, which applies to certain The Boeing Model 777-200 and -300 series airplanes. AD 2006-19-12 currently requires inspecting the lower web of the aft fairing of the engine struts for any discoloration and doing any related investigative and corrective action if necessary; inspecting the heat shield castings for any damage and doing any corrective action if necessary; installing gap cover strips; and replacing insulation blankets with new insulation blankets. Since we issued AD 2006-19-12, we have received a report that an aft fairing lower spar web exceeded the allowable conductivity limits. This proposed AD would also require, depending on airplane configuration, one-time or repetitive detailed inspections for cracking and deformation, as applicable, of the aft fairing lower structure, and one-time or repetitive conductivity inspections of the aft fairing lower structure and related investigative and corrective actions if necessary. This proposed AD also adds airplanes to the applicability. We are proposing this AD to detect and correct degradation of the aft fairing lower web, which could lead to cracking of the web and could allow flammable fluids to leak into the heat shield pan castings, and consequent increased risk of an uncontained fire and subsequent structural damage.

DATES: We must receive comments on this proposed AD by January 4, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-5809.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-5809; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Sue Lucier, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-917-6438; fax: 425-917-6590; email: suzanne.lucier@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2015-5809; Directorate Identifier 2015-NM-055-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any

personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On September 13, 2006, we issued AD 2006-19-12, Amendment 39-14769 (71 FR 55727, September 25, 2006), for certain Boeing Model 777-200 and -300 series airplanes. AD 2006-19-12 requires inspecting the lower web of the aft fairing of engine struts for any discoloration and doing any related investigative and corrective action if necessary; inspecting the heat shield castings for any damage and doing any corrective action if necessary; installing gap cover strips; and replacing insulation blankets with new insulation blankets. AD 2006-19-12 resulted from a report that several discolored fairing lower webs and some damaged/deteriorated insulation blankets were found in the aft fairings of engine struts. We issued AD 2006-19-12 to prevent cracking of lower webs of the aft fairings, which could result in flammable hydraulic fluid leaking onto or near an ignition source, and possibly result in an uncontrollable fire in the engine strut area.

Actions Since AD 2006-19-12, Amendment 39-14769 (71 FR 55727, September 25, 2006) Was Issued

Since we issued AD 2006-19-12, Amendment 39-14769 (71 FR 55727, September 25, 2006), we have received a report that an aft fairing lower spar web exceeded the allowable conductivity limits. An investigation concluded that wear to the pan casting and gap cover strips allowed increased heat into the aft fairing heat shield cavity, which exceeded the thermal capability of the insulation blankets.

Related Service Information Under 14 CFR Part 51

We have reviewed Boeing Service Bulletin 777-54-0026, Revision 2, dated January 5, 2012. The service information describes procedures for a detailed inspection of the gap cover strips and heat shield pan castings for damage, corrective actions, and installation of new gap cover strip fillers, new velcro strips, and new aft fairing insulation blankets.

We reviewed Boeing Special Attention Service Bulletin 777-54-0038, dated March 6, 2015. The service information describes procedures for one-time and repetitive detailed inspections for any cracking and deformation, as applicable, of the aft fairing lower structure; conductivity

inspections of the aft fairing lower structure; and related investigative and corrective actions.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this NPRM.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would retain all requirements of AD 2006–19–12, Amendment 39–14769 (71 FR 55727, September 25, 2006). In addition, this proposed AD would add airplanes to the applicability of this AD. This proposed

AD would also require accomplishing the actions specified in the service information described previously.

The phrase “related investigative actions” is used in this proposed AD. “Related investigative actions” are follow-on actions that (1) are related to the primary action, and (2) further investigate the nature of any condition found. Related investigative actions in an AD could include, for example, inspections.

The phrase “corrective actions” is used in this proposed AD. “Corrective actions” are actions that correct or address any condition found. Corrective actions in an AD could include, for example, repairs.

Change to AD 2006–19–12, Amendment 39–14769 (71 FR 55727, September 25, 2006)

Since AD 2006–19–12, Amendment 39–14769 (71 FR 55727, September 25,

2006) was issued, the AD format has been revised, and certain paragraphs have been rearranged. As a result, the corresponding paragraph identifiers have been redesignated in this proposed AD, as listed in the following table:

REVISED PARAGRAPH IDENTIFIERS

Requirement in AD 2006–19–12	Corresponding requirement in this proposed AD
paragraph (f) paragraph (g) paragraph (h)	paragraph (g) paragraph (h) paragraph (i)

Costs of Compliance

We estimate that this proposed AD affects 99 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection and other actions [retained actions from AD 2006–19–12, Amendment 39–14769 (71 FR 55727, September 25, 2006)].	Up to 11 work-hours × \$85 per hour = \$935, depending on airplane configuration.	Up to \$16,179, depending on airplane configuration.	Up to \$17,114, depending on airplane configuration.	Up to \$1,694,286, depending on airplane configuration
Inspections [new proposed action].	Up to 24 work-hours × \$85 per hour = \$2,040, depending on airplane configuration.	\$0	Up to \$2,040, depending on airplane configuration.	Up to \$201,960, depending on airplane configuration

We estimate the following costs to do any necessary related investigative and corrective actions that would be

required based on the results of the proposed inspection. We have no way of determining the number of aircraft that

might need these inspections and replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Related Investigative Actions	Up to 36 work-hours × \$85 per hour = \$3,060, depending on airplane configuration.	\$0	Up to \$3,060, depending on airplane configuration
Corrective Actions	Up to 38 work-hours × \$85 per hour = \$3,230, depending on airplane configuration.	0	Up to \$3,230, depending on airplane configuration

According to the manufacturer, all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue

rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in

air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2006–19–12, Amendment 39–14769 (71 FR 55727, September 25, 2006), and adding the following new AD:

The Boeing Company: Docket No. FAA–2015–5809; Directorate Identifier 2015–NM–055–AD.

(a) Comments Due Date

The FAA must receive comments on this AD action by January 4, 2016.

(b) Affected ADs

This AD replaces AD 2006–19–12, Amendment 39–14769 (71 FR 55727, September 25, 2006).

(c) Applicability

This AD applies to The Boeing Company Model 777–200, –200LR, –300, –300ER, and 777F series airplanes, certified in any category, as identified in Boeing Special Attention Service Bulletin 777–54–0038, dated March 6, 2015.

(d) Subject

Air Transport Association (ATA) of America Code 54, Nacelles/pylons.

(e) Unsafe Condition

This AD was prompted by a report that an aft fairing lower spar web exceeded the allowable conductivity limits. An investigation concluded that wear to the pan casting and gap cover strips allowed increased heat into the aft fairing heat shield cavity. We are proposing this AD to detect and correct degradation of the aft fairing lower web, which could lead to cracking of the web and could allow flammable fluids to leak into the heat shield pan castings, and consequent increased risk of an uncontained fire and subsequent structural damage.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Inspection, Installation, and Replacement Actions With No Changes

This paragraph restates the actions required by paragraph (f) of AD 2006–19–12, Amendment 39–14769 (71 FR 55727, September 25, 2006), with no changes. For Model 777–200 and –300 series airplanes identified in Boeing Special Attention Service Bulletin 777–54–0021, Revision 1, dated March 16, 2006: Except as provided by paragraph (h) of this AD, within 12 months after October 30, 2006 (the effective date of AD 2006–19–12), do the actions specified in paragraphs (g)(1), (g)(2), (g)(3), and (g)(4) of this AD, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777–54–0021, Revision 1, dated March 16, 2006.

(1) Do a general visual inspection of the lower web of the aft fairing for any discoloration and do any related investigative action.

(2) Do a general visual inspection of the heat shield castings for any damage (crack(s), dent(s), gouge(s), warpage, fretting, or missing/loose nutplates).

(3) Install gap cover strips on the heat shield pans.

(4) Replace insulation blankets on the heat shield pans with new insulation blankets.

(h) Retained Repair Instructions

This paragraph restates the actions required by paragraph (g) of AD 2006–19–12, Amendment 39–14769 (71 FR 55727, September 25, 2006), with no changes. If any damage, discoloration, heat damage, or crack is found during any inspection required by paragraph (g) of this AD: Before further flight, do all applicable corrective actions in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, or in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777–54–0021, Revision 1, dated March 16, 2006.

(i) Retained Credit for Previous Actions With Revised Format

This paragraph restates the credit provided by paragraph (h) of AD 2006–19–12, Amendment 39–14769 (71 FR 55727,

September 25, 2006), with revised format. This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before October 30, 2006 (the effective date of AD 2006–19–12, Amendment 39–14769 (71 FR 55727, September 25, 2006)) using Boeing Special Attention Service Bulletin 777–54–0021, dated June 23, 2005, except where Boeing Special Attention Service Bulletin 777–54–0021, dated June 23, 2005, does not provide an International Annealed Copper Standard (IACS) value for determining the results of the inspection for heat damage, the maximum acceptable IACS value is 42 percent. Boeing Special Attention Service Bulletin 777–54–0021, dated June 23, 2005, is not incorporated by reference in this AD.

(j) New Requirements: Detailed and Conductivity Inspections and Related Investigative and Corrective Actions (Repetitive Inspections for Certain Airplanes)

Within 24 months after the effective date of this AD: Do detailed and conductivity inspections of the aft fairing lower structure for cracks and deformation, as applicable, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777–54–0038, dated March 6, 2015. Do all applicable related investigative and corrective actions before further flight. For Group 1, Configurations 1 and 3 airplanes, and Group 2, Configuration 1, airplanes, identified in Boeing Special Attention Service Bulletin 777–54–0038, dated March 6, 2015, repeat the inspections thereafter at intervals not to exceed 24 months until the terminating action specified in paragraph (k) of this AD is done.

(k) Optional Terminating Action

Accomplishing a detailed inspection of the gap cover strips and heat shield pan castings for damage and applicable corrective actions, and installation of new gap cover strip fillers, new velcro strips, and new aft fairing insulation blankets, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 777–54–0026, Revision 2, dated January 5, 2012, concurrently with accomplishing detailed and conductivity inspections and all applicable related investigative and corrective actions required by paragraph (j) of this AD, terminates the repetitive inspections specified in paragraph (j) of this AD; except where Boeing Service Bulletin 777–54–0026, Revision 2, dated January 5, 2012, specifies to contact the manufacturer, repair using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the

attention of the person identified in paragraph (m)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for AD 2006–19–12, Amendment 39–14769 (71 FR 55727, September 25, 2006) are approved as AMOCs for the corresponding provisions of paragraphs (g), (h), and (i) of this AD.

(m) Related Information

(1) For more information about this AD, contact Sue Lucier, Aerospace Engineer, Propulsion Branch, ANM–140S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone: 425–917–6438; fax: 425–917–6590; email: suzanne.lucier@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on November 12, 2015.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015–29617 Filed 11–19–15; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Highway Administration

23 CFR Parts 771 and 774

Federal Transit Administration

49 CFR Part 622

[Docket No. FHWA–2015–0011]

FHWA RIN 2125–AF60

FTA RIN 2132–AB26

Environmental Impact and Related Procedures

AGENCY: Federal Highway Administration (FHWA), Federal Transit Administration (FTA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This NPRM provides interested parties with the opportunity to comment on proposed revisions to the FHWA and FTA joint regulations that implement the National Environmental Policy Act (NEPA) and Section 4(f) of the Department of Transportation Act. The revisions are prompted by the enactment of the Moving Ahead for Progress in the 21st Century Act (MAP–21), which requires rulemaking to address programmatic approaches. This NPRM proposes to revise the FHWA/FTA Environmental Impact and Related Procedures and Parks, Recreation Areas, Wildlife and Waterfowl Refuges, and Historic Sites regulations due to MAP–21 changes to the environmental review process that FHWA and FTA have not previously captured in other rulemakings, such as the use of programmatic agreements and the use of single final environmental impact statement/record of decision documents. In addition, FHWA and FTA propose changes to the regulatory text to improve readability and to reflect current practice, consistent with an Executive order to improve regulations and regulatory review. The FHWA and FTA seek comments on the proposals contained in this notice.

DATES: Comments must be received on or before January 19, 2016.

ADDRESSES: To ensure that you do not duplicate your docket submissions, please submit them by only one of the following means:

Federal eRulemaking Portal: Go to <http://www.regulations.gov> and follow the online instructions for submitting comments.

Mail: Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Ave. SE., West Building Ground Floor Room W12–140, Washington, DC 20590.

Hand Delivery: West Building Ground Floor, Room W12–140, 1200 New Jersey Ave. SE., between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The telephone number is (202) 366–9329.

Instructions: You must include the agency name and docket number or the Regulatory Identifier Number (RIN) for the rulemaking at the beginning of your comments. All comments received will be posted without change to <http://www.regulations.gov>, including any personal information provided.

FOR FURTHER INFORMATION CONTACT: For the FHWA: Neel Vanikar, Office of Project Development and Environmental Review, (202) 366–2068, or Diane

Mobley, Office of Chief Counsel, (202) 366–1366. For FTA: Megan Blum, Office of Planning and Environment, (202) 366–0463, or Helen Serassio, Office of Chief Counsel, (202) 366–1974. The FHWA and FTA are both located at 1200 New Jersey Ave. SE., Washington, DC 20590. Office hours are from 9:00 a.m. to 5:00 p.m., Monday through Friday, except Federal holidays.

SUPPLEMENTARY INFORMATION:

Background

On July 6, 2012, President Obama signed into law MAP–21 (Pub. L. 112–141, 126 Stat. 405), which contains new requirements that FHWA and FTA, hereafter referred to as the “Agencies,” must meet in complying with NEPA (42 U.S.C. 4321 *et seq.*), as well as a requirement to initiate a rulemaking to allow for the use of programmatic approaches. 23 U.S.C. 139(b)(3)(A). Through this NPRM, the Agencies propose to revise their regulations that implement NEPA at 23 CFR part 771—Environmental Impact and Related Procedures, and 23 U.S.C. 138 and 49 U.S.C. 303 (hereafter referred to as Section 4(f)¹) at 23 CFR part 774—Parks, Recreation Areas, Wildlife and Waterfowl Refuges, and Historic Sites. The proposed revisions would reflect MAP–21 requirements and better reflect current Agency practice, as well as improve readability consistent with Executive Order 13563, “Improving Regulation and Regulatory Review” (2011).

General Discussion of the Proposals

The following bullets are sections of MAP–21 that affect 23 CFR parts 771 and 774; the list does not include the sections of MAP–21 that have been the subject of other rulemakings:

- Section 1119(c)(2) revised the Section 4(f) exception for park road and parkway projects to apply to Federal lands transportation facilities, which affects the Section 4(f) exception in 774.13(e);
- Section 1122 replaced the former “transportation enhancement projects program” with a new “transportation alternatives projects program,” which affects the Section 4(f) exception in 774.13(g);
- Section 1302 amended 23 U.S.C. 108 to address advance acquisition of real property interests, which affects the

¹ Section 4(f) of the Department of Transportation Act of 1966 was repealed in 1983 when it was codified without substantive change at 49 U.S.C. 303. A provision with the same meaning is found at 23 U.S.C. 138. This regulation continues to refer to Section 4(f) as such because the policies Section 4(f) engendered are widely referred to as “Section 4(f)” matters.