

to the manager of the ACO, send it to the attention of the person identified in paragraph (j)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact David Enns, Aerospace Engineer, Wichita ACO, FAA, 1801 S. Airport Road, Room 100, Wichita, Kansas 67209; phone: (316) 946-4147; fax: (316) 946-4107; email: david.enns@faa.gov.

(2) For service information identified in this AD, contact B/E Aerospace, Inc., 10800 Pflumm Road, Commercial Aircraft Products Group, Lenexa, Kansas 66215; telephone: (913) 338-9800; fax: (913) 338-8419; Internet: www.beaerospace.com. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on January 6, 2016.

Kelly Broadway,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-00374 Filed 1-14-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-0068; Directorate Identifier 2015-CE-037-AD]

RIN 2120-AA64

Airworthiness Directives; SOCATA Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for SOCATA Models MS 880B, MS 885, MS 892A-150, MS 892E-150, MS 893A, MS 893E, MS 894A, MS 894E, Rallye 100S, Rallye 150ST, Rallye 150T, Rallye 235E, and Rallye 235C airplanes that would supersede AD 92-06-10. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as fatigue failure of the nose landing gear wheel axle. We are issuing this proposed AD to require actions to

address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by February 29, 2016.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact SOCATA, Direction des services, 65921 Tarbes Cedex 9, France; phone: +33 (0) 5 62 41 73 00; fax: +33 (0) 5 62 41 76 54; email: info@socata.daher.com; Internet: <http://www.tbm.aero/>. For the United States, contact SOCATA NORTH AMERICA, North Perry Airport, 601 NE 10 Street, Pompano Beach, Florida 33060; phone: (954) 366-3331; Internet: <http://www.socatanorthamerica.com/default.htm>. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106.

FOR FURTHER INFORMATION CONTACT:

Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090; email: albert.mercado@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2016-0068; Directorate Identifier 2015-CE-037-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each

substantive verbal contact we receive about this proposed AD.

Discussion

On February 25, 1992, we issued AD 92-06-10, Amendment 39-8190 (57 FR 8063; March 6, 1992) ("92-06-10"). That AD required actions intended to address an unsafe condition on SOCATA Models MS 880B, MS 885, MS 894A, MS 893A, MS 892A-150, MS 892E-150, MS 893E, MS 894E, Rallye 100S, Rallye 150T, Rallye 150ST, Rallye 235E, and Rallye 235C airplanes and was based on mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country.

Since we issued AD 92-06-10, new findings led to an adjustment of the inspection intervals.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2015-0203, dated October 7, 2015 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

A nose landing gear (NLG) wheel axle rupture occurred in service. The results of the technical investigation revealed that this failure was due to premature wear.

This condition, if not detected and corrected, could lead to cracks in the axle and detachment of axle and wheel, possibly resulting in failure of the NLG with consequent damage to the aeroplane and injury to occupants.

To address this potential unsafe condition, DGAC France issued AD 91-163(A) (later revised twice) to require repetitive detailed inspections (DET) of the NLG wheel axle and replacement of the NLG wheel axle attachment screws in accordance with the instructions of SOCATA Service Bulletin (SB) 150-32.

Since DGAC France AD 91-163(A)R2 was issued, new findings led to an adjustment of the inspection interval. Consequently, SOCATA issued SB 150-32, now at Revision 3.

For the reasons described above, this new AD retains the requirements of the DGAC France AD 91-163(A)R2, which is superseded, but requires these actions to be accomplished within reduced intervals.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-0068.

Related Service Information Under 1 CFR Part 51

SOCATA has issued Daher-Socata Mandatory Service Bulletin SB 150-32, Revision 3, dated September 2015. The service bulletin describes procedures for inspection of the nose gear wheel axle. This service information is reasonably available because the interested parties

have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this NPRM.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 77 products of U.S. registry. We also estimate that it would take about 10 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$500 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$103,950, or \$1,350 per product.

In addition, we estimate that any necessary follow-on actions would take about 3 work-hours and require parts costing \$1,450, for a cost of \$1,705 per product. We have no way of determining the number of products that may need these actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Amendment 39–8190 (57 FR 8063; March 6, 1992), and adding the following new AD:

SOCATA: Docket No. FAA–2016–0068; Directorate Identifier 2015–CE–037–AD.

(a) Comments Due Date

We must receive comments by February 29, 2016.

(b) Affected ADs

This AD supersedes AD 92–06–10 Amendment 39–8190 (57 FR 8063; March 6, 1992) ("AD 92–06–10").

(c) Applicability

This AD applies to SOCATA Models MS 880B, MS 885, MS 892A–150, MS 892E–150, MS 893A, MS 893E, MS 894A, MS 894E, Rallye 100S, Rallye 150ST, Rallye 150T, Rallye 235E, and Rallye 235C airplanes, all serial numbers, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 32: Landing Gear.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as fatigue failure of the nose landing gear wheel axle. We are issuing this proposed AD to detect and correct chafing and cracking of the nose gear wheel axle, which could lead to failure of the nose landing gear with consequent damage to the airplane and/or occupants.

(f) Actions and Compliance

Unless already done, do the following actions in paragraphs (f)(1) through (f)(5) of this AD, including all subparagraphs.

(1) Do a detailed visual inspection of the intersection between the axle radius and the nose landing gear fork area for chafing at whichever occurs later in paragraph (f)(1)(i) or (f)(1)(ii) of this AD and repetitively thereafter at intervals not to exceed 200 hours time-in-service (TIS) following Daher-Socata Mandatory Service Bulletin SB 150–32, Revision 3, dated September 2015:

(i) Upon accumulating 200 hours TIS since the airplane's first flight or 200 hours TIS since the last inspection required by AD 92–06–10; or

(ii) Within the next 50 hours TIS after the effective date of this AD or within 500 hours TIS since the last inspection required by AD 92–06–10, whichever occurs first.

(2) Do a dye penetrant inspection on the nose wheel axle for cracks, distortion, and nicks or wear at whichever occurs later in paragraph (f)(2)(i) or (f)(2)(ii) of this AD and repetitively thereafter at intervals not to exceed 200 hours time-in-service (TIS) following Daher-Socata Mandatory Service Bulletin SB 150–32, Revision 3, dated September 2015:

(i) Upon accumulating 200 hours TIS since the airplane's first flight or 200 hours TIS since the last inspection required by AD 92–06–10; or

(ii) Within the next 50 hours TIS after the effective date of this AD or within 500 hours TIS since the last inspection required by AD 92–06–10, whichever occurs first.

(3) If any cracks or damage is found in any inspection required by paragraphs (f)(1) or (f)(2) in this AD, contact SOCATA for FAA-approved repair or replacement instructions approved specifically for this AD and, before further flight, implement those instructions. Use the contact information found in paragraph (i) of this AD to contact SOCATA.

(4) Replace the nose landing gear wheel axle attachment screws with new screws at whichever occurs later in paragraph (f)(4)(i) or (f)(4)(ii) of this AD following Daher-Socata Mandatory Service Bulletin SB 150–32, Revision 3, dated September 2015:

(i) Upon accumulating 2,000 hours TIS since airplane's first flight or 2,000 hours TIS since last nose landing gear wheel attachment screw replacement with new screws; or

(ii) Within 50 hours TIS since April 17, 1992 (the effective date retained from AD 92–06–10).

(5) After the effective date of this AD, a used nose landing gear or a used nose landing gear wheel axle may be installed provided it has been inspected and found free of cracks and/or damage and the nose landing gear wheel axle attachment screws have been replaced with new screws as specified in paragraphs (f)(1), (f)(2), and (f)(4) of this AD.

(g) Credit for Actions Accomplished in Accordance With Previous Service Information

This AD allows credit for the inspections required in paragraph (f)(1) and (f)(2) of this AD, if done before the effective date of this AD, following Daher-Socata Mandatory Service Bulletin SB 150–32, Revision 2, dated January 1994.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4119; fax: (816) 329–4090; email: albert.mercado@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(i) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD 2015–0203, dated October 7, 2015; and Daher-Socata Mandatory Service Bulletin SB 150–32, Revision 2, dated January 1994, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–0068. For service information related to this AD, contact SOCATA, Direction des services, 65921 Tarbes Cedex 9, France; phone: +33 (0) 5 62 41 73 00; fax: +33 (0) 5 62 41 76 54; email: info@socata.daher.com; Internet: <http://www.tbm.aero/>. For the United States, contact SOCATA NORTH AMERICA, North Perry Airport, 601 NE 10 Street, Pompano Beach, Florida 33060;

phone: (954) 366–3331; Internet: <http://www.socatanorthamerica.com/default.htm>. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Issued in Kansas City, Missouri, on January 5, 2016.

Kelly Broadway,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–00320 Filed 1–14–16; 8:45 am]

BILLING CODE 4910–13–P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA–R09–OAR–2012–959; FRL–9941–14–Region 9]

Revisions to the California State Implementation Plan, Sacramento Metropolitan Air Quality Management District

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: The Environmental Protection Agency (EPA) is proposing a partial approval and partial disapproval of revisions to the Sacramento Metropolitan (Metro) Air Quality Management District (SMAQMD or District) portion of the California State Implementation Plan (SIP). These revisions concern the District’s demonstration regarding Reasonably Available Control Technology (RACT) requirements for the 1997 8-hour ozone National Ambient Air Quality Standard (NAAQS). We are proposing action on a local SIP revision under the Clean Air Act (CAA or the Act). We are taking comments on this proposal and plan to follow with a final action.

DATES: Any comments must arrive by February 16, 2016.

ADDRESSES: Submit your comments, identified by Docket ID No. EPA–R09–OAR–2012–959 at <http://www.regulations.gov>, or via email to Steckel.Andrew@epa.gov. For comments submitted at Regulations.gov, follow the online instructions for submitting comments. Once submitted, comments cannot be edited or removed from

Regulations.gov. For either manner of submission, the EPA may publish any comment received to its public docket. Do not submit electronically any information you consider to be Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Multimedia submissions (audio, video, etc.) must be accompanied by a written comment. The written comment is considered the official comment and should include discussion of all points you wish to make. The EPA will generally not consider comments or comment contents located outside of the primary submission (*i.e.*, on the web, cloud, or other file sharing system). For additional submission methods, please contact the person identified in the **FOR FURTHER INFORMATION CONTACT** section. For the full EPA public comment policy, information about CBI or multimedia submissions, and general guidance on making effective comments, please visit <http://www2.epa.gov/dockets/commenting-epa-dockets>.

FOR FURTHER INFORMATION CONTACT: Stanley Tong, EPA Region IX, (415) 947–4122, tong.stanley@epa.gov.

SUPPLEMENTARY INFORMATION: Throughout this document, “we,” “us” and “our” refer to the EPA.

Table of Contents

- I. The State’s Submittal
 - A. What documents did the State submit?
 - B. Are there other versions of these documents?
 - C. What is the purpose of the RACT SIP submissions?
- II. The EPA’s Evaluation and Proposed Action
 - A. How is the EPA evaluating the RACT SIP submissions?
 - B. Do the RACT SIP submissions meet the evaluation criteria?
 - C. What are the RACT deficiencies?
 - D. EPA Recommendations To Further Improve the RACT SIP.
 - E. Proposed Action and Public Comment
- III. Statutory and Executive Order Reviews

I. The State’s Submittal

A. What documents did the State submit?

Table 1 lists the documents addressed by this proposal with the dates that they were adopted by the local air agency and submitted to the EPA by the California Air Resources Board (CARB).

TABLE 1—SUBMITTED DOCUMENTS

Local agency	Document	Adopted	Submitted
SMAQMD	Reasonably Available Control Technology (RACT) as Applicable to the 8-Hour Ozone Standard, dated October 26, 2006 (“2006 RACT SIP”).	10/26/06	07/11/07