

recommending rulemaking to: (1) Require that the post-shutdown decommissioning activities report (PSDAR) contain a description of how the spent fuel stored under a general independent spent fuel storage installation license will be removed from the reactor site in accordance with the regulatory requirements in § 50.82, “Termination of License,” of title 10 of the *Code of Federal Regulations* (10 CFR), 10 CFR 50.54(bb), 10 CFR 52.110, “Termination of License,” and 10 CFR 72.218, “Termination of Licenses;” and (2) amend 10 CFR 51.53, “Postconstruction Environmental Reports,” and 10 CFR 51.95, “Postconstruction Environmental Impact Statements,” to clarify that the requirements for a license amendment before decommissioning activities may commence applies only to non-power reactors, as specified in 10 CFR 50.82(b).

In the draft regulatory basis, the NRC concludes that regulatory activities other than rulemaking—such as guidance development—should be used to address stakeholder concerns regarding the appropriate role of State and local governments in the decommissioning process, the level of NRC review and approval of the PSDAR, and the 60 year limit for power reactor decommissioning. The NRC also determined that additional stakeholder input is needed prior to finalizing recommendations related to cyber security, drug and alcohol testing, certified fuel handler training and minimum staffing, aging management, and fatigue management. The NRC is seeking specific public input on these topics as part of the public comment request on the entire draft regulatory basis.

To supplement the draft regulatory basis, the NRC has prepared a preliminary draft regulatory analysis, in which the costs, benefits, and other impacts of each rulemaking alternative are presented in order to determine the economic impact to industry and to government from the proposed rulemaking. The NRC prepared the preliminary draft regulatory analysis to support decision making during the preparation of the draft regulatory basis document, which includes an evaluation of possible regulatory improvements for reactors transitioning to decommissioning.

### III. Request for Comment

The NRC is requesting comment on the preliminary draft regulatory analysis that was prepared to support the draft regulatory basis for the “Regulatory Improvements for Reactors Transitioning to Decommissioning”

rulemaking. As you prepare your comments, consider the following general questions:

1. Is the NRC considering appropriate alternatives for each regulatory area described in the preliminary draft regulatory analysis?

2. Are there additional factors that the NRC should consider in each regulatory area? What are these factors?

3. Is there additional information concerning regulatory impacts that the NRC should include in its regulatory analysis for this rulemaking?

4. Are all costs and benefits properly addressed to determine the economic impact of the rulemaking alternatives?

5. What additional costs or cost savings will the rulemaking alternatives cause to society, industry, and government?

### IV. Cumulative Effects of Regulation

The cumulative effects of regulation (CER) describe the challenges that licensees or other impacted entities (such as State agency partners) may face while implementing new regulatory positions, programs, and requirements (e.g., rules, generic letters, backfits, inspections). The CER is an organizational effectiveness challenge that results from a licensee or impacted entity implementing a number of complex positions, programs, or requirements within a limited implementation period and with available resources (which may include limited available expertise to address a specific issue). The NRC has implemented CER enhancements to the rulemaking process to facilitate public involvement throughout the rulemaking process. In developing comments on the preliminary draft regulatory analysis, consider the following questions:

(1) In light of any current or projected CER challenges, what should be a reasonable effective date, compliance date, or submittal date(s) from the time the final rule is published to the actual implementation of any new proposed requirements, including changes to programs, procedures, or the facility?

(2) If current or projected CER challenges exist, what should be done to address this situation (e.g., if more time is required to implement the new requirements, what period of time would be sufficient, and why such a time frame is necessary)?

(3) Do other regulatory actions (e.g., orders, generic communications, license amendment requests, and inspection findings of a generic nature) by the NRC or other agencies influence the implementation of the potential proposed requirements?

(4) Are there unintended consequences? Does the potential proposed action create conditions that would be contrary to the potential proposed action’s purpose and objectives? If so, what are the consequences and how should they be addressed?

(5) Please provide information on the costs and benefits of the potential proposed action. This information will be used to support additional regulatory analysis by the NRC.

### V. Plain Writing

The Plain Writing Act of 2010 (Pub. L. 111–274) requires Federal agencies to write documents in a clear, concise, well-organized manner. The NRC has written this document to be consistent with the Plain Writing Act as well as the Presidential Memorandum, “Plain Language in Government Writing,” published in the **Federal Register** on June 10, 1998 (63 FR 31883). The NRC requests comment on this document with respect to the clarity and effectiveness of the language used.

Dated at Rockville, Maryland, this 3rd day of May 2017.

For the Nuclear Regulatory Commission.

**Gregory T. Bowman,**

*Deputy Director, Division of Policy and Rulemaking, Office of Nuclear Reactor Regulation.*

[FR Doc. 2017–09332 Filed 5–4–17; 11:15 am]

**BILLING CODE 7590–01–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2017–0333; Directorate Identifier 2017–NM–005–AD]

RIN 2120–AA64

#### **Airworthiness Directives; Bombardier, Inc. (Type Certificate Previously Held by Canadair Limited) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model CL–215–6B11 (CL–415 Variant) airplanes. This proposed AD was prompted by a report indicating that an oxygen bottle was found loose while the clamp strap was in the locked position. This proposed AD would require modification of the clamp strap and installation of additional shims, as applicable, to the

flight crew's oxygen bottle retaining structures. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by June 23, 2017.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514-855-5000; fax: 514-855-7401; email: [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet: <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0333; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone: 800-647-5527) is in the **ADDRESSES** section. Comments will

be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7318; fax: 516-794-5531.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2017-0333; Directorate Identifier 2017-NM-005-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2016-33, dated October 12, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Bombardier, Inc., Model CL-215-6B11 (CL-415 Variant) airplanes. The MCAI states:

During the implementation of Service Bulletin (SB) 215-4051, the oxygen bottle was found loose while the clamp strap was in the locked position. This was determined to be caused by the quick release latch assembly not achieving the proper clamping pressure.

The release of the oxygen bottle due to improper clamping pressure may result in a loose mass cockpit hazard or an oxygen rich environment leading to a possible fire hazard.

In order to mitigate the unsafe condition, SB 215-4457 was issued to modify the clamp strap and install additional shims to add strength to the attaching structure for all affected aeroplanes.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0333.

#### Related Service Information Under 1 CFR Part 51

We reviewed Bombardier Service Bulletin 215-4457, Revision 3, dated May 8, 2013. The service information describes procedures for installing shims, and, for certain airplanes, modifying the straps of the latch assembly, on the flight crew's oxygen bottles' retaining structure. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Costs of Compliance

We estimate that this proposed AD affects 26 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

#### ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Modification and installation	16 work-hours × \$85 per hour = \$1,360 .....	\$2,250	\$3,610	\$93,860

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII:

Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701:

General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for

safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Bombardier, Inc. (Type Certificate Previously Held by Canadair Limited):**  
Docket No. FAA-2017-0333; Directorate Identifier 2017-NM-005-AD.

#### (a) Comments Due Date

We must receive comments by June 23, 2017.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Bombardier, Inc. (Type Certificate previously held by Canadair Limited) Model CL-215-6B11 (CL-415

Variant) airplanes, certificated in any category, having serial numbers 2001, 2002, 2005 through 2007 inclusive, 2010, 2012 through 2017 inclusive, 2019, 2022 through 2024 inclusive, 2026, 2057, 2063, 2065, 2076, 2077, and 2081.

#### (d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

#### (e) Reason

This AD was prompted by a report indicating that an oxygen bottle was found loose while the clamp strap was in the locked position. We are issuing this AD to prevent an oxygen bottle from being released, which would result in a loose mass object in the cockpit and could also result in an oxygen-rich environment that could lead to a possible fire hazard.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Installation and Modification

Within 12 months after the effective date of this AD, install additional shims and modify the clamp strap, as applicable, to the flight crew's oxygen bottle retaining structures, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 215-4457, Revision 3, dated May 8, 2013.

#### (h) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using any of the service information identified in paragraphs (h)(1), (h)(2), or (h)(3) of this AD.

(1) Bombardier Service Bulletin 215-4457, Revision 2, dated October 24, 2012.

(2) Bombardier Service Bulletin 215-4457, Revision 1, dated June 12, 2012.

(3) Bombardier Service Bulletin 215-4457, dated April 4, 2012.

#### (i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7300; fax: 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must

be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Viking Air Limited's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

#### (j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2016-33, dated October 12, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0333.

(2) For more information about this AD, contact Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7318; fax: 516-794-5531.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514-855-5000; fax: 514-855-7401; email: [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet: <http://www.bombardier.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on May 2, 2017.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2017-09324 Filed 5-8-17; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2017-0334; Directorate Identifier 2017-NM-008-AD]

**RIN 2120-AA64**

### Airworthiness Directives; Bombardier, Inc., Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to supersede Airworthiness Directive (AD) 2014-25-01, for certain Bombardier, Inc., Model DHC-8-400 series airplanes. AD 2014-25-01 currently requires modifying the nose landing gear (NLG) trailing arm and installing a new pivot pin retention mechanism. Since we issued AD 2014-25-01, we have received reports of discrepancies of a certain bolt at the