

(g) Actions for Group 2 Airplanes

For airplanes identified as Group 2 in ASB 737–53A1267, R1: Within 120 days after the effective date of this AD, inspect the airplane and do all applicable corrective actions using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(h) Inspections for Group 1 Airplanes

For airplanes identified as Group 1 in ASB 737–53A1267, R1: Except as specified in paragraph (j)(1) of this AD, at the applicable time specified in paragraph 1.E. “Compliance” of ASB 737–53A1267, R1, do the applicable actions specified in paragraphs (h)(1) and (h)(2) of this AD; and do all applicable corrective actions; in accordance with the Accomplishment Instructions of ASB 737–53A1267, R1, except as specified in paragraph (j)(2) of this AD and as provided by paragraph (i) of this AD. Do all applicable corrective actions before further flight. Repeat the applicable inspections specified in paragraph (h)(1) of this AD thereafter at the applicable intervals specified paragraph 1.E., “Compliance,” of ASB 737–53A1267, R1, except as provided by paragraph (i) of this AD.

(1) Do detailed inspections and high frequency eddy current (HFEC) surface inspections of the skin around the fastener heads for any crack on the forward and aft fastener columns, left and right sides, at STA 259.5 circumferential butt splice, in accordance with Parts 1, 2, 6, 7, 8, and 9 of the Accomplishment Instructions of ASB 737–53A1267, R1, as applicable.

(2) Do a one-time detailed inspection for any defect of the production countersunk rivet heads on both forward and aft fastener columns, left and right sides, at STA 259.5 circumferential butt splice, in accordance with Part 3 of the Accomplishment Instructions of ASB 737–53A1267, R1.

(i) Repairs That Terminate Inspections in Repair Areas

(1) For airplanes identified as Group 1, Configuration 1, in ASB 737–53A1267, R1: Doing the skin trim-out repair specified in Part 5 of the Accomplishment Instructions of ASB 737–53A1267, R1, terminates the initial and repetitive inspections required by paragraph (h) of this AD that are specified in Part 1 of the Accomplishment Instructions of ASB 737–53A1267, R1, only; all other inspections required by paragraph (h) of this AD must be done, except as provided by paragraph (i)(2) of this AD.

(2) For airplanes identified as Group 1, Configuration 1 in ASB 737–53A1267, R1: Doing the skin repair specified in Part 4 of the Accomplishment Instructions of ASB 737–53A1267, R1, terminates the initial and repetitive inspections required by paragraph (h) of this AD that are specified in Part 1 and Part 2 of the Accomplishment Instructions of ASB 737–53A1267, R1, for the repaired area only; all other inspections required by paragraph (h) of this AD must be done, except as provided by paragraph (i)(1) of this AD.

(j) Exceptions to Service Information

(1) Where paragraph 1.E., “Compliance,” of ASB 737–53A1267, R1, specifies a

compliance time “after the Revision 1 date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Although ASB 737–53A1267, R1, specifies to contact Boeing for appropriate action, and specifies that action as “RC” (Required for Compliance), this AD requires repair before further flight using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-LAACO-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2007–26–04 are approved as AMOCs for the corresponding provisions of this AD.

(5) Except as required by paragraph (j)(2) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (k)(5)(i) and (k)(5)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

For more information about this AD, contact Jennifer Tsakoumakis, Aerospace Engineer, Airframe Branch, ANM–120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712–4137;

phone: 562–627–5264; fax: 562–627–5210; email: jennifer.tsakoumakis@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737–53A1267, Revision 1, dated March 8, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 2, 2017.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017–12175 Filed 6–19–17; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2016–9574; Directorate Identifier 2016–NM–063–AD; Amendment 39–18921; AD 2017–12–06]

RIN 2120–AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Airbus Model A300 series airplanes; Model A300 B4–600, B4–600R, and F4–600R series airplanes, and Model A300 C4–605R Variant F airplanes (collectively called Model A300–600 series airplanes); and Model A310 series airplanes. This AD is intended to complete certain mandated programs

intended to support the airplane reaching its limit of validity (LOV) of the engineering data that support the established structural maintenance program. This AD requires inspecting the forward passenger doors to identify the part number, and for affected doors, inspecting to identify existing repairs and doing corrective actions if necessary. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 25, 2017.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of July 25, 2017.

ADDRESSES: For service information identified in this final rule, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: account.airworth-eas@airbus.com; Internet: <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9574.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9574; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-2125; fax: 425-227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR

part 39 by adding an AD that would apply to all Airbus Model A300 series airplanes; Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Model A310 series airplanes. The NPRM published in the *Federal Register* on February 17, 2017 (82 FR 10968) (“the NPRM”). The NPRM was intended to complete certain mandated programs intended to support the airplane reaching its limit of validity (LOV) of the engineering data that support the established structural maintenance program. The NPRM proposed to require inspecting the forward passenger doors to identify the part number, and for affected doors, inspecting to identify existing repairs and doing corrective actions if necessary. We are issuing this AD to detect and correct widespread fatigue damage of the forward passenger doors, which could result in reduced structural integrity of the airplane.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2016-0079, dated April 21, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A300 series airplanes; Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Model A310 series airplanes. The MCAI states:

In the frame of the “Ageing Aeroplane Safety Rule Project”, a review of the A300, A300-600 and A310 Structural Repair Manuals (SRMs) was performed against Fatigue and Damage Tolerance criteria to satisfy the ageing aeroplane regulation.

As a result of this review, some repairs concerning the forward passenger door flanges were identified as no longer applicable and had to be de-activated. Those repairs may however have been accomplished on some aeroplanes passenger door flanges prior to de-activation of the repair.

This condition, if not detected and corrected, could reduce the structural integrity of the aeroplane.

To address this potential unsafe condition, Airbus issued Service Bulletin (SB) A300-52-0180, SB A300-52-6084 and SB A310-52-2076 to provide inspection instructions.

For the reasons described above, this [EASA] AD requires identification of the forward passenger door part number (P/N) and a one-time Detailed Inspection (DET) of the forward passenger door frame segments inner flanges for SRM repair embodied and, depending on the results from the identification and inspection,

accomplishment of corrective action(s) [e.g., repair].

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9574.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comment received on the NPRM and the FAA’s response to that comment.

Support for the NPRM

FedEx agrees that the inspection is necessary and supports the intent of the NPRM.

Request To Change the Reporting Requirement

FedEx stated that it does not have a process in place to report the inspection results specified by paragraph (i) of the proposed AD using the on-line Airbus reporting tool. FedEx asked that it be allowed to use the older method of reporting identified in Airbus Service Bulletins A310-52-2076, Revision 01, dated October 14, 2014; and A300-52-6084, Revision 01, dated October 16, 2014. FedEx added that the new on-line application would be used when a method and adequate personnel are in place to utilize that application.

We agree with the commenter. We recognize that operators may not have a method in place or adequate personnel available to utilize the online Airbus reporting tool. Using the reporting sheet provided in Airbus Service Bulletins A310-52-2076, Revision 01, dated October 14, 2014; and A300-52-6084, Revision 01, dated October 16, 2014; is an acceptable method for reporting. We have revised paragraph (i) of this AD to include this option for reporting.

Conclusion

We reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this AD with the change described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that this change will not increase the economic burden on any operator or increase the scope of this AD.

Related Service Information Under 1 CFR Part 51

Airbus has issued the following service information:

- Airbus Service Bulletin A300–52–0180, Revision 01, dated October 14, 2014.
- Airbus Service Bulletin A310–52–2076, Revision 01, dated October 14, 2014.

- Airbus Service Bulletin A300–52–6084, Revision 01, dated October 16, 2014.

The service information describes procedures for inspecting the forward passenger doors on the left- and right-hand sides to identify the part number, and for affected doors, inspecting to identify existing repairs and doing corrective actions. These documents are distinct since they apply to different airplane models. This service

information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 128 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Part number inspection	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$10,880.
Reporting for forward passenger door having P/N A521-71851-000 or P/N A521-71851-001.	1 work-hour × \$85 per hour = \$85	0	85	Up to \$10,880.

We estimate the following costs to do any necessary corrective actions that will be required based on the results of

the part number inspection. We have no way of determining the number of

airplanes that might need these corrective actions:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Detailed inspection	7 work-hours × \$85 per hour = \$595	\$0	\$595

We have received no definitive data that would enable us to provide cost estimates for other on-condition actions specified in this AD.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this AD is 2120–0056. The paperwork cost associated with this AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES–200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2017-12-06 Airbus: Amendment 39-18921; Docket No. FAA-2016-9574; Directorate Identifier 2016-NM-063-AD.

(a) Effective Date

This AD is effective July 25, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus airplanes identified in paragraphs (c)(1) through (c)(6) of this AD, certificated in any category, all manufacturer serial numbers.

(1) Model A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes.

(2) Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes.

(3) Model A300 B4-605R and B4-622R airplanes.

(4) Model A300 F4-605R and F4-622R airplanes.

(5) Model A300 C4-605R Variant F airplanes.

(6) Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD is intended to complete certain mandated programs intended to support the airplane reaching its limit of validity (LOV) of the engineering data that support the established structural maintenance program. We are issuing this AD to detect and correct widespread fatigue damage of the forward passenger doors, which could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Parts Identification

Within 36 months after the effective date of this AD, or before exceeding the applicable airplane design service goal specified in table 1 to paragraph (g) of this AD, whichever occurs later: Identify the part number on the forward passenger doors on the left-hand and right-hand sides, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraph (g)(1), (g)(2), or (g)(3) of this AD.

(1) Airbus Service Bulletin A300-52-0180, Revision 01, dated October 14, 2014 (for Model A300 airplanes).

(2) Airbus Service Bulletin A300-52-6084, Revision 01, dated October 16, 2014 (for Model A300-600 series airplanes).

(3) Airbus Service Bulletin A310-52-2076, Revision 01, dated October 14, 2014.

TABLE 1 TO PARAGRAPH (g) OF THIS AD—DESIGN SERVICE GOAL

Airplane model/series	Design service goal flight cycles or flight hours
A300 B2-100, B2-200, B2-320	Before the accumulation of 48,000 total flight cycles.
A300 B4-100	Before the accumulation of 40,000 total flight cycles.
A300 B4-200	Before the accumulation of 34,000 total flight cycles.
A300 B4-600, B4-600R, F4-600R, C4-600R	Before the accumulation of 30,000 total flight cycles or 67,500 total flight hours, whichever occurs first.
A310-200	Before the accumulation of 40,000 total flight cycles or 60,000 total flight hours, whichever occurs first.
A310-300	Before the accumulation of 35,000 total flight cycles or 60,000 total flight hours, whichever occurs first.

(h) Corrective Actions

(1) For airplanes on which no forward passenger door having part number (P/N) A521-71851-000 or P/N A521-71851-001 is found to be installed, after identifying the part number as specified in paragraph (g) of this AD: No further action is required for these airplanes.

(2) For airplanes on which any forward passenger door having P/N A521-71851-000 or P/N A521-71851-001 is found to be installed, after identifying the part number as specified in paragraph (g) of this AD: Before further flight, do a detailed inspection of all frame segment inner flanges of the forward passenger doors with the affected part numbers for installed repairs, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraph (g)(1), (g)(2), or (g)(3) of this AD.

(i) For Airbus Model A300 airplanes: Before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-52-0180, Revision 01, dated October 14, 2014. Where Airbus Service Bulletin A300-52-0180, Revision 01, dated October 14, 2014, specifies to contact Airbus for appropriate action, and specifies that action as "RC" (Required for Compliance): Before further flight, accomplish corrective actions in accordance with the procedures specified in paragraph (i)(2) of this AD.

(ii) For Airbus Model A310 and A300-600 series airplanes on which the repair principle A310 Structural Repair Manual (SRM) 52-10-00, page block (PB) 201, Figure 209, or A300-600 SRM 52-10-00, PB 201, Figure 206, as applicable, is not embodied on any inner flange, no further action is required for these airplanes.

(iii) For Airbus Model A310 and A300-600 series airplanes on which the repair principle A310 SRM 52-10-00, PB 201, Figure 209, or A300-600 SRM 52-10-00, PB 201, Figure 206, as applicable, is embodied on at least one inner flange: Before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-52-6084, Revision 01, dated October 16, 2014; or Airbus Service Bulletin A310-52-2076, Revision 01, dated October 14, 2014; as applicable. Where Airbus Service Bulletins A300-52-6084, Revision 01, dated October 16, 2014; and A310-52-2076, Revision 01, dated October 14, 2014; specify to contact Airbus for appropriate action, and specify that action as "RC": Before further flight, accomplish corrective actions in accordance with the procedures specified in paragraph (i)(2) of this AD.

(i) Reporting Requirement

At the applicable time specified in paragraph (i)(1) or (i)(2) of this AD, report the results of the inspection required by paragraph (h)(2) of this AD to Airbus Service

Bulletin Reporting Online Application on Airbus World (<https://w3.airbus.com/>), or submit the results to Airbus using the reporting sheet provided in the service information identified in paragraphs (g)(2) or (g)(3) of this AD, as applicable.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(j) Parts Installation Limitations

As of the effective date of this AD, no person may replace a forward passenger door on any airplane, unless the replacement door has been inspected in accordance with the requirements of this AD.

(k) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using the applicable service information identified in paragraph (k)(1), (k)(2), or (k)(3) of this AD.

(1) Airbus Service Bulletin A300-52-0180, dated September 23, 2014.

(2) Airbus Service Bulletin A300-52-6084, dated September 23, 2014.

(3) Airbus Service Bulletin A310-52-2076, dated September 23, 2014.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Branch, send it to the attention of the person identified in paragraph (m)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(4) *Required for Compliance (RC)*: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA

Airworthiness Directive 2016-0079, dated April 21, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9574.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-2125; fax: 425-227-1149.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A300-52-0180, Revision 01, dated October 14, 2014.

(ii) Airbus Service Bulletin A300-52-6084, Revision 01, dated October 16, 2014.

(iii) Airbus Service Bulletin A310-52-2076, Revision 01, dated October 14, 2014.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: account.airworth-eas@airbus.com; Internet: <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 2, 2017.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-12286 Filed 6-19-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2015-3148; Directorate Identifier 2014-NM-254-AD; Amendment 39-18928; AD 2017-12-13]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Airbus Model A320-212, -214, -232, and -233 airplanes. This AD was prompted by a report of a crack found during an inspection of the pocket radius of the fuselage frame. This AD requires repetitive low frequency eddy current inspections or repetitive high frequency eddy current inspections of this area, and repair if necessary. The repair terminates the repetitive inspections. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective July 25, 2017.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 25, 2017.

ADDRESSES: For service information identified in this final rule, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3148; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory