

APY Earned=5.00%

■ 14. In Supplement I to part 1030, under Section 1030.7—*Payment of Interest*, paragraph 7(c)—*Date interest begins to accrue* is revised to read as follows:

Supplement I to Part 1030—Official Interpretations

* * * * *

Section 1030.7—Payment of Interest

* * * * *

(c) *Date interest begins to accrue.*

1. *Relation to Regulation CC.* Institutions may rely on the Expedited Funds Availability Act (EFAA) and Regulation CC (12 CFR part 229) to determine, for example, when a deposit is considered made for purposes of interest accrual, or when interest need not be paid on funds because a deposited check is later returned unpaid.

2. *Ledger and collected balances.* Institutions may calculate interest by using a “ledger” or “collected” balance method, as long as the crediting requirements of the EFAA are met (12 CFR 229.14).

3. *Withdrawal of principal.* Institutions must accrue interest on funds until the funds are withdrawn from the account. For example, if a check is debited to an account on a Tuesday, the institution must accrue interest on those funds through Monday.

By order of the Board of Governors of the Federal Reserve System, November 19, 2018.

Ann E. Misback,

Secretary of the Board.

Dated: September 20, 2018.

Mick Mulvaney,

Acting Director, Bureau of Consumer Financial Protection.

[FR Doc. 2018–25746 Filed 12–7–18; 8:45 am]

BILLING CODE P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2018–1005; Product Identifier 2018–NM–109–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to supersede Airworthiness Directive (AD) 2016–16–01, which applies to certain Airbus SAS Model A330–200 Freighter, –200, and –300 series airplanes. AD 2016–16–01 requires an inspection of affected structural parts in the cargo and cabin compartments to determine if proper

heat treatment has been done, and replacement or repair if necessary. Since we issued AD 2016–16–01, we have determined that additional affected parts in the cabin compartment structure must also be inspected. This proposed AD would retain the requirements of AD 2016–16–01 and require inspection of additional locations of the cabin compartment structure. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by January 24, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus SAS, Airworthiness Office—EIAS, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–1005; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South

216th St., Des Moines, WA 98198; telephone and fax 206–231–3229.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2018–1005; Product Identifier 2018–NM–109–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We issued AD 2016–16–01, Amendment 39–18599 (81 FR 51325, August 4, 2016) (corrected September 1, 2016 (81 FR 60246)) (“AD 2016–16–01”), for certain Airbus SAS Model A330–200 Freighter, –200, and –300 series airplanes. AD 2016–16–01 requires an inspection of affected structural parts in the cargo and cabin compartments to determine if proper heat treatment has been done, and replacement or repair if necessary. AD 2016–16–01 was prompted by a report of a manufacturing defect that affects the durability of affected parts in the cargo and cabin compartment. We issued AD 2016–16–01 to address crack initiation and propagation in structural parts of the cargo and cabin compartments, which could result in reduced structural integrity of the fuselage.

Actions Since AD 2016–16–01 Was Issued

Since we issued AD 2016–16–01, we have determined that additional affected parts in the cabin compartment structure must also be inspected.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018–0147, dated July 13, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Model A330–200 Freighter, –200, and –300 series airplanes. The MCAI states:

It was determined that several structural parts, intended for cargo or cabin compartment installation, were manufactured from improperly heat-treated materials. A subsequent review identified that some of those parts were installed on aeroplanes manufactured between November 2011 and February 2013. Consequently, Airbus implemented measures into manufacturing processes to ensure detection and to prevent further installation of such non-conforming parts. A detailed safety assessment was accomplished to identify the possible impact of these parts on the aeroplane structure. The result of this structural analysis demonstrated the capability of the affected structure to sustain static limit loads, but failed to confirm that the affected structures meet the certified fatigue life.

This condition, if not detected and corrected, could lead to crack initiation and propagation, possibly resulting in reduced structural integrity of the fuselage.

To address this unsafe condition, Airbus published the applicable SBs [service bulletins] to provide inspection instructions for affected structural cargo and cabin parts, respectively. Consequently, EASA issued AD 2015-0212 [which corresponds to FAA AD 2016-16-01] to require a one-time special detailed inspection (SDI) [eddy current inspection] to measure the electrical conductivity of affected parts, to identify the presence or absence of heat treatment, and, depending on findings, applicable corrective action(s) [replacement or repair].

Since that AD was issued, Airbus identified that some additional affected parts, located in the cabin compartment structure, have been missed and need to be inspected. Consequently, Airbus issued SB A330-53-3228 Revision 01 to introduce the locations

of those missed structural parts to be inspected.

For the reasons described above, this [EASA] AD retains the requirements of EASA AD 2015-0212, which is superseded, and expands the number and locations of structural parts to be inspected.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-1005.

Related Service Information Under 1 CFR Part 51

Airbus has issued Service Bulletin A330-53-3227, Revision 02, dated July 25, 2018, which describes procedures for inspecting affected structural parts in the cargo compartment to determine if proper heat treatment has been done, and replacing discrepant parts.

Airbus has also issued Service Bulletin A330-53-3228, Revision 01, dated April 11, 2018, which describes procedures for inspecting affected structural parts in the cabin compartment to determine if proper heat treatment has been done, doing additional work (inspecting additional locations of the cabin compartment structure), and doing related investigative and corrective actions. Related investigative actions include an eddy current inspection to verify the measurement from the inspection to determine if proper heat treatment has been done. Corrective actions include replacing discrepant parts.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed Requirements of This NPRM

This proposed AD would retain all of the requirements of AD 2016-16-01. This proposed AD would also require accomplishing the additional work specified in Airbus Service Bulletin A330-53-3228, Revision 01, dated April 11, 2018, described previously.

Costs of Compliance

We estimate that this proposed AD affects 20 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Actions	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Retained actions from AD 2016-16-01.	11 work-hours × \$85 per hour = \$935	\$0	\$935	\$18,700
New proposed additional work	5 work-hours × \$85 per hour = \$425	0	425	8,500

We estimate the following costs to do any necessary on-condition action that would be required based on the results

of any required actions. We have no way of determining the number of aircraft

that might need this on-condition action:

ESTIMATED COSTS OF ON-CONDITION ACTION

Labor cost	Parts cost	Cost per product
45 work-hours × \$85 per hour = \$3,825	\$0 *	\$3,825

* We have received no definitive data on the parts cost for the on-condition action.

According to the manufacturer, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a

result, we have included all known costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII,

Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866,
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
3. Will not affect intrastate aviation in Alaska, and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2016–16–01, Amendment 39–18599 (81 FR 51325, August 4, 2016) (corrected September 1, 2016 (81 FR 60246)), and adding the following new AD:

Airbus SAS: Docket No. FAA–2018–1005; Product Identifier 2018–NM–109–AD.

(a) Comments Due Date

We must receive comments by January 24, 2019.

(b) Affected ADs

This AD replaces AD 2016–16–01, Amendment 39–18599 (81 FR 51325, August 4, 2016) (corrected September 1, 2016 (81 FR 60246)) (“AD 2016–16–01”).

(c) Applicability

This AD applies to the Airbus SAS airplanes, certificated in any category, identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, manufacturer serial numbers 1175, 1180, 1287 through 1475 inclusive, 1478, 1480, 1483, and 1506.

(1) Model A330–223F and –243F airplanes.

(2) Model A330–201, –202, –203, –223, and –243 airplanes.

(3) Model A330–301, –302, –303, –321, –322, –323, –341, –342, and –343 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by a report of a manufacturing defect (*i.e.*, improperly heat-treated materials) that affects the durability of affected parts in the cargo and cabin compartments. We are issuing this AD to address crack initiation and propagation in affected parts in the cargo and cabin compartments, which could result in reduced structural integrity of the fuselage.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Inspection of Affected Structure in the Cargo Compartment, With Revised Service Information

This paragraph restates the requirements of paragraph (g) of AD 2016–16–01, with revised service information. Within 72 months since first flight of the airplane, do an eddy current inspection (*i.e.*, conductivity measurement) of affected structural parts in the cargo compartment to determine if proper heat treatment has been done as identified in, and in accordance with, the Accomplishment Instructions of Airbus Service Bulletin A330–53–3227, dated August 18, 2015; or Airbus Service Bulletin A330–53–3227, Revision 02, dated July 25, 2018. As of the effective date of this AD, only Airbus Service Bulletin A330–53–3227, Revision 02, dated July 25, 2018, may be used.

(h) Retained Replacement of Non-Conforming Parts in the Cargo Compartment, With Revised Service Information

This paragraph restates the requirements of paragraph (h) of AD 2016–16–01, with revised service information. If, during the inspection required by paragraph (g) of this AD, an affected structural part in the cargo compartment is identified to have a measured value greater than 26 megasiemens per meter (MS/m), or greater than 44.8% International Annealed Copper Standard (IACS), before further flight, replace the affected structural part with a serviceable part, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330–53–3227, dated August 18, 2015; or Airbus Service Bulletin A330–53–3227, Revision 02, dated July 25, 2018. As of the effective date of this AD, only Airbus Service Bulletin A330–53–3227, Revision 02, dated July 25, 2018, may be used.

(i) Retained Repair of Non-Conforming Parts in the Cargo Compartment, With Revised Service Information

This paragraph restates the requirements of paragraph (i) of AD 2016–16–01, with revised service information. If, during the inspection required by paragraph (g) of this AD, an affected structural part in the cargo compartment is identified to have a measured value other than those specified in Figure A–GFAAA, Sheet 01, “Inspection Flowchart,” of Airbus Service Bulletin A330–53–3227, dated August 18, 2015; or Airbus Service Bulletin A330–53–3227, Revision 02, dated July 25, 2018; before further flight, repair using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature. As of the effective date of this AD, only Airbus Service Bulletin A330–53–3227, Revision 02, dated July 25, 2018, may be used to identify the measured value.

(j) Retained Inspection of Affected Structure in the Cabin Compartment, With Revised Service Information

This paragraph restates the requirements of paragraph (j) of AD 2016–16–01, with revised service information. Within 72 months since first flight of the airplane, do an eddy current inspection of affected structural parts in the cabin compartment to determine if proper heat treatment has been done as identified in, and in accordance with, the Accomplishment Instructions of Airbus Service Bulletin A330–53–3228, dated August 18, 2015; or Airbus Service Bulletin A330–53–3228, Revision 01, dated April 11, 2018. As of the effective date of this AD, only Airbus Service Bulletin A330–53–3228, Revision 01, dated April 11, 2018, may be used.

(k) Retained Replacement of Non-Conforming Parts in the Cabin Compartment, With Revised Service Information

This paragraph restates the requirements of paragraph (k) of AD 2016–16–01, with

revised service information. If, during the inspection required by paragraph (j) of this AD, an affected structural part in the cabin compartment is identified to have a measured value greater than 26 MS/m or greater than 44.8% IACS, before further flight, replace the affected structural part with a serviceable part, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330–53–3228, dated August 18, 2015; or Airbus Service Bulletin A330–53–3228, Revision 01, dated April 11, 2018. As of the effective date of this AD, only Airbus Service Bulletin A330–53–3228, Revision 01, dated April 11, 2018, may be used.

(l) Retained Repair of Non-Conforming Parts in the Cabin Compartment, With Revised Service Information and New Alternative Actions

This paragraph restates the requirements of paragraph (l) of AD 2016–16–01, with revised service information and new alternative actions. If, during the inspection required by paragraph (j) of this AD, an affected structural part in the cabin compartment is identified to have a measured value other than those specified in Figure A–GFAAA, Sheet 01, “Inspection Flowchart,” of Airbus Service Bulletin A330–53–3228, dated August 18, 2015; or to have to a measured value between 22 MS/m and 26 MS/m or between 37.9 and 44.8% IACS, as specified in Airbus Service Bulletin A330–53–3228, Revision 01, dated April 11, 2018, before further flight, do the actions specified in paragraph (l)(1) or (l)(2) of this AD. As of the effective date of this AD, only Airbus Service Bulletin A330–53–3228, Revision 01, dated April 11, 2018, may be used to identify the measured value.

(1) Repair using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the EASA; or Airbus SAS’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(2) Do an eddy current inspection to verify the measurement, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330–53–3228, Revision 01, dated April 11, 2018.

(i) If an affected structural part in the cabin compartment is identified to have a measured value between 22 MS/m and 26 MS/m or between 37.9 and 44.8% IACS, before further flight, repair using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the EASA; or Airbus SAS’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(ii) If an affected structural part in the cabin compartment is identified to have a measured value greater than 26 MS/m or greater than 44.8% IACS, before further flight, do the replacement specified in paragraph (k) of this AD.

(m) New Requirement of This AD: Inspection of Additional Cabin Locations

For an airplane on which the cabin compartment structure was inspected and corrective actions were done before the effective date of this AD as specified in the

Accomplishment Instructions of Airbus Service Bulletin A330–53–3228, dated August 18, 2015: Before exceeding 108 months since the airplane’s first flight, do an eddy current conductivity test of the forward cabin overhead compartment, and do all applicable related investigative and corrective actions, in accordance with the applicable “additional work” task in the Accomplishment Instructions of Airbus Service Bulletin A330–53–3228, Revision 01, dated April 11, 2018. Do all applicable related investigative and corrective actions before further flight. Where Airbus Service Bulletin A330–53–3228, Revision 01, dated April 11, 2018, specifies to contact Airbus for appropriate action: Before further flight, accomplish corrective actions in accordance with the procedures specified in paragraph (p)(2) of this AD.

(n) No Reporting

Although Airbus Service Bulletin A330–53–3227, Revision 02, dated July 25, 2018, and Airbus Service Bulletin A330–53–3228, Revision 01, dated April 11, 2018, specify to submit certain information to the manufacturer, and specify that action as “RC” (required for compliance), this AD does not include that requirement.

(o) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraphs (g), (h), and (i) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A330–53–3227, Revision 01, dated July 5, 2016.

(p) Other FAA AD Provisions

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (q)(2) of this AD. Information may be emailed to 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(ii) AMOC letters ANM–116–17–118, dated February 2, 2017, and AIR–676–18–369, dated September 17, 2018, approved previously for AD 2016–16–01, are approved as AMOCs for the corresponding provisions of this AD.

(2) *Contacting the Manufacturer*: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraphs (i), (l), (m), and (o) of this AD: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(q) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2018–0147, dated July 13, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–1005.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3229.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EIAS, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on November 23, 2018.

John P. Piccola,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018–26462 Filed 12–7–18; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2018–0987; Airspace Docket No. 18–ASO–19]

RIN 2120–AA66

Proposed Amendment of Class E Airspace; Auburn, AL

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E airspace extending