

control if necessary to prevent inappropriate use or confusion.

(g) Under any condition of flight appropriate to its use, the flight guidance system may not produce hazardous loads on the airplane, nor create hazardous deviations in the flight path. This applies to both fault-free operation and in the event of a malfunction, and assumes that the pilot begins corrective action within a reasonable period of time.

(h) When the flight guidance system is in use, a means must be provided to avoid excursions beyond an acceptable margin from the speed range of the normal flight envelope. If the airplane experiences an excursion outside this range, a means must be provided to prevent the flight guidance system from providing guidance or control to an unsafe speed.

(i) The flight guidance system functions, controls, indications, and alerts must be designed to minimize flightcrew errors and confusion concerning the behavior and operation of the flight guidance system. Means must be provided to indicate the current mode of operation, including any armed modes, transitions, and reversions. Selector switch position is not an acceptable means of indication. The controls and indications must be grouped and presented in a logical and consistent manner. The indications must be visible to each pilot under all expected lighting conditions.

(j) Following disengagement of the autothrust function, a caution must be provided to each pilot.

(k) During autothrust operation, it must be possible for the flightcrew to move the thrust levers without requiring excessive force. The autothrust may not create a potential hazard when the flightcrew applies an override force to the thrust levers.

(l) For purposes of these special conditions, a transient is a disturbance in the control or flight path of the airplane that is not consistent with response to flightcrew inputs or environmental conditions.

(1) A minor transient would not significantly reduce safety margins and would involve flightcrew actions that are well within their capabilities. A minor transient may involve a slight increase in flightcrew workload or some physical discomfort to passengers or cabin crew.

(2) A significant transient may lead to a significant reduction in safety margins, an increase in flightcrew workload, discomfort to the flightcrew, or physical distress to the passengers or cabin crew, possibly including non-fatal injuries. Significant transients do not

require, in order to remain within or recover to the normal flight envelope, any of the following:

(i) Exceptional piloting skill, alertness, or strength.

(ii) Forces applied by the pilot which are greater than those specified in § 23.143(c).

(iii) Accelerations or attitudes in the airplane that might result in further hazard to secured or non-secured occupants.

Issued in Kansas City, Missouri, on August 1, 2019.

**Pat Mullen,**

*Manager, Small Airplane Standards Branch, Policy and Innovation Division, Aircraft Certification Service.*

[FR Doc. 2019-17570 Filed 8-14-19; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2019-0117; Product Identifier 2018-NM-169-AD; Amendment 39-19696; AD 2019-15-03]**

**RIN 2120-AA64**

#### **Airworthiness Directives; 328 Support Services GmbH (Type Certificate Previously Held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all 328 Support Services GmbH Model 328-100 airplanes. This AD was prompted by a report indicating that undetected cracks may develop at the roll spoiler bearing arms. This AD requires a one-time non-destructive test (NDT) inspection for cracks in the roll spoiler bearing arms and, if necessary, corrective actions. The agency is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective September 19, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of September 19, 2019.

**ADDRESSES:** For service information identified in this final rule, contact 328 Support Services GmbH, Global Support Center, P.O. Box 1252, D-82231 Wessling, Federal Republic of Germany; telephone +49 8153 88111 6666; fax +49 8153 88111 6565; email [gsc.op@328support.de](mailto:gsc.op@328support.de)

; internet <http://www.328support.de>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0117.

#### **Examining the AD Docket**

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0117; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### **FOR FURTHER INFORMATION CONTACT:**

Todd Thompson, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3228.

#### **SUPPLEMENTARY INFORMATION:**

##### **Discussion**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all 328 Support Services GmbH Model 328-100 airplanes. The NPRM published in the **Federal Register** on March 8, 2019 (84 FR 8482). The NPRM was prompted by a report indicating that undetected cracks may develop at the roll spoiler bearing arms. The NPRM proposed to require a one-time NDT inspection for cracks in the roll spoiler bearing arms and, if necessary, corrective actions.

The FAA is issuing this AD to address cracks at the roll spoiler bearing arms, which, if not detected and corrected, could lead to a roll spoiler becoming unresponsive to flight crew control inputs, possibly resulting in loss of control of the airplane.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2018-0254R1, dated June 4, 2019 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all 328 Support

Services GmbH Model 328–100 airplanes. The MCAI states:

Dornier 328 Maintenance Review Board Report provides instructions for a detailed inspection for the roll spoilers, including the bearing arms, by eddy current [EC] method. It was reported that whilst performing Maintenance Planning Document Task 57–71–03–02–01, referring to Non-Destructive Test (NDT) Manual task 57–71–03–318–000–AA0, the stacking of 6 parts at the bearing arm No. 3 prevents detection of cracks with the given EC test settings. The NDT results are distorted by geometric features such as part edges and fastener installations. Furthermore, the access to certain areas is limited for the suggested NDT probe for geometrical reasons. The result of the technical investigation identified that undetected cracks may develop at the roll spoiler bearing arms, leading to a broken (disconnected) bearing arm No. 3, where the actuator is connected.

This condition, if not detected and corrected, could lead to a roll spoiler becoming unresponsive to flight crew control inputs, possibly resulting in loss of control of the aeroplane.

To address this potential unsafe condition, 328 SSG published the ASB [328 Support Services Alert Service Bulletin ASB–328–57–043, dated September 21, 2018] to provide appropriate inspection instructions.

For the reasons described above, EASA issued AD 2018–0254 to require a one-time NDT inspection of the affected parts and, depending on findings, accomplishment of applicable corrective action(s).

Since that [EASA] AD was issued, it was noted that an error had been made in the compliance times, creating an inconsistency with those in the ASB. This [EASA] AD is revised to correct those errors.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0117.

**Comments**

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA’s response to each comment.

**Requests To Correct Compliance Time**

The commenters, David Davidson and David Moreno, each requested that the compliance time for accomplishing the NDT inspection specified in paragraph (h) of the proposed AD be revised to require the inspection within 2,500 flight hours (FH) after the effective date of the proposed AD instead of within 2,500 flight cycles (FC) after the effective date of the proposed AD. The commenters noted that a compliance time counted in FC conflicts with the compliance time specified in 328 Support Services Alert Service Bulletin ASB–328–57–043, dated September 21, 2018. The commenters went on to point out that using a compliance time counted in FH aligns with the regularly scheduled A5 maintenance check.

The FAA agrees with the commenters’ requests to revise the specified compliance time from FC to FH. Since the agency issued the NPRM, EASA issued 2018–0254R1, dated June 4, 2019, to correct the identified error in the specified compliance time. The FAA has discussed this change with EASA and determined that using a FH compliance time will not adversely affect safety, and will allow the modification to be performed during regularly scheduled maintenance. Further, EASA and 328 Support Services GmbH provided data that confirms that the difference between FH and FC for determining compliance time is small, and the burden to the operator is minimal as a result of this change.

Therefore, where figure 1 to paragraph (h) of the proposed AD used the phrase “within 2,500 FC after the effective date of this AD,” the FAA has revised figure 1 to paragraph (h) of this final AD to state “within 2,500 FH after the effective date of this AD.”

**Conclusion**

The FAA reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule with the change described previously and minor editorial changes. The agency has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

The FAA has also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

**Related Service Information Under 1 CFR Part 51**

328 Support Services has issued Alert Service Bulletin ASB–328–57–043, dated September 21, 2018. This service information describes procedures for a one-time NDT inspection for cracks in the roll spoiler bearing arms. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**Costs of Compliance**

The FAA estimates that this AD affects 27 airplanes of U.S. registry. The agency estimates the following costs to comply with this AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
8 work-hours × \$85 per hour = \$680 .....	\$0	\$680	\$18,360

The FAA has received no definitive data that would enable the agency to provide cost estimates for the on-condition actions specified in this AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more

detail the scope of the agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of

that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has

delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

#### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2019–15–03 328 Support Services GmbH (Type Certificate Previously Held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH):** Amendment 39–19696; Docket No. FAA–2019–0117; Product Identifier 2018–NM–169–AD.

##### (a) Effective Date

This AD is effective September 19, 2019.

##### (b) Affected ADs

None.

##### (c) Applicability

This AD applies to 328 Support Services GmbH (Type Certificate previously held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Model 328–100 airplanes, certificated in any category, all serial numbers.

##### (d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

##### (e) Reason

This AD was prompted by a report indicating that undetected cracks may develop at the roll spoiler bearing arms. The FAA is issuing this AD to address cracking at the roll spoiler bearing arms, which, if not detected and corrected, could lead to a roll spoiler becoming unresponsive to flight crew control inputs, possibly resulting in loss of control of the airplane.

##### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

##### (g) Definition of Affected Parts

For the purposes of this AD, an affected part is the bearing arm of roll spoilers having part number (P/N) 001B577A1200000, 001B577A1200001, 001B577A1200002, 001B577A1200003, 001B577A1200004, or 001B577A1200005.

##### (h) Inspection

Within the compliance time specified in Figure 1 to paragraph (h) of this AD, as applicable, do a non-destructive test (NDT) inspection of each affected part, in accordance with the Accomplishment Instructions of 328 Support Services Alert Service Bulletin ASB–328–57–043, dated September 21, 2018. The flight cycles (FC) specified in Figure 1 to paragraph (h) of this AD are the FC accumulated on the airplane since first flight of the airplane, unless otherwise specified.

**Figure 1 to paragraph (h) – Affected Parts Inspection**

Total FC Accumulated	Compliance Time
More than 25,000 FC	Within 2,500 flight hours (FH) after the effective date of this AD
25,000 FC or less	Before exceeding 25,000 total FC, or within 2,500 FH after the effective date of this AD, whichever occurs later

##### (i) Corrective Action

If any crack is found during any inspection required by paragraph (h) of this AD: Before further flight, obtain corrective actions approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or 328 Support Services GmbH's EASA Design Organization Approval (DOA); and accomplish the corrective actions within the compliance time specified therein. If approved by the DOA, the approval must include the DOA-authorized signature.

##### (j) No Reporting Requirement

Although 328 Support Services Alert Service Bulletin ASB–328–57–043, dated

September 21, 2018, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

##### (k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in

paragraph (l)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or 328 Support Services GmbH's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

**(l) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018–0254R1, dated June 4, 2019, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0117.

(2) For more information about this AD, contact Todd Thompson, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3228.

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) 328 Support Services Alert Service Bulletin ASB–328–57–043, dated September 21, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact 328 Support Services GmbH, Global Support Center, P.O. Box 1252, D–82231 Wessling, Federal Republic of Germany; telephone +49 8153 88111 6666; fax +49 8153 88111 6565; email [gsc.op@328support.de](mailto:gsc.op@328support.de); internet <http://www.328support.de>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 26, 2019.

**Michael Kaszycki,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019–17504 Filed 8–14–19; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA–2019–0575; Product Identifier 2019–NM–113–AD; Amendment 39–19690; AD 2019–14–12]**

**RIN 2120–AA64**

**Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is adopting an airworthiness directive (AD) for certain The Boeing Company Model 737–8 and 737–9 airplanes. This AD requires a maintenance records check to determine if any main slat track assembly has been removed, an inspection of the main slat track assemblies for a suspect lot number or a lot number that cannot be determined, and applicable on-condition actions. This AD was prompted by a report that certain main slat track assemblies were manufactured incorrectly and are affected by hydrogen embrittlement. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective August 30, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 30, 2019.

The FAA must receive comments on this AD by September 30, 2019.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA.

For information on the availability of this material at the FAA, call 206–231–3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0575.

**Examining the AD Docket**

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0575; or in person at the Docket

Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Greg Rutar, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3529; email: [Greg.Rutar@faa.gov](mailto:Greg.Rutar@faa.gov).

**SUPPLEMENTARY INFORMATION:****Discussion**

The FAA has received a report from Boeing indicating that 148 main slat track assemblies from a set of lot numbers were manufactured incorrectly and are affected by hydrogen embrittlement. Main slat track assemblies that are affected by hydrogen embrittlement have reduced strength. After reviewing information within the report provided from Boeing, the FAA determined on May 22, 2019, that this condition, if not addressed, could result in failure of main slat track assemblies, which could cause the slat to depart and potentially strike the airplane, resulting in injury to airplane occupants and/or preventing continued safe flight and landing.

**Other Relevant Rulemaking**

The FAA issued AD 2019–11–03, Amendment 39–19649 (84 FR 26743, June 10, 2019) (“AD 2019–11–03”), for certain The Boeing Company Model 737–700C, –800, and –900ER series airplanes. The FAA issued AD 2019–11–03 to address main slat track assemblies that have reduced strength due to hydrogen embrittlement. This condition, if not addressed, could result in failure of main slat track assemblies, which could cause the slat to depart and potentially strike the airplane, resulting in injury to airplane occupants and/or preventing continued safe flight and landing.

In the preamble of the final rule issuing AD 2019–11–03, the FAA stated that the identified unsafe condition also exists on Boeing Model 737–8 and 737–9 airplanes. The FAA also stated that Boeing was developing service information that would address the unsafe condition for these airplanes and that the FAA might consider additional rulemaking once that service information was developed, approved, and available. Boeing has since developed such service information and the FAA has determined that further rulemaking is indeed necessary.