may file a petition requesting the Director's review of an NRC staff determination on an amendment application. A petition requesting the Director's review may not exceed 30 pages and must be filed within 30 days after the date of the NRC staff's determination. Any person described in this paragraph may file a written response to a petition requesting the Director's review. This response may not exceed 30 pages and must be filed within 15 days after the filing date of the petition requesting the Director's review. The Director may adopt, modify, or set aside the findings, conclusions, conditions, or terms in the NRC staff's amendment determination by providing a written basis for the action. If the Director does not issue a decision or take other appropriate action within 60 days after receiving the petition for review, the NRC staff's determination on the amendment application remains in effect.

(e) Request for review of a Director's decision. The Corporation, or any person whose interest may be affected and who filed a petition for review or filed a response to a petition for review under § 76.45(d), may file a petition requesting the Commission's review of a Director's decision on an amendment application.

(1) A petition requesting the Commission's review may not exceed 30 pages and must be filed within 30 days after the date of the Director's decision. A petition requesting the Commission's

review may be either:

(i) Delivered to the Rulemakings and Adjudications Staff of the Office of the Secretary at One White Flint North, 11555 Rockville Pike, Rockville, MD

(ii) Sent by mail or telegram to the Secretary, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, Attention: Rulemakings and Adjudications Staff.

- (2) Any person described in paragraph (e) of this section may file a written response to a petition requesting the Commission's review. This response may not exceed 30 pages and must be filed within 15 days after the filing date of the petition requesting the Commission's review.
- (3) The Commission may adopt, by order, further procedures that, in its judgment, would serve the purpose of review of the Director's decision. The Commission may adopt, modify, or set aside the findings, conclusions, conditions, or terms in the Director's amendment review decision and will state the basis of its action in writing. If the Commission does not issue a decision or take other appropriate action

within 90 days after receiving the petition for review, the Director's decision, under § 76.45(d), on the amendment application remains in effect.

11. In § 76.60, paragraphs (c)(2), (d)(2), (e)(1), and (e)(2) are revised to read as follows:

## §76.60 Regulatory requirements which apply.

(c) \* \* \*

- (2) The Corporation shall post NRC Form 3 during the term of the certificate and for 30 days following certificate termination.
  - (d) \*
- (2) The Corporation shall comply with the requirements in this part or as specified in an approved plan for achieving compliance.
  - (e) \* \*
- (1) The Corporation shall comply with the requirements in §§ 21.6 and 21.21.
- (2) Under § 21.31, procurement documents issued by the Corporation must specify that the provisions of 10 CFR Part 21 apply.

12. In § 76.62, paragraph (c) is revised to read as follows:

#### §76.62 Issuance of certificate and/or approval of compliance plan.

\* \* \*

(c) The Corporation, or any person whose interest may be affected, may file a petition, not to exceed 30 pages, requesting review of the Director's decision. This petition must be filed with the Commission not later than 30 days after publication of the Federal **Register** notice. Any person described in this paragraph may file a response to any petition for review, not to exceed 30 pages, within 15 days after the filing of the petition. If the Commission does not issue a decision or take other appropriate action within 90 days after the publication of the **Federal Register** notice, the Director's decision remains in effect. The Commission may adopt, by order, further procedures that, in its judgment, would serve the purpose of review of the Director's decision.

13. In § 76.64, paragraph (d) is revised to read as follows:

#### § 76.64 Denial of certificate or compliance plan.

(d) The Corporation, or any person whose interest may be affected, may file a petition for review, not to exceed 30 pages, requesting review of the Director's decision. This petition for review must be filed with the

Commission not later than 30 days after publication of the Federal Register notice. Any person described in this paragraph may file a response to any petition for review, not to exceed 30 pages, within 15 days after the filing of the petition for review. If the Commission does not issue a decision or take other appropriate action within 90 days after the publication of the Federal **Register** notice, the Director's decision remains in effect. The Commission may adopt, by order, further procedures that, in its judgment, would serve the purpose of review of the Director's decision.

14. In § 76.91, the introductory paragraph and paragraph (n) are revised to read as follows:

## §76.91 Emergency planning.

The Corporation shall establish, maintain, and be prepared to follow a written emergency plan. The emergency plan submitted under § 76.35(f) must include the following information:

(n) Comment from offsite response organizations. The Corporation shall allow the offsite response organizations that are expected to respond in case of an accident 60 days to comment on the emergency plan before submitting it to NRC. The Corporation shall provide any comments received within the 60 days to the NRC with the emergency plan.

Dated at Rockville, Maryland, this 11th day of August, 1999.

For the Nuclear Regulatory Commission.

#### Annette L. Vietti-Cook,

Secretary of the Commission. [FR Doc. 99-21306 Filed 8-16-99; 8:45 am] BILLING CODE 7590-01-P

## **DEPARTMENT OF TRANSPORTATION**

## **Federal Aviation Administration**

#### 14 CFR Part 39

[Docket No. 99-NM-204-AD; Amendment 39-11254; AD 99-17-051

## RIN 2120-AA64

## Airworthiness Directives; Israel Aircraft Industries, Ltd., Model Astra **SPX Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that is applicable to certain Israel Aircraft Industries Model Astra SPX series airplanes. This action requires repetitive inspections to detect cracking of the main fuel tube assemblies of the left and right engines, and corrective action, if necessary. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified in this AD are intended to detect and correct fuel line fractures, which could result in in-flight engine shutdowns or an increased risk of engine nacelle fires.

DATES: Effective September 1, 1999.
The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 1, 1999.

Comments for inclusion in the Rules Docket must be received on or before September 16, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-204-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

The service information referenced in this AD may be obtained from Galaxy Aerospace Corporation, One Galaxy Way, Fort Worth Alliance Airport, Fort Worth, Texas 76177. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

## FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: The Civil Aviation Administration of Israel (CAAI), which is the airworthiness authority for Israel, recently notified the FAA that an unsafe condition may exist on certain Israel Aircraft Industries Model Astra SPX series airplanes. The CAAI advises that cracking of the main fuel tube assembly on the left engine was found at the base of the "T" joint weld (fuel pressure switch boss), which resulted in fuel leakage on one occasion. Such cracking may be caused by excessive vibration of the tube-mounted fuel pressure switch. This condition, if not corrected, could result in fuel line fractures and consequent in-flight engine shutdowns or an increased risk of engine nacelle fires.

## **Explanation of Relevant Service Information**

Israel Aircraft Industries has issued Astra Alert Service Bulletin 1125–73A–191, dated April 2, 1999, which describes procedures for a repetitive fluorescent penetrant inspection to detect cracking of the main fuel tube assemblies of the left and right engines, and corrective action, if necessary. The CAAI classified this alert service bulletin as mandatory and issued Israeli airworthiness directive 73–99–07–05, dated July 11, 1999, in order to assure the continued airworthiness of these airplanes in Israel.

#### **FAA's Conclusions**

This airplane model is manufactured in Israel and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAAI has kept the FAA informed of the situation described above. The FAA has examined the findings of the CAAI, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

#### **Explanation of Requirements of Rule**

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, this AD is being issued to detect cracking of the main fuel tube assemblies of the left and right engines, which could result in fuel line fractures and consequent inflight engine shutdowns or an increased risk of engine nacelle fires. This AD requires accomplishment of the actions specified in the alert service bulletin described previously.

#### **Interim Action**

This is considered to be interim action until final action is identified, at which time the FAA may consider further rulemaking.

#### **Determination of Rule's Effective Date**

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

#### **Comments Invited**

Although this action is in the form of a final rule that involves requirements

affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption ADDRESSES. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99–NM–204–AD." The postcard will be date stamped and returned to the commenter.

## **Regulatory Impact**

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency

regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### **Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

99–17–05 Israel Aircraft Industries, Ltd.: Amendment 39–11254. Docket 99–NM– 204–AD.

Applicability: Model Astra SPX series airplanes, serial numbers 089 through 115 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct cracking of the main fuel tube assemblies of the left and right engines, which could result in fuel line fractures and consequent in-flight engine shutdowns or an increased risk of engine nacelle fires, accomplish the following:

## **Repetitive Inspections and Corrective Action**

(a) Within 5 hours time-in-service after the effective date of this AD: Perform a fluorescent penetrant inspection to detect cracking of the main fuel tube assemblies of the left and right engines around the bases of the "T" joint welds of the pressure

transmitter tubes, in accordance with Astra Alert Service Bulletin 1125–73A–191, dated April 2, 1999. Repeat the inspection thereafter at intervals not to exceed 25 hours time-in-service. If any crack is detected during any inspection required by this paragraph, prior to further flight, replace the fuel tube assembly with a new or serviceable part, in accordance with the alert service bulletin.

#### **Alternative Methods of Compliance**

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

#### **Special Flight Permits**

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

## **Incorporation by Reference**

(d) The actions shall be done in accordance with Astra Alert Service Bulletin 1125–73A–191, dated April 2, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from from Galaxy Aerospace Corporation, One Galaxy Way, Fort Worth Alliance Airport, Fort Worth, Texas 76177. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 3:** The subject of this AD is addressed in Israeli airworthiness directive 73–99–07–05, dated July 11, 1999.

(e) This amendment becomes effective on September 1, 1999.

Issued in Renton, Washington, on August 6, 1999.

#### D. L. Riggin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 99–20878 Filed 8–16–99; 8:45 am] BILLING CODE 4910–13–U

#### **DEPARTMENT OF ENERGY**

Federal Energy Regulatory Commission

18 CFR Part 381

[Docket No. RM99-11-000]

## Annual Update of Filing Fees

August 11, 1999.

AGENCY: Federal Energy Regulatory

Commission.

**ACTION:** Final rule; annual update of Commission filing fees.

SUMMARY: In accordance with § 381.104 of the Commission's regulations, the Commission issues this update of its filing fees. This notice provides the yearly update using data in the Commission's Payroll Utilization Reporting System to calculate the new fees. The purpose of updating is to adjust the fees on the basis of the Commission's costs for Fiscal Year 1998.

**EFFECTIVE DATE:** September 16, 1999.

FOR FURTHER INFORMATION CONTACT: Troy Cole, Office of Finance, Accounting and Operations, Federal Energy Regulatory Commission, 888 First Street, NE, Room 42–80, Washington, DC 20426, 202–219–2970.

SUPPLEMENTARY INFORMATION: In addition to publishing the full text of this document in the **Federal Register**, the Commission also provides all interested persons an opportunity to inspect or copy the contents of this document during normal business hours in the Public Reference Room at 888 First Street, NE, Room 2A, Washington, DC 20426.

The Commission Issuance Posting System (CIPS) provides access to the texts of formal documents issued by the Commission. CIPS can be accessed via Internet through FERC's Home Page (http://www.ferc.fed.us) using the CIPS link or the Energy Information Online icon. The full text of this document will be available on CIPS in ASCII, WordPerfect 6.1 and WordPerfect 8.0 format. User assistance is available at 202–208–2222 or by E-mail to CipsMaster@ferc.fed.us.

This document is also available through the Commission's Records and Information Management System (RIMS), an electronic storage and retrieval system of documents submitted to and issued by the Commission after November 16, 1981. Documents from November 1995 to the present can be viewed and printed. RIMS is available in the Public Reference Room or remotely via Internet through FERC's