

Action	Compliance time	Procedures
(1) Accomplish the CVR system modifications specified in Raytheon Recommended Service Bulletin SB 23-3094, Issued: November, 1999.	Within 12 months after the effective date of this AD.	Do the modifications in accordance with procedures in the ACCOMPLISHMENT INSTRUCTIONS section of Raytheon Recommended Service bulletin SB 23-3094, Issued: November, 1999.
(2) Do not install a CVR on any of the affected airplanes without incorporating the modifications required by paragraph (d)(1) of this AD.	As of the effective date of this AD.	Not Applicable.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

- (1) Your alternative method of compliance provides an equivalent level of safety; and
- (2) The Manager, Wichita Aircraft Certification Office (ACO), approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* You may contact Harvey Nero, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4137; facsimile: (316) 946-4407.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Raytheon Recommended Service Bulletin SB 23-3094, Issued: November, 1999. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from the Raytheon Aircraft Corporation, P.O. Box 85, Wichita, Kansas 67201-0085. You can look at copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(i) *When does this amendment become effective?* This amendment becomes effective on November 22, 2000.

Issued in Kansas City, Missouri, on September 26, 2000.

Michael K. Dahl,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-25148 Filed 10-5-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-329-AD; Amendment 39-11915; AD 2000-20-04]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model MD-90-30 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document supersedes an existing airworthiness directive (AD) that applies to certain McDonnell Douglas Model MD-90-30 series airplanes. That AD currently requires replacement of certain ground block screws with new screws; and retermination of the circuit ground wires of the electrical power control unit (EPCU) to separate grounding points. The actions specified in that AD are intended to prevent a loose electrical ground block of the circuit ground wires of the EPCU, which could result in complete loss of the primary electrical power of an airplane during flight. This amendment is prompted by the Federal Aviation Administration's determination that the existing AD must be revised to ensure that the requirements apply to the appropriate airplane groups.

DATES: Effective November 13, 2000.

The incorporation by reference of McDonnell Douglas Service Bulletin MD90-24-062, dated February 3, 2000, as listed in the regulations, is approved by the Director of the Federal Register as of November 13, 2000.

The incorporation by reference of McDonnell Douglas Alert Service

Bulletin MD90-24A060, Revision 01, dated September 2, 1999, as listed in the regulations, was approved previously by the Director of the Federal Register as of September 19, 2000 (65 FR 49728, August 15, 2000).

FOR FURTHER INFORMATION CONTACT:

George Mabuni, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5341; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: On August 3, 2000, the Federal Aviation Administration (FAA) issued AD 2000-16-01, amendment 39-11855 (65 FR 49728, August 15, 2000), which applies to certain McDonnell Douglas Model MD-90-30 series airplanes. That AD requires replacement of certain ground block screws with new screws; and retermination of the circuit ground wires of the electrical power control unit (EPCU) to separate grounding points. That AD was prompted by reports of complete loss of the primary electrical power on an airplane during flight. The actions required by that AD are intended to prevent a loose electrical ground block of the circuit ground wires of the EPCU, which could result in complete loss of the primary electrical power of an airplane during flight.

Need for the Correction

In the preamble of AD 2000-16-01, the FAA indicated that a supplemental notice of proposed rulemaking (NPRM) was published in the **Federal Register** on June 12, 2000 (65 FR 36799). After careful review of the available data, including the comments received from the public, the FAA determined that air safety and the public interest required the adoption of the rule as proposed in the supplemental NPRM. However, the FAA inadvertently included the requirements from the original NPRM (64 FR 68302, December 7, 1999) in the final rule, rather than the requirements specified in paragraphs (a) and (b) of the supplemental NPRM. The effect of this error is that operators of certain airplanes are not required to accomplish actions that apply to those airplanes,

and that certain actions are to be accomplished in accordance with a method approved by the FAA, rather than a specific service bulletin. Therefore, consistent with the FAA's intent in the supplemental NPRM, this correction is necessary to require operators of specific airplanes to replace certain ground block screws with new screws and to reterminate the circuit ground wires of the EPCU to separate grounding points.

These actions shall be done in accordance with McDonnell Douglas Alert Service Bulletin MD90-24A060, Revision 01, dated September 2, 1999; and McDonnell Douglas Service Bulletin MD90-24-062, dated February 3, 2000; as applicable. The FAA inadvertently omitted McDonnell Douglas Service Bulletin MD90-24-062 from the incorporation by reference paragraph and is incorporating by reference that service bulletin in this final rule.

Correction of Publication

Action is taken herein to correct these inadvertent errors in AD 2000-16-01 and to correctly add this AD as an amendment to section 39.13 of the Federal Aviation Regulations (14 CFR 39.13). The AD is reprinted in its entirety for the convenience of affected operators.

Since this action only corrects current requirements, it has no adverse economic impact and imposes no additional burden on any person. Therefore, the FAA has determined that notice and public procedures are unnecessary.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Correction

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-11855 (65 FR 49728, August 15, 2000), and by adding a new airworthiness directive (AD), amendment 39-, to read as follows:

2000-20-04 McDonnell Douglas: Amendment 39-11915. Docket 99-NM-329-AD. Supersedes AD 2000-16-01, Amendment 39-11855.

Applicability: Model MD-90-30 series airplanes, as listed in McDonnell Douglas Alert Service Bulletin MD90-24A060, Revision 01, dated September 2, 1999, and McDonnell Douglas Service Bulletin MD90-24-062, dated February 3, 2000; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent a loose electrical ground block of the circuit ground wires of the electrical power control unit (EPCU), accomplish the following:

Replacement

(a) For airplanes listed in McDonnell Douglas Alert Service Bulletin MD90-24A060, Revision 01, dated September 2, 1999: Within 30 days after the effective of this AD, replace the electrical ground block screws with new screws in accordance with McDonnell Douglas Alert Service Bulletin MD90-24A060, Revision 01, dated September 2, 1999.

Note 2: Accomplishment of the replacement of electrical ground block screws prior to the effective date of this AD in accordance with McDonnell Douglas Alert Service Bulletin MD90-24A060, dated July 28, 1999, is acceptable for compliance with the requirements of paragraph (a) of this AD.

Modification of the Electrical Power Control Unit

(b) For airplanes listed in McDonnell Douglas Service Bulletin MD90-24-062, dated February 3, 2000: Within 12 months after the effective date of this AD, reterminate the circuit ground wires of the EPCU to separate grounding points to ensure that a single point failure does not occur, in accordance with McDonnell Douglas Service Bulletin MD90-24-062, dated February 3, 2000.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add

comments and then send it to the Manager, Los Angeles ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Incorporation by Reference

(d) The actions shall be done in accordance with McDonnell Douglas Alert Service Bulletin MD90-24A060, Revision 01, dated September 2, 1999; and McDonnell Douglas Service Bulletin MD90-24-062, dated February 3, 2000; as applicable.

(1) The incorporation by reference of McDonnell Douglas Service Bulletin MD90-24-062, dated February 3, 2000, is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of McDonnell Douglas Alert Service Bulletin MD90-24A060, Revision 01, dated September 2, 1999, was approved previously by the Director of the Federal Register as of September 19, 2000 (65 FR 49728, August 15, 2000).

(3) Copies may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(e) This amendment becomes effective on November 13, 2000.

Issued in Renton, Washington, on September 26, 2000.

Donald L. Riggin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 00-25149 Filed 10-5-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-356-AD; Amendment 39-11916; AD 2000-20-05]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-120 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD),