

(2) The final agreement and all supporting documents material to the Corporation's purchase of a security under section 8.6(e) of the Act.

(c) For securities backed by qualified loans as defined in section 8.0(9)(B) of the Act, the Corporation must provide summary information on such securities issued during each calendar quarter in the form prescribed by us. Such summary information must be provided with each report of condition and performance (Call report) filed pursuant to § 621.12, and at such other times as we may require.

**§ 655.21 Filings and communications with the U.S. Treasury, the SEC, and NYSE.**

(a) The Corporation must send us one paper and one electronic copy of every filing made with U.S. Treasury, the SEC, or NYSE, including financial statements and related schedules, exhibits, and other documents that are a part of the filing. Such items must be filed with us no later than 1 business day after the U.S. Treasury, SEC, or NYSE filing. For those filings with the NYSE that duplicate ones made to the SEC, the Corporation may send only the SEC filing to us. If the filing is one addressed in subpart B of this part, no action under this paragraph is required.

(b) The Corporation must send us, within 3 business days and according to instructions provided by us, copies of all substantive correspondence between the Corporation and the U.S. Treasury, the SEC, or NYSE that are directed at the activities of the Corporation.

(c) The Corporation must notify us within 1 business day if it becomes exempt or claims exemption from the filing requirements of the Securities Act. Notice is not required when the Corporation claims an exemption that is generally available under SEC rules and regulations to similarly situated filers.

Date: July 20, 2016.

**Dale L. Aultman,**

*Secretary, Farm Credit Administration Board.*  
[FR Doc. 2016-17455 Filed 7-26-16; 8:45 am]

**BILLING CODE 6705-01-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA-2015-8435; Directorate Identifier 2015-NM-049-AD; Amendment 39-18594; AD 2016-15-03]

**RIN 2120-AA64**

**Airworthiness Directives; Bombardier, Inc. Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Bombardier, Inc. Model BD-700-1A10 and BD-700-1A11 airplanes. This AD was prompted by reports of operator inability to open the main passenger door following severe hot soak conditions. This AD requires the incorporation of a new configuration to the passenger door external handle detent to enhance the performance across the full range of the airplane operating temperatures. We are issuing this AD to prevent thermal expansion and permanent deformation at severe hot soak conditions, creating high friction between the spring pot housing and the slider that could result in inability to open the main passenger door and impede evacuation in the event of an emergency.

**DATES:** This AD is effective August 31, 2016.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of August 31, 2016.

**ADDRESSES:** For service information identified in this final rule, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-8435.

*Examining the AD Docket*

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for

and locating Docket No. FAA-2015-8435; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:**

Cesar A. Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7318; fax 516-794-5531.

**SUPPLEMENTARY INFORMATION:**

**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc. Model BD-700-1A10 and BD-700-1A11 airplanes. The NPRM published in the **Federal Register** on January 13, 2016 (81 FR 1584) ("the NPRM"). The NPRM was prompted by reports of operator inability to open the main passenger door following severe hot soak conditions. The NPRM proposed to require the incorporation of a new configuration to the passenger door external handle detent to enhance the performance across the full range of the airplane operating temperatures. We are issuing this AD to prevent thermal expansion and permanent deformation at severe hot soak conditions, creating high friction between the spring pot housing and the slider that could result in inability to open the main passenger door and impede evacuation in the event of an emergency.

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2015-03, dated March 13, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Bombardier, Inc. Model BD-700-1A10 and BD-700-1A11 airplanes. The MCAI states:

There have been reports where operators experienced an inability to open the main passenger door following severe hot soak conditions.

Investigation determined that the nylon slider in the plunger assembly of the door handle is susceptible to thermal expansion

and permanent deformation at severe hot soak conditions, creating high friction between the spring pot housing and the slider.

This condition, if not corrected, could result in an inability to open the main passenger door and could impede evacuation in the event of an emergency.

This [Canadian] AD mandates the incorporation of a new configuration to the passenger door external handle detent to enhance the performance across the full range of the aeroplanes operating temperatures.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-8435.

### Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

### Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

### Related Service Information Under 14 CFR Part 51

Bombardier issued the following service information:

- Bombardier Service Bulletin 700-1A11-52-021, Revision 01, dated February 3, 2015.
- Bombardier Service Bulletin 700-52-044, Revision 01, dated February 3, 2015.
- Bombardier Service Bulletin 700-52-5008, Revision 01, dated February 3, 2015.
- Bombardier Service Bulletin 700-52-6008, Revision 01, dated February 3, 2015.

The service information describes procedures to incorporate a new configuration to the passenger door external handle detent. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

### Costs of Compliance

We estimate that this AD affects 60 airplanes of U.S. registry.

We also estimate that it would take about 4 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$0 per product. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$20,400, or \$340 per product.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2016-15-03 Bombardier, Inc.:** Amendment 39-18594. Docket No. FAA-2015-8435; Directorate Identifier 2015-NM-049-AD.

#### (a) Effective Date

This AD is effective August 31, 2016.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Bombardier Inc. Model BD-700-1A10 and BD-700-1A11 airplanes, certificated in any category, serial numbers (S/Ns) 9002 through 9515 inclusive and S/N 9998.

#### (d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

#### (e) Reason

This AD was prompted by reports of operator inability to open the main passenger door following severe hot soak conditions. We are issuing this AD to prevent thermal expansion and permanent deformation at severe hot soak conditions, creating high friction between the spring pot housing and the slider that could result in inability to open the main passenger door that could impede evacuation in the event of an emergency.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Modification

Within 15 months after the effective date of this AD, incorporate the new configuration to the passenger door external handle detent, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraphs (g)(1) through (g)(4) of this AD:

(1) Bombardier Service Bulletin 700-1A11-52-021, Revision 01, dated February 3, 2015 (for Model BD-700-1A11 airplanes).

(2) Bombardier Service Bulletin 700-52-044, Revision 01, dated February 3, 2015 (for Model BD-700-1A10 airplanes).

(3) Bombardier Service Bulletin 700-52-5008, Revision 01, dated February 3, 2015 (for Model BD-700-1A11 airplanes).

(4) Bombardier Service Bulletin 700-52-6008, Revision 01, dated February 3, 2015 (for Model BD-700-1A10 airplanes).

**(h) Credit for Previous Actions**

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using the following service information, as applicable. This service information is not incorporated by reference in this AD.

(1) Bombardier Service Bulletin 700–1A11–52–021, dated November 9, 2012.

(2) Bombardier Service Bulletin 700–52–044, dated November 9, 2012.

(3) Bombardier Service Bulletin 700–52–5008, dated November 9, 2012.

(4) Bombardier Service Bulletin 700–52–6008, dated November 9, 2012.

**(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE–170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE–170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

**(j) Related Information**

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF–2015–03, dated March 26, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–8435.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 700–1A11–52–021, Revision 01, dated February 3, 2015.

(ii) Bombardier Service Bulletin 700–52–044, Revision 01, dated February 3, 2015.

(iii) Bombardier Service Bulletin 700–52–5008, Revision 01, dated February 3, 2015.

(iv) Bombardier Service Bulletin 700–52–6008, Revision 01, dated February 3, 2015.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–5000; fax 514–855–7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 19, 2016.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2016–17538 Filed 7–26–16; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 145**

[Docket No.: FAA–2016–8744; Amdt. No. 145–31]

**RIN 2120–AK86**

**Repair Stations**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Interim final rule.

**SUMMARY:** The Federal Aviation Administration (FAA) is revising its repair station rules to remove the requirement that a repair station with an airframe rating provide suitable permanent housing to enclose the largest type and model aircraft listed on its operations specifications. The FAA is also revising its general housing and facilities regulation to provide that a repair station's housing for its facilities, equipment, materials, and personnel must be consistent not only with its ratings, but also with its limitations to those ratings. Finally, the FAA is adding an additional general purpose limited rating to cover maintenance work not covered by the existing 12 limited rating categories. These changes are necessary because the existing ratings and housing rules impose unnecessary housing requirements on certain repair stations that work only on component parts of an aircraft. These changes will enable

some repair stations to obtain a limited rating that is tailored to their intended scope of work, and will relieve repair stations that have a limited airframe rating, but that work only on component parts of an aircraft, from having to provide large and expensive housing to enclose the entire aircraft when that type of housing is not needed for the limited scope of their work.

**DATES:** Effective July 27, 2016.

Submit comments on or before August 26, 2016.

**ADDRESSES:** Send comments identified by docket number FAA–2016–8744 using any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the online instructions for sending your comments electronically.

- *Mail:* Send comments to Docket Operations, M–30; U.S. Department of Transportation (DOT), 1200 New Jersey Avenue SE., Room W12–140, West Building Ground Floor, Washington, DC 20590–0001.

- *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Fax:* Fax comments to Docket Operations at 202–493–2251.

*Privacy:* In accordance with 5 U.S.C. 553(c), DOT solicits comments from the public to better inform its rulemaking process. DOT posts these comments, without edit, including any personal information the commenter provides, to [www.regulations.gov](http://www.regulations.gov), as described in the system of records notice (DOT/ALL–14 FDMS), which can be reviewed at [www.dot.gov/privacy](http://www.dot.gov/privacy).

*Docket:* Background documents or comments received may be read at <http://www.regulations.gov> at any time. Follow the online instructions for accessing the docket or Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**FOR FURTHER INFORMATION CONTACT:** For technical questions concerning this action, contact Susan Traugott Ludwig, Aircraft Maintenance Division, Repair Station Branch, AFS–340, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone (214) 587–8887; email [susan.traugott.ludwig@faa.gov](mailto:susan.traugott.ludwig@faa.gov).

**SUPPLEMENTARY INFORMATION:**