

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

[Airspace Docket No. 96-AGL-29]

**Establishment of Class E Airspace;  
Lemmon, SD, Lemmon Municipal  
Airport***Correction*

In rule document 97-6617, beginning on page 12536, in the issue of Monday, March 17, 1977, make the following correction:

On page 12537, in the first column, in the **AGL SD E5 Lemmon, SD [New]** paragraph, in the eighth line, "45°33'00"" should read "45°45'00"".

BILLING CODE 1505-01-D