required installation, and that the average labor rate is \$60 per work hour. Required parts will be provided by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the installation required by this AD on U.S. operators is estimated to be \$6,000, or \$1,500 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a 'significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT **Regulatory Policies and Procedures (44** FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

98-19-16 Aerospatiale: Amendment 39-

10756. Docket 98–NM–159–AD. Applicability: Model ATR72–212A series airplanes, on which Aerospatiale Modification 4831 has not been accomplished; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent rupture of the lower attachment fittings of the flap support beam due to fatigue, and consequent damage to the flaps, accomplish the following:

(a) Prior to the accumulation of 24,000 total flight cycles, or within 500 flight cycles after the effective date of this AD, whichever occurs later, install bushings on the lower attachment fittings of the flap support beam in accordance with Avions de Transport Regional Service Bulletin ATR72–57–1020, dated March 9, 1998.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The installation shall be done in accordance with Avions de Transport Regional Service Bulletin ATR72–57–1020, dated March 9, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, Cedex 03, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in French airworthiness directive 98–072– 036(B), dated February 11, 1998, as revised by Erratum 98–072–036(B), dated February 25, 1998.

(e) This amendment becomes effective on October 20, 1998.

Issued in Renton, Washington, on September 4, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 98–24407 Filed 9–14–98; 8:45 am] BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 98-ANM-12]

Amendment of Class E Airspace; Price, UT

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule.

SUMMARY: This action amends the Price, UT, Class E airspace by providing additional controlled airspace to accommodate the development of a new Standard Instrument Approach Procedure (SIAP) at Carbon County Airport.

EFFECTIVE DATE: 0901 UTC, December 3, 1998.

FOR FURTHER INFORMATION CONTACT: Dennis Ripley, ANM–520.6, Federal Aviation Administration, Docket No. 98–ANM–12, 1601 Lind Avenue, SW, Renton, Washington, 98055–4056; telephone number: (425) 227–2527.

SUPPLEMENTARY INFORMATION:

History

On June 22, 1998, the FAA proposed to amend Title 14, Code of Federal Regulations, part 71 (14 CFR part 71) by revising the Price, UT, Class E airspace area (63 FR 33881). This revision provides the additional airspace necessary to encompass the holding pattern for the new GPS Runway 36 SIAP for the Carbon County Airport, Price, UT. Interested parties were invited to participate in the rulemaking proceeding by submitting written comments on the proposal. No comments were received.

The coordinates for this airspace docket are based on North American Datum 83. Class E airspace areas extending upward from 700 feet or more above the surface of the earth are published in Paragraph 6005 of FAA Order 7400.9E, dated September 10, 1997, and effective September 16, 1997, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

The Rule

This amendment to 14 CFR part 71 modifies Class E airspace at Price, UT, by providing the additional airspace necessary to fully contain new flight procedures at Carbon County Airport. This modification of airspace allows the holding pattern and the transition procedure for the new SIAP to be fully encompassed within controlled airspace. The intended effect of this rule is designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under Instrument Flight Rules (IFR) at the Carbon County Airport and between the terminal and en route transition stages.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a ''significant rule'' under DOT **Regulatory Policies and Procedures (44** FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9E, Airspace Designations and Reporting Points, dated September 10, 1997, and effective September 16, 1997, is amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth. * * * * * *

ANM UT E5 Price, UT [Revised]

Price, Carbon County Airport, UT (Lat. 39°36'43" N, long. 110°45'02" W) Carbon VOR/DME

(Lat. 39°36'11" N, long. 110°45'13" W) That airspace extending upward from 700 feet above the surface within a 4.3-mile radius of the Carbon VOR/DME, and within 1.8 miles each side of the 200° radial of the Carbon VOR/DME extending from the 4.3mile radius to 7 miles south of the Carbon VOR/DME; that airspace extending upward from 1,200 feet above the surface bounded by a line beginning at lat. 39°50′00″ N, long. 111°00′00″ W; to lat. 39°45′00″ N, long. 110°30′00″ W; to lat. 39°05′00″ N, long. 110°30'00" W; to lat. 39°05'00" N, long. 111°00′00″ W; to lat. 39°21′00″ N, long. 111°05′00″ W; thence to point of beginning; excluding that airspace within Federal Airways, the Moab, UT, and the Salt Lake City, UT, Class E airspace areas.

* * * * *

Issued in Seattle, Washington, on August 26, 1998.

Glenn A. Adams, III,

Assistant Manager, Air Traffic Division, Northwest Mountain Region. [FR Doc. 98–24709 Filed 9–14–98; 8:45 am] BILLING CODE 4910–13–M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 98-ACE-28]

Amendment to Class E Airspace; Fairbury, NE

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Direct final rule; request for comments.

SUMMARY: This action amends the Class E airspace area at Fairbury Municipal Airport, Fairbury, NE. The FAA has developed Global Positioning System (GPS) Runway (RWY) 17 and RWY 35 Standard Instrument Approach Procedures (SIAPs) to serve Fairbury Municipal Airport, NE. Additional controlled airspace extending upward from 700 feet Above Ground Level (AGL) is needed to accommodate these SIAPs and for Instrument Flight Rules (IFR) operations at this airport. The enlarged area will contain the new GPS RWY 17 and GPS RWY 35 SIAPs in controlled airspace. The intended effect of this rule is to provide controlled Class E airspace for aircraft executing the GPS RWY 17 and GPS RWY 35 SIAPs and to segregate aircraft using instrument approach procedures in instrument conditions from aircraft operating in visual conditions. DATES: This direct final rule is effective on 0901 UTC, January 28, 1999.

Comments for inclusion in the Rules Docket must be received on or before October 23, 1998.

ADDRESSES: Send comments regarding the rule in triplicate to: Manager, Airspace Branch, Air Traffic Division, ACE–520, Federal Aviation Administration, Docket Number 98– ACE–28, 601 East 12th Street, Kansas City, MO 64106.

The official docket may be examined in the Office of the Regional Counsel for the Central Region at the same address between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

An informal docket may also be examined during normal business hours in the Air Traffic Division at the same address listed above.

FOR FURTHER INFORMATION CONTACT: Kathy Randolph, Air Traffic Division, Airspace Branch, ACE–520C, Federal Aviation Administration, 601 East 12th Street, Kansas City, MO 64106; telephone: (816) 426–3408.

SUPPLEMENTARY INFORMATION: The FAA has developed GPS RWY 17 and GPS RWY 35 SIAPs to serve the Fairbury Municipal Airport, Fairbury, NE. The amendment to Class E airspace at Fairbury, NE, will provide additional controlled airspace at the above 700 feet AGL in order to contain the new SIAPs within controlled airspace, and thereby facilitate separation of aircraft operating under Instrument Flight Rules. The area will be depicted on appropriate aeronautical charts. Class E airspace areas extending upward from 700 feet or more above the surface of the earth are published in paragraph 6005 of FAA Order 7400.9E, dated September 10, 1997, and effective September 16, 1997, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

The Direct Final Rule Procedure

The FAA anticipates that this regulation will not result in adverse or negative comment and, therefore, is issuing it as a direct final rule. Previous