

been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct scoring of the upper fuselage skin around the periphery of the cockpit canopy blister interface, which could result in reduced structural integrity of the fuselage skin, and consequent cabin depressurization; accomplish the following:

Restatement of the Requirements of AD 97-09-12

(a) For Model DH.125-1A, -3A, and -400A series airplanes as identified in Raytheon Aircraft Service Bulletin SB 53-93, dated May 16, 1996: Within 90 days after June 6, 1997 (the effective date of AD 97-09-12, amendment 39-10008), perform a one-time detailed visual inspection to detect scoring of the upper fuselage skin around the periphery of the cockpit canopy blister interface, in accordance with the service bulletin.

(b) If no scoring is detected during the inspection required by paragraph (a) of this AD, no further action is required by this AD.

(c) If any scoring is detected during the inspection required by paragraph (a) of this AD, prior to further flight, determine the maximum location and details of each score, including the edge distance and material thickness, in accordance with Raytheon Aircraft Service Bulletin SB 53-93, dated May 16, 1996.

(1) If any scoring is found that is within the limits specified in the service bulletin, prior to further flight, repair in accordance with the service bulletin.

(2) If any scoring is found that is outside the limits specified in the service bulletin, prior to further flight, repair in accordance with a method approved by the Manager, Wichita Aircraft Certification Office (ACO), FAA, Small Airplane Directorate.

New Requirements of This AD

(d) For airplanes identified in Raytheon Aircraft Service Bulletin SB 53-93, Revision 2, dated April 2000, and not previously identified in paragraph (a) of this AD: Within 90 days after the effective date of this AD, perform a one-time detailed visual inspection to detect scoring of the upper fuselage skin around the periphery of the cockpit canopy blister interface, in accordance with Raytheon Aircraft Service Bulletin SB 53-93, Revision 2, dated April 2000.

(1) If no scoring is detected during the inspection required by paragraph (d) of this AD, no further action is required by this AD.

(2) If any scoring is detected during the inspection required by paragraph (d) of this AD, prior to further flight, determine the location and details of each score, including the edge distance and material thickness, in accordance with the service bulletin.

(i) If any scoring is found that is within the limits specified in the service bulletin, prior to further flight, repair in accordance with the service bulletin.

(ii) If any scoring is found that is outside the limits specified in the service bulletin, prior to further flight, repair in accordance with a method approved by the Manager, Wichita ACO.

Note 2: Any inspections and repairs accomplished prior to the effective date in

accordance with Raytheon Service Bulletin SB 53-93, Revision 1, dated April 1999, are considered acceptable for compliance for the applicable actions required by this AD.

Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Wichita ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on June 12, 2000.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-15310 Filed 6-15-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00-AGL-17]

Proposed Modification of Class E Airspace; Dickinson, ND

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to modify Class E airspace at Dickinson, ND. An examination of the Class E airspace for Dickinson, ND, has revealed a discrepancy in the airport reference point used for the controlled airspace legal descriptions. This action would correct that discrepancy by incorporating the current airport reference point in the Class E airspace for Dickinson Municipal Airport.

DATES: Comments must be received on or before July 24, 2000.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Office of the Regional Counsel, AGL-7, Rules Docket No. 00-AGL-17, 2300 East Devon Avenue, Des Plaines, Illinois 60018.

The official docket may be examined in the Office of the Regional Counsel,

Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois. An informal docket may also be examined during normal business hours at the Air Traffic Division, Airspace Branch, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois.

FOR FURTHER INFORMATION CONTACT:

Denis C. Burke, Air Traffic Division, Airspace Branch, AGL-520, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018, telephone (847) 294-7568.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 00-AGL-17." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the Rules docket, FAA, Great Lakes Region, Office of the Regional Counsel, 2300 East Devon Avenue, Des Plaines, Illinois, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Office of Public Affairs, Attention: Public Inquiry Center, APA-230, 800 Independence Avenue, SW, Washington, DC 20591, or

by calling (202) 267-3484.

Communications must identify the docket number of this NPRM. Persons interested in being placed on a mailing list for future NPRM's should also request a copy of Advisory Circular No. 11-2A, which describes the application procedure.

The Proposal

The FAA is considering an amendment to 14 CFR part 71 to modify Class E airspace at Dickinson, ND, by incorporating the correct airport reference point for Dickinson Municipal Airport into the controlled airspace legal descriptions. Controlled airspace extending upward from the surface of the earth is needed to contain aircraft executing instrument approach procedures. The area would be depicted on appropriate aeronautical charts. Class E airspace areas designated as surface areas are published in paragraph 6002 and Class E airspace areas extending upward from 700 feet or more above the surface are published in paragraph 6005 of FAA Order 7400.9G dated September 1, 1999, and effective September 16, 1999, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an establishment body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore this, proposed regulation—(1) Is not a “significant regulatory action” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9G, Airspace Designations and Reporting Points, dated September 1, 1999, and effective September 16, 1999, is amended as follows:

* * * * *

Paragraph 6002 Class E airspace designated as a surface area.

* * * * *

AGL ND E2 Dickinson, ND [Revised]

Dickinson Municipal, ND

(Lat. 46°47'51" N., long. 102°48'07" W.)

Within an 4.4-mile radius of the Dickinson Municipal Airport, and within 1.4 miles each side of the 150° bearing from the airport, extending from the 4.4-mile radius to 7.0 miles southeast of the airport.

* * * * *

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

AGL ND E5 Dickinson, ND [Revised]

Dickinson Municipal, ND

(Lat. 46°47'51" N., long. 102°48'07" W.)

Dickinson VORTAC

(Lat. 46°51'36" N., long. 102°46'25" W.)

That airspace extending upward from 700 feet above the surface within an 8.3-mile radius of the Dickinson Municipal Airport, and within 4.0 miles each side of the 150° bearing from the airport, extending from the 8.3-mile radius to 14.0 miles southeast of the airport, and that airspace extending upward from 1,200 feet above the surface within a 25.2-mile radius of the Dickinson VORTAC extending clockwise from the Dickinson VORTAC 214° radial to the Dickinson VORTAC 093° radial.

* * * * *

Issued in Des Plaines, Illinois on May 23, 2000.

Christopher R. Blum,

Manager, Air Traffic Division.

[FR Doc. 00-15207 Filed 6-15-00; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. 00-AGL-19]

Proposed Establishment of Class E Airspace; Soldiers Grove, WI

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to establish Class E airspace at Soldiers Grove, WI. A Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) to Runway (Rwy) 11, and a GPS SIAP to Rwy 29, have been developed for Leeward Farm Airport. Controlled airspace extending upward from 700 feet or more above the surface of the earth is needed to contain aircraft executing these approaches. This action would create controlled airspace for Leeward Farm Airport.

DATES: Comments must be received on or before July 24, 2000.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Office of the Regional Counsel, AGL-7, Rules Docket No. 00-AGL-19, 2300 East Devon Avenue, Des Plaines, Illinois 60018.

The official docket may be examined in the Office of the Regional Counsel, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois. An informal docket may also be examined during normal business hours at the Air Traffic Division, Airspace Branch, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois.

FOR FURTHER INFORMATION CONTACT: Denis C. Burke, Air Traffic Division, Airspace Branch, AGL-520, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018, telephone (847) 294-7568.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify the