



Figure 1

**BILLING CODE 4910-13-C**

(2) Inspect each bearing attach hardware lock plate for bent-open tabs and slippage marks for attach hardware looseness or rotation. Before further flight, replace any loose bearing attach hardware (including lock plates found bent or open due to bolt rotation) with airworthy hardware.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(f) The modifications shall be done in accordance with Eurocopter Deutschland GmbH Alert Service Bulletin EC 135-53A-005, Revision 3, dated September 2, 1998, and Eurocopter Deutschland GmbH Alert Service Bulletin EC 135-53A-004, dated

August 14, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(g) This amendment becomes effective on August 9, 2000.

**Note 4:** The subject of this AD is addressed in Luftfahrt-Bundesamt (Federal Republic of Germany) AD's 1998-033/7 and 1998-389, both dated September 14, 1998.

Issued in Fort Worth, Texas, on June 26, 2000.

**Eric Bries,**

*Acting Manager, Rotorcraft Directorate,  
Aircraft Certification Service.*

[FR Doc. 00-16781 Filed 7-3-00; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

[Airspace Docket No. 00-AAL-1]

**Revision of Class E Airspace; Barrow, AK**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action revises Class E airspace at Barrow, AK. The revision of instrument approach procedures to runway (RWY) 6 and RWY 24 at Wiley Post—Will Rogers Memorial Airport, Barrow, AK, made this action necessary. This rule provides adequate controlled airspace for aircraft flying IFR procedures at Barrow, AK.

**EFFECTIVE DATE:** 0901 UTC, October 5, 2000.

**FOR FURTHER INFORMATION CONTACT:** Bob Durand, Operations Branch, Federal Aviation Administration, 222 West 7th Avenue, Box 14, Anchorage, AK 99513-

7587; telephone number (907) 271-5898; fax: (907) 271-2850; email: Bob.Durand@faa.gov. Internet address: <http://www.alaska.faa.gov/at> or at address <http://162.58.28.41/at>.

#### SUPPLEMENTARY INFORMATION:

#### History

On April 24, 2000, a proposal to amend part 71 of the Federal Aviation Regulations (14 CFR part 71) to revise the Class E airspace at Barrow, AK, was published in the **Federal Register** (65 FR 21681). The proposal was necessary due to revisions to the instrument approaches to runway (RWY) 06 and RWY 24 at Wiley Post—Will Rogers Memorial Airport, Barrow, AK.

Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No public comments to the proposal were received, thus, the rule is adopted as written.

The area will be depicted on aeronautical charts for pilot reference. The coordinates for this airspace docket are based on North American Datum 83. The Class E airspace areas designated as 700/1200 foot transition areas are published in paragraph 6005 of FAA Order 7400.9G, *Airspace Designations and Reporting Points*, dated September 1, 1999, and effective September 16, 1999, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be revised and published subsequently in the Order.

#### The Rule

This amendment to 14 CFR part 71 revises the Class E airspace at Barrow, AK, through the revisions of instrument approaches to the Wiley Post—Will Rogers Memorial Airport, Barrow, AK. The area will be depicted on aeronautical charts for pilot reference. The intended effect of this proposal is to provide adequate controlled airspace for IFR operations at Wiley Post—Will Rogers Memorial Airport, Barrow, AK.

The FAA has determined that these proposed regulations only involve an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore —(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air

navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR part 71

Airspace, Incorporation by reference, Navigation (air).

#### Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

#### PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

#### § 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9G, *Airspace Designations and Reporting Points*, dated September 1, 1999, and effective September 16, 1999, is amended as follows:

*Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.*

\* \* \* \* \*

#### AAL AK E5 Barrow, AK [Revised]

Barrow/Wiley Post—Will Rogers Memorial Airport, AK

(Lat. 71°17′08″ N, long. 156°45′58″ W)

Barrow VORTAC

(Lat. 71°16′24″ N, long. 156°47′18″ W)

Barrow Localizer

(Lat. 71°17′08″ N, long. 156°44′07″ W)

That airspace extending upward from 700 feet above the surface within a 6.6-mile radius of Barrow/Wiley Post—Will Rogers Memorial Airport and within 4 miles north and 6 miles south of the Barrow Localizer back course extending from the 6.6-mile radius to 14.6 miles east of the airport; and that airspace extending upward from 1,200 feet above the surface within a 77-mile radius of the airport extending clockwise from the Barrow VORTAC 101° radial to the 240° radial and within the area bounded by a line beginning at the Barrow VORTAC 240° radial 20 miles west to lat. 71°13′ N long. 158° W, to lat. 71°23′ N long. 157°48′ W to lat. 71°25′ N long. 156°55′ W to lat. 71°20′ N long. 155°40′ W to lat. 71°14′ N 155°40′ W.

\* \* \* \* \*

Issued in Anchorage, AK, on June 27, 2000.

**Willis C. Nelson,**

*Manager, Air Traffic Division, Alaskan Region.*

[FR Doc. 00–16918 Filed 7–3–00; 8:45 am]

BILLING CODE 4910–13–P

#### DEPARTMENT OF TRANSPORTATION

#### Federal Aviation Administration

#### 14 CFR Part 71

[Airspace Docket No. 99–ASW–33]

RIN 2120–AA66

#### Realignment of Jet Route; TX

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This action corrects a final rule published in the **Federal Register** on June 14, 2000 (Airspace Docket No. 99–ASW–33). The legal description of Jet Route 25 (J–25) contained an inadvertent error between the Corpus Christi, TX, Very High Frequency Omnidirectional Range/Tactical Air Navigation (VORTAC) and the San Antonio, TX, VORTAC. This action corrects that error.

**EFFECTIVE DATE:** July 5, 2000.

**FOR FURTHER INFORMATION CONTACT:** Bill Nelson, Airspace and Rules Division, ATA–400, Office of Air Traffic Airspace Management, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267–8783.

**SUPPLEMENTARY INFORMATION:** On June 14, 2000, Airspace Docket No. 99–ASW–33, FR Doc. 00–14909, was published amending the legal description of J–25 between the Corpus Christi, TX, VORTAC and the San Antonio, TX, VORTAC (65 FR 37277). This rule inadvertently listed the true bearing between Corpus Christi, TX, and San Antonio, TX, as “166°.” The correct true bearing is “174°.” The correct true bearing was listed in the Notice of Proposed Rulemaking for this matter.

#### Correction to Final Rule

Accordingly, pursuant to the authority delegated to me, the legal description for J–25 as published in the **Federal Register** on June 24, 2000 (65 FR 37277), FR Doc. 00–14909, and incorporated by reference in 14 CFR 71.1, is corrected as follows:

#### § 71.1 [Corrected]

*Paragraph 2004 Jet Routes*

\* \* \* \* \*