Action	Compliance time	Procedures
(1) Visually inspect the push rod guide to ensure that the outer aluminum tube of the guide does not move.	Within the next 30 days after the effective date of this AD, and prior to accomplishing the modification required in paragraph (d)(3) of this AD. The second inspection is not required if the modification is incorporated immediately after the initial inspection.	Follow the inspection procedures in the Instruction section of DG Flugzeugbau Technical Note (TN) 348/12 (applicable to the model DG–500 Elan Series) or TN 843/12 (applicable to the models DG–500M and DG–500MB), both dated October 6, 1999.
<ul> <li>(2) If any movement is detected in the outer aluminum tube as specified in this AD and the referenced service information, accomplish the following: <ul> <li>(i) Obtain a repair scheme from the manufacturer at the address presented in paragraph (h) of this AD; and.</li> <li>(ii) Incorporate this repair scheme</li></ul></li></ul>	Required prior to further flight after the inspection when the discrepancy is found.	In accordance with the repair scheme obtained from the manufacturer.
(3) Modify and install resin thickened cottonflock reinforcements to the elevator control system as a way to increase the stiffness of the elevator control support stand.	Within the next 120 days after the effective date of this AD.	Follow the modification procedures in the Working Instructions No. 1 for TN 348/12 (843/12), dated September 28, 1999. The instructions are referenced in DG Flugzeugbau Technical Note (TN) 348/12 (applicable to the model DG–500 Elan Series) or TN 843/12 (applicable to the models DG–500M and DG–500MB), both dated October 6, 1999.

(e) Can I comply with this AD in any other way? You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the

Note 1: This AD applies to each sailplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For sailplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specify actions you propose to address it.

- (f) Where can I get information about any already-approved alternative methods of compliance? Contact Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4144; facsimile:  $(816)\ 329 - \hat{4}090.$
- (g) What if I need to fly the sailplane to another location to comply with this AD? The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your sailplane to a location where you can accomplish the requirements
- (h) How do I get copies of the documents referenced in this AD? You may obtain copies of the documents referenced in this AD from DG Flugzeugbau, Postbox 41 20, D-76646 Bruchsal, Federal Republic of Germany. You

may examine these documents at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Note 2: The subject of this AD is addressed in German AD 1999-341, dated November 18, 1999.

Issued in Kansas City, Missouri, on September 11, 2000.

#### Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-23862 Filed 9-20-00; 8:45 am] BILLING CODE 4910-13-P

#### **DEPARTMENT OF TRANSPORTATION**

#### Federal Aviation Administration

#### 14 CFR Part 71

[Airspace Docket No. 99-ANM-10]

### Proposed Modification of Class E Airspace, St. George, UT

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of Proposed Rulemaking

(NPRM).

**SUMMARY:** This action proposes to modify the Class E airspace at St. George, UT. A new Area Navigation (RNAV) Standard Instrument Approach Procedure (SIAP) to Runway (RWY) 34 at St. George Municipal Airport has made this proposal necessary. Additional Class E controlled airspace from 700 feet and 1,200 feet above the earth is required to contain aircraft executing the RNAV RWY 34 SIAP with a Terminal Arrival Area (TAA) design to

St. George Municipal Airport. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at St. George Municipal Airport, St. George, UT.

DATES: Comments must be received on or before November 6, 2000.

ADDRESSES: Send comments on the proposal in triplicate to: Manager, Airspace Branch, ANM-520, Federal Aviation Administration, Docket No. 99-ANM-10, 1601 Lind Avenue SW, Renton, Washington 98055-4056.

The official docket nay be examined in the Office of the Regional Counsel for the Northwest Mountain Region at the same address.

As informal docket may also be examined during normal business hours in the office of the Manager, Air Traffic Division, Airspace Branch, at the address listed above.

#### FOR FURTHER INFORMATION CONTACT:

Brian Durham, ANM-520.7, Federal Aviation Administration, Docket No. 99-ANM-10, 1601 Lind Avenue SW, Renton, Washington 98055-4056; telephone number: (425) 227-2527.

**SUPPLEMENTARY INFORMATION: Comments** Invited Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy related

aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit, with those comments, a self-addressed stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 99-ANM-10." The Postcard will be date/ time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in the light of comments received. All comments submitted will be available for examination at the address listed above both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

## Availability of NPRM's

Any person may obtain a copy of this NPRM by submitting a request to the Federal Aviation Administration, Airspace Branch, ANM–520, 1601 Lind Avenue SW, Renton, Washington 98055–4056. Communications must identify the docket number of this NPRM. Persons interested in being placed on a mailing list for future NPRM's should also request a copy of Advisory Circular No. 11–2A, which describes the application procedure.

## The Proposal

The FAA is considering an amendment to Title 14 Code of Federal Regulations, part 71 (14 CFR part 71) by modifying Class E airspace at St. George, UT. A new RNAV SIAP to RWY 34 at St. George Municipal Airport has made this proposal necessary. Additional controlled airspace from 700 feet and 1,200 feet above the surface is required to contain aircraft executing the RNAV RWY 34 SIAP with a TAA design to St. George Municipal Airport. The FA establishes Class E airspace where necessary to contain aircraft transitioning between the terminal and en route environments. The intended effect of this proposal is designed to provide for the safe and efficient use of the navigable airspace. This proposal would promote safe flight operations under IFR at the St. George Municipal Airport and between the terminal and en route transition stages.

The area would be depicted on aeronautical charts for pilot reference.

The coordinates for this airspace docket are based on North American Datum 83. Class E airspace areas extending upward from 700 feet or more above the surface of the earth, are published in Paragraph 6005, of FAA Order 7400.9G dated September 1, 1999, and effective September 16, 1999, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

# The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

# PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

#### §71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9G, Airspace Designations and Reporting Points, dated September 1, 1999, and effective September 16, 1999, is amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

\* \* \* \* \*

#### ANM UT E5 St. George, UT [Revised]

St. George Municipal Airport, UT (Lat. 37°05′29″N., long. 113°35′35″W.) St. George VOR/DME

(Lat. 37°05′17″N., long. 113°35′31″W.)

That airspace extending upward from 700 feet above the surface within a 8.3 miles northeast and 5.3 miles southwest of the St. George VOR/DME 131° and 311° radials extending from 6.1 miles northwest to 16.1 miles southeast, and within 5.9 miles each side of the St. George VOR/DME  $183^{\circ}$  radial extending from the VOR/DME to 18.2 miles south; and that airspace extending upward from 1,200 feet above the surface within the 30 mile radius of lat. 36°48′87″N., long. 113°35′62″W., extending clockwise from the 256° bearing to the 076° bearing, and within 30 miles radius of lat. 36°48′89"N., long. 113°43′10″W., extending clockwise from the 076° bearing to the 166° bearing of lat. 36°48′87″N., long. 113°35′62″W., and within 30 miles radius of lat. 36°48′86″N., long. 113°29′40″W., extending counterclockwise from the 256° bearing to the 166° bearing of lat. 36°48′87″N., long. 113°35′62″W; excluding that portion of airspace within the Colorado City, AZ, 700 and 1,200 feet Class E airspace area; that portion of airspace within the Mesquite, NV, 700 feet Class E airspace; that portion of airspace for V-235 southeast of the Mormon Mesa VORTAC: that portion of airspace for V-235 northeast of the Mormon Mesa VORTAC; that portion of airspace for V-21 northeast of the Mormon Mesa VORTAC.

Issued in Seattle, Washington, on August

Daniel A. Bovle.

31, 2000.

Acting Manager, Air Traffic Division, Northwest Mountain Region.

[FR Doc. 00–24143 Filed 9–20–00; 8:45 am]

# **DEPARTMENT OF COMMERCE**

**Bureau of Economic Analysis** 

#### 15 CFR Part 801

[Docket No. 000720214-0214-01]

RIN 0691-AA39

International Services Surveys: BE-93 Annual Survey of Royalties, License Fees, and Other Receipts and Payments for Intangible Rights Between U.S. and Unaffiliated Foreign Persons

**AGENCY:** Bureau of Economic Analysis, Commerce.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This notice sets forth proposed rules to amend the reporting requirements for the BE-93, Annual Survey of Royalties, License Fees, and Other Receipts and Payments for