

Actions	Compliance	Procedures
(1) For all affected airplanes, inspect the fuel selector valve for leakage.	Within the next 100 hours time-in-service (TIS) after October 10, 2003 (the effective date of this AD), unless already accomplished.	In accordance with EXTRA Flugzeugbau GmbH Service Letter No. 300-09-02, Issue: A, dated September 19, 2002, and the applicable airplane maintenance manual.
(2) For all affected airplanes, if any leakage is found during the inspection required by this AD, repair the damage.	Prior to further flight after the inspection required in paragraph (d)(1) of this AD, unless already accomplished.	In accordance with the applicable airplane maintenance manual.
(3) For all affected airplanes, inspect the external wing for structural damage:	Within the next 100 hours time-in-service (TIS) after October 10, 2003 (the effective date of this AD), unless already accomplished.	In accordance with the applicable airplane maintenance manual.
(i) Cracks (ii) Delamination (iii) Fuel leakage		
(4) For all affected airplanes, if any cracks, delamination, or fuel leakage is found during the inspection required by this AD, accomplish the following:	Prior to further flight after the inspection required in paragraph (d)(3) of this AD, unless already accomplished.	In accordance with a repair scheme obtained from EXTRA Flugzeugbau GmbH, Flugplatz Dinslaken, D-46569 Hünxe, Federal Republic of Germany; telephone: (0 28 58) 91 37-00; facsimile: (0 28 58) 91 37-30. Obtain this repair scheme through the FAA at the address specified in paragraph (e) of this AD.
(i) obtain a repair scheme from the manufacturer;		
(ii) incorporate this repair scheme; and		
(iii) accomplish any follow-up actions as directed by the FAA.		

(e) *Can I comply with this AD in any other way?* To use an alternative method of compliance or adjust the compliance time, use the procedures in 14 CFR 39.19. Send these requests to the Manager, Standards Office, Small Airplane Directorate. For information on any already approved alternative methods of compliance, contact Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; facsimile: (816) 329-4090.

(f) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with EXTRA Flugzeugbau GmbH Service Letter No. 300-09-02, Issue: A, dated September 19, 2002. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You may get copies from EXTRA Flugzeugbau GmbH, Flugplatz Dinslaken, D-46569 Hünxe, Federal Republic of Germany; telephone: (0 28 58) 91 37-00; facsimile: (0 28 58) 91 37-30. You may view copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(g) *When does this amendment become effective?* This amendment becomes effective on October 10, 2003.

Issued in Kansas City, Missouri, on August 11, 2003.

Diane K. Malone,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-20832 Filed 8-18-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2003-15720; Airspace Docket No. 03-ACE-62]

Modification of Class E Airspace; Maryville, MO

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; request for comments.

SUMMARY: Maryville Memorial Airport, Maryville, MO, has been renamed Northwest Missouri Regional Airport. An examination of controlled airspace for Maryville, MO indicates it does not comply with criteria set forth in FAA Orders. This action corrects the discrepancies by modifying the Maryville, MO Class E airspace area, replaces "Maryville Memorial Airport" in the legal description of Maryville, MO Class E airspace area with "Northwest Missouri Regional Airport" and brings the legal description into compliance with FAA Orders.

EFFECTIVE DATE: This direct final rule is effective on 0901 UTC, December 25, 2003. Comments for inclusion in the Rules Docket must be received on or before September 29, 2003.

ADDRESSES: Send comments on this rule to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket number FAA-2003-15720/Airspace Docket No. 03-ACE-62, at the beginning of your comments. You

may also submit comments on the Internet at <http://dms.dot.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

FOR FURTHER INFORMATION CONTACT: Brenda Mumper, Air Traffic Division, Airspace Branch, ACE-520A, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas City, MO 64106; telephone: (816) 329-2524.

SUPPLEMENTARY INFORMATION: This amendment to 14 CFR 71 modifies the Class E airspace area extending upward from 700 feet above the surface at Maryville, MO. It replaces "Maryville Memorial Municipal Airport," the former name of the airport, with "Northwest Missouri Regional Airport," the new name of the airport, in the legal description. A review of controlled airspace at Maryville, MO indicates 700 feet Above Ground Level (AGL) airspace required for diverse departures, as specified in FAA Order 7400.2E, Procedures for Handling Airspace Matters, for Northwest Missouri Regional Airport does not comply with the Order. The criteria in FAA Order 7400.2E for an aircraft to reach 1200 feet AGL is based on a standard climb gradient of 200 feet per mile plus the distance from the Airport Reference Point (ARP) to the end of the outermost runway. Any fractional part of a mile is converted to the next higher tenth of a

mile. The area is enlarged to conform to the criteria in FAA Order 7400.2E. This action also expands the northwest extension of the Maryville, MO Class E airspace area an additional 2.6 miles to provide appropriate controlled airspace for aircraft executing the NDB or Global Positioning System (GPS) Runway (RWY) 14 Standard Instrument Approach Procedure (SIAP) to Northwest Missouri Regional Airport. It also modifies this extension by defining it with the 334° bearing from the Emville NDB versus the current 333° bearing. It brings the legal description of this airspace area into compliance with FAA Order 7400.2E. The area will be depicted on appropriate aeronautical charts. Class E airspace areas extending upward from 700 feet or more above the surface of the earth are published in paragraph 6005 of FAA Order 7400.9K, dated August 30, 2002, and effective September 16, 2002, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

The Direct Final Rule Procedure

The FAA anticipates that this regulation will not result in adverse or negative comment and, therefore, is issuing it as a direct final rule. Previous actions of this nature have not been controversial and have not resulted in adverse comments or objections. Unless a written adverse or negative comment, or a written notice of intent to submit an adverse or negative comment is received within the comment period, the regulation will become effective on the date specified above. After the close of the comment period, the FAA will publish a document in the **Federal Register** indicating that no adverse or negative comments were received and confirming the date on which the final rule will become effective. If the FAA does receive, within the comment period, an adverse or negative comment, or written notice of intent to submit such a comment, a document withdrawing the direct final rule will be published in the **Federal Register**, and a notice of proposed rulemaking may be published with a new comment period.

Comments Invited

Interested parties are invited to participate in this rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall

regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2003-15720/Airspace Docket No. 03-ACE-62." The postcard will be date/time stamped and returned to the commenter.

Agency Findings

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is noncontroversial and unlikely to result in adverse or negative comments. For the reasons discussed in the preamble, I certify that this regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

■ Accordingly, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9K, dated August 30, 2002, and effective September 16, 2002, is amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

ACE MO E5 Maryville, MO

Maryville, Northwest Missouri Regional Airport, MO
(Lat. 40°21'09" N., long. 94°54'56" W.)
Emville NDB
(Lat. 40°20'54" N., long. 94°54'56" W.)

That airspace extending upward from 700 feet above the surface within a 6.5-mile radius of Northwest Missouri Regional Airport and within 2.6 miles each side of the 334° bearing from the Emville NDB extending from the 6.5-mile radius of the airport to 10 miles northwest of the NDB.

* * * * *

Issued in Kansas City, MO on August 1, 2003.

Herman J. Lyons, Jr.,

Manager, Air Traffic Division, Central Region.
[FR Doc. 03-21079 Filed 8-18-03; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2003-15724; Airspace Docket No. 03-ACE-66]

Modification of Class E Airspace; Centerville, IA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; request for comments.

SUMMARY: This action modifies the Class E airspace area at Centerville, IA. A review of controlled airspace for Centerville Municipal Airport indicates it does not comply with the criteria for 700 feet Above Ground Level (AGL) airspace required for diverse departures as specified in FAA Order 7400.2E. The area is enlarged to conform to the criteria in FAA Order 7400.2E.

DATES: This direct final rule is effective on 0901 UTC, December 25, 2003. Comments for inclusion in the Rules Docket must be received on or before October 2, 2003.

ADDRESSES: Send comments on this rule to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW.,