

(c) Applicability

This AD applies to all The Boeing Company Model 707–100 Long Body, –200, –100B Long Body, and –100B Short Body series airplanes; and Model 707–300, –300B, –300C, and –400 series airplanes; certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Unsafe Condition

This AD was prompted by analysis of the cam support assemblies of the main cargo door that indicated the repetitive high frequency eddy current (HFEC) inspections required by the existing maintenance program are not adequate to detect cracks before two adjacent cam support assemblies of the main cargo door could fail. We are issuing this AD to detect and correct cracking of the cam support assemblies of the main cargo door. Such cracking could result in reduced structural integrity of the main cargo door and consequent rapid decompression of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection To Determine Part Numbers

At the later of the times specified in paragraphs (g)(1) and (g)(2) of this AD: Inspect the cam support assemblies of the main cargo door to determine whether part number (P/N) 69–23588–1, 69–23588–2, 69–23588–5, 69–23588–6, 69–23588–9, or 69–23588–10 is installed. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number(s) of the cam support assemblies of the main cargo door can be conclusively determined from that review.

(1) Before the accumulation of 18,000 total flight cycles.

(2) Within 1,790 flight cycles or 24 months after the effective date of this AD, whichever occurs later.

(h) Repetitive Inspections for the Cam Support Assemblies of the Main Cargo Door and Corrective Actions

If, during any inspection required by paragraph (g) of this AD, any cam support assembly of the main cargo door having P/N 69–23588–1, 69–23588–2, 69–23588–5, 69–23588–6, 69–23588–9, or 69–23588–10 is determined to be installed: Except as required by paragraph (i) of this AD, at the applicable time specified in paragraph 1.E., “Compliance,” of Boeing 707 Alert Service Bulletin A3542, dated February 12, 2016, do an ultrasonic inspection to detect cracking of the affected cam support assemblies of the main cargo door, and do all applicable replacements, in accordance with the Accomplishment Instructions of Boeing 707 Alert Service Bulletin A3542, dated February 12, 2016. Do all applicable replacements before further flight. Repeat the inspections thereafter at the applicable time specified in paragraph 1.E., “Compliance,” of Boeing 707 Alert Service Bulletin A3542, dated February 12, 2016.

(i) Service Information Exception

Where Boeing 707 Alert Service Bulletin A3542, dated February 12, 2016, specifies a compliance time “after the original issue date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

(1) For more information about this AD, contact Chandra Ramdoss, Aerospace Engineer, Airframe Branch, ANM–120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5239; fax: 562–627–5210; email: chandraduth.ramdoss@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone: 206–

544–5000, extension 1; fax: 206–766–5680; Internet: <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on September 27, 2016.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–23939 Filed 10–3–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF THE TREASURY**Internal Revenue Service****26 CFR Part 1**

[REG–163113–02]

RIN 1545–BB71

Estate, Gift, and Generation-Skipping Transfer Taxes; Restrictions on Liquidation of an Interest; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Correction to notice of proposed rulemaking.

SUMMARY: This document contains a correction to a notice of proposed rulemaking (REG–163113–02) that was published in the **Federal Register** on Thursday, August 4, 2016 (81 FR 51413). The proposed regulations concern the valuation of interests in corporations and partnerships for estate, gift, and generation-skipping transfer tax purposes.

DATES: Written or electronic comments and outlines of topics to be discussed at the public hearing scheduled for December 1, 2016, for the notice of proposed rulemaking at 81 FR 51413, August 4, 2016, are still being accepted and must be received by November 2, 2016.

ADDRESSES: Send submissions to CC:PA:LPD:PR (REG–163113–02), Room 5203, Internal Revenue Service, P.O. Box 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand delivered Monday through Friday between the hours of 8 a.m. and 4 p.m. to CC:PA:LPD:PR (REG–163113–02), Courier's desk, Internal Revenue Service, 1111 Constitution Avenue NW., Washington, DC 20224, or sent electronically, via the Federal eRulemaking Portal at www.regulations.gov (IRS REG–163113–02).

FOR FURTHER INFORMATION CONTACT: John D. MacEachen, at (202) 317-6859 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

The notice of proposed rulemaking that is the subject of this document is under section 2704 of the Internal Revenue Code.

Need for Correction

As published, the notice of proposed rulemaking (REG-163113-02) contains an error that is misleading and is in need of clarification.

Correction to Publication

Accordingly, the notice of proposed rulemaking, that is the subject of FR Doc. 2016-18370, is corrected as follows:

1. On page 51418, in the third column, under the paragraph heading “Effective Dates”, in the second line from the top of the paragraph, the language “proposed to be effective on and after the” is corrected to read “proposed to be effective on the”.

Martin V. Franks,

Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel, (Procedure and Administration).

[FR Doc. 2016-23957 Filed 10-3-16; 8:45 am]

BILLING CODE 4830-01-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA-R09-OAR-2016-0291; FRL-9952-12-Region 9]

Approval of California Air Plan Revisions, Sacramento Metropolitan Air Quality Management District and San Diego County Air Pollution Control District

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: The Environmental Protection Agency (EPA) is proposing to approve revisions to the Sacramento Metropolitan Air Quality Management District (SMAQMD) and the San Diego County Air Pollution Control District (SDCAPCD) portions of the California State Implementation Plan (SIP). These revisions concern volatile organic compound (VOC) emissions from architectural coatings. We are proposing to approve local rules and a rule rescission to regulate these emission sources under the Clean Air Act (CAA or the Act).

DATES: Any comments on this proposal must arrive by November 3, 2016.

ADDRESSES: Submit your comments, identified by Docket ID No. EPA-R09-OAR-2016-0291 at <http://www.regulations.gov>, or via email to Steckel.Andrew@epa.gov. For comments submitted at [Regulations.gov](http://www.regulations.gov), follow the online instructions for submitting comments. Once submitted, comments cannot be edited or removed from [Regulations.gov](http://www.regulations.gov). For either manner of submission, the EPA may publish any comment received to its public docket. Do not submit electronically any information you consider to be Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Multimedia submissions (audio, video, etc.) must be accompanied by a written comment. The written comment is considered the official comment and should include discussion of all points you wish to make. The EPA will generally not consider comments or comment contents located outside of the primary submission (*i.e.* on the Web, cloud, or other file sharing system). For additional submission methods, please contact the person identified in the **FOR FURTHER INFORMATION CONTACT** section. For the full EPA public comment policy, information about CBI or multimedia submissions, and general guidance on making effective comments, please visit <http://www2.epa.gov/dockets/commenting-epa-dockets>.

FOR FURTHER INFORMATION CONTACT: Arnold Lazarus, EPA Region IX, (415) 972-3024, lazarus.arnold@epa.gov.

SUPPLEMENTARY INFORMATION:

Throughout this document, “we,” “us” and “our” refer to the EPA. This proposal addresses the following local rules: SMAQMD Rule 442, SDCAPCD Rule 67.0 (rescinded) and SDCAPCD Rule 67.0.1 (the replacement rule). In the Rules and Regulations section of this **Federal Register**, we are approving these local rules and rule rescission in a direct final action without prior proposal because we believe these SIP revisions are not controversial. If we receive adverse comments, however, we will publish a timely withdrawal of the direct final rule and address the comments in subsequent action based on this proposed rule.

We do not plan to open a second comment period, so anyone interested in commenting should do so at this time. If we do not receive adverse comments, no further activity is planned. For further information, please see the direct final action.

Dated: August 24, 2016.

Alexis Strauss,

Acting Regional Administrator, Region IX.

[FR Doc. 2016-23838 Filed 10-3-16; 8:45 am]

BILLING CODE 6560-50-P

DEPARTMENT OF THE INTERIOR

Fish and Wildlife Service

50 CFR Part 17

[Docket No. FWS-R6-ES-2016-0086; 4500030113]

RIN 1018-BB52

Endangered and Threatened Wildlife and Plants; 12-Month Finding on a Petition To List the Western Glacier Stonefly as an Endangered or Threatened Species; Proposed Threatened Species Status for Meltwater Lednian Stonefly and Western Glacier Stonefly

AGENCY: Fish and Wildlife Service, Interior.

ACTION: Proposed rule; 12-month petition finding and status review.

SUMMARY: We, the U.S. Fish and Wildlife Service (Service), announce a 12-month finding for the western glacier stonefly (*Zapada glacier*). After a review of the best available scientific and commercial information, we find that listing the western glacier stonefly is warranted. We are also announcing the proposed listing rule for the candidate species meltwater lednian stonefly (*Lednia tumana*). Therefore, we are proposing to list both the meltwater lednian stonefly and the western glacier stonefly, two insect species from Glacier National Park and northwestern Montana, as threatened species under the Endangered Species Act (Act). If we finalize this rule as proposed, it would extend the Act's protections to these species. The effect of this regulation will be to add these species to the Federal List of Endangered and Threatened Wildlife. The Service seeks data and comments from the public on this proposed listing rule.

DATES: We will accept comments received or postmarked on or before December 5, 2016. Comments submitted electronically using the Federal eRulemaking Portal (see **ADDRESSES** below) must be received by 11:59 p.m. Eastern Time on the closing date. We must receive requests for public hearings, in writing, at the address shown in **FOR FURTHER INFORMATION CONTACT** by November 18, 2016.

ADDRESSES: You may submit comments by one of the following methods: