

**§ 81.8 Public reading facility.**

GAO maintains a public reading facility in the Law Library at the General Accounting Office Building, 441 G Street, NW., Washington, DC. The facility shall be open to the public from 8:30 a.m. to 4 p.m. except Saturday, Sundays, and holidays.

**Anthony H. Gamboa,**

*General Counsel, General Accounting Office.*

[FR Doc. 03-14304 Filed 6-5-03; 8:45 am]

BILLING CODE 1610-02-P

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 25**

[Docket No. NM256, Special Conditions No. 25-236-SC]

**Special Conditions: Raytheon Model HS.125 Series 700A and 700B Airplanes; High Intensity Radiated Fields (HIRF)**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final special conditions; request for comments.

**SUMMARY:** These special conditions are issued for Raytheon Model HS.125 Series 700A and 700B airplanes modified by Raytheon Aircraft Services, Inc. These modified airplanes will have a novel or unusual design feature when compared to the state of technology envisioned in the airworthiness standards for transport category airplanes. The modification incorporates the installation of a Rockwell Collins AFD 2000 Electronic Flight Instrument System (EFIS) that performs critical functions. The applicable airworthiness regulations do not contain adequate or appropriate safety standards for the protection of this system from the effects of high-intensity radiated fields (HIRF). These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that provided by the existing airworthiness standards.

**DATES:** The effective date of these special conditions is May 22, 2003. Comments must be received on or before July 7, 2003.

**ADDRESSES:** Comments on these special conditions may be mailed in duplicate to: Federal Aviation Administration, Transport Airplane Directorate, Attn: Rules Docket (ANM 113), Docket No. NM256, 1601 Lind Avenue SW., Renton, Washington, 98055-4056; or

delivered in duplicate to the Transport Airplane Directorate at the above address. All comments must be marked: Docket No. NM256.

**FOR FURTHER INFORMATION CONTACT:** Connie Beane, FAA, Standardization Branch, ANM-113, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington, 98055-4056; telephone (425) 227-2796; facsimile (425) 227-1149.

**SUPPLEMENTARY INFORMATION:****Comments Invited**

The FAA has determined that notice and opportunity for public comment in accordance with 14 CFR 11.38 are unnecessary, because the FAA has provided previous opportunities to comment on substantially identical special conditions and has fully considered and addressed all the substantive comments received. Based on a review of the comment history and the comment resolution, the FAA is satisfied that new comments are unlikely. The FAA, therefore, finds that good cause exists for making these special conditions effective upon issuance.

However, the FAA invites interested persons to participate in this rulemaking by submitting written comments, data, or views. The most helpful comments reference a specific portion of the special conditions, explain the reason for any recommended change, and include supporting data. We ask that you send us two copies of written comments.

We will file in the docket all comments we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning these special conditions. The docket is available for public inspection before and after the comment closing date. If you wish to review the docket in person, go to the address in the **ADDRESSES** section of this preamble between 7:30 a.m., and 4 p.m., Monday through Friday, except Federal holidays.

We will consider all comments we receive on or before the closing date for comments. We will consider comments filed late if it is possible to do so without incurring expense or delay. We may change these special conditions based on the comments we received.

If you want the FAA to acknowledge receipt of your comments on these special conditions, include with your comments a pre-addressed, stamped postcard on which the docket number appears. We will stamp the date on the postcard and mail it back to you.

**Background**

On September 23, 2002, Raytheon Aircraft Services, Inc., 1115 Paul Wilkins Road, San Antonio, Texas 78216, applied for a supplemental type certificate (STC) to modify Raytheon Model HS.125 Series 700A and 700B airplanes. These models are currently approved under Type Certificate No. A3EU. The HS.125 Series 700A and 700B airplanes are two flightcrew, two-engine airplanes, each with a maximum takeoff weight of 25,500 lbs. The modification incorporates the installation of a Rockwell Collins AFD 2000 EFIS. This equipment will replace the equipment originally installed in these airplanes which presents the required flight information in the form of analog displays. The avionics/electronics and electrical system to be installed has the potential to be vulnerable to high-intensity radiated fields (HIRF) external to the airplane.

**Type Certification Basis**

Under the provisions of 14 CFR 21.101, Amendment 21-69, effective September 16, 1991, Raytheon Aircraft Services, Inc. must show that the modified Model HS.125 Series 700A and 700B airplanes, as modified, continue to meet the applicable provisions of the regulations incorporated by reference in Type Certificate No. A3EU, or the applicable regulations in effect on the date of application for the change. Subsequent changes have been made to § 21.101 as part of Amendment 21-77, but those changes do not become effective until June 10, 2003. The regulations incorporated by reference in the type certificate are commonly referred to as the "original type certification basis."

If the Administrator finds that the applicable airworthiness regulations (*i.e.*, part 25, as amended) do not contain adequate or appropriate safety standards for the Model HS.125 Series 700A and 700B airplanes because of a novel or unusual design feature, special conditions are prescribed under the provisions of § 21.16.

In addition to the applicable airworthiness regulations and special conditions, the Raytheon Model HS.125 Series 700A and 700B airplanes must comply with the fuel vent and exhaust emission requirements of 14 CFR part 34 and the noise certification requirements of 14 CFR part 36.

Special conditions, as defined in 14 CFR 11.19, are issued in accordance with § 11.38 and become part of the type certification basis in accordance with § 21.101(b)(2), Amendment 21-69, effective September 16, 1991.

Special conditions are initially applicable to the model for which they are issued. Should Raytheon Aircraft Services, Inc. apply at a later date for a supplemental type certificate to modify any other model included on Type Certificate A3EU to incorporate the same or similar novel or unusual design feature, these special conditions would also apply to the other model under the provisions of § 21.101(a)(1), Amendment 21-69, effective September 16, 1991.

#### Novel or Unusual Design Features

As noted earlier, the Raytheon Model HS.125 Series 700A and 700B airplanes modified by Raytheon Aircraft Services, Inc. will incorporate an EFIS that will perform critical functions. This system may be vulnerable to high-intensity radiated fields external to the airplane. The current airworthiness standards of part 25 do not contain adequate or appropriate safety standards for the protection of this equipment from the adverse effects of HIRF. Accordingly, this system is considered to be a novel or unusual design feature.

#### Discussion

There is no specific regulation that addresses protection requirements for

electrical and electronic systems from HIRF. Increased power levels from ground-based radio transmitters and the growing use of sensitive avionics/electronics and electrical systems to command and control airplanes have made it necessary to provide adequate protection.

To ensure that a level of safety is achieved equivalent to that intended by the regulations incorporated by reference, special conditions are needed for the Raytheon Model HS.125 Series 700A and 700B airplanes modified by Raytheon Aircraft Services, Inc. These special conditions require that new avionic/electronic and electrical systems that perform critical functions be designed and installed to preclude component damage and interruption of function due to both the direct and indirect effects of HIRF.

#### High-Intensity Radiated Fields (HIRF)

With the trend toward increased power levels from ground-based transmitters and the advent of space and satellite communications coupled with electronic command and control of the airplane, the immunity of critical digital avionic/electronic and electrical systems to HIRF must be established.

It is not possible to precisely define the HIRF to which the airplane will be exposed in service. There is also uncertainty concerning the effectiveness of airframe shielding for HIRF. Furthermore, coupling of electromagnetic energy to cockpit-installed equipment through the cockpit window apertures is undefined. Based on surveys and analysis of existing HIRF emitters, an adequate level of protection exists when compliance with the HIRF protection special condition is shown with either paragraph 1 or 2 below:

1. A minimum threat of 100 volts rms (root-mean-square) per meter electric field strength from 10 KHz to 18 GHz.

a. The threat must be applied to the system elements and their associated wiring harnesses without the benefit of airframe shielding.

b. Demonstration of this level of protection is established through system tests and analysis.

2. A threat external to the airframe of the field strengths indicated in the following table for the frequency ranges indicated. Both peak and average field strength components from the table are to be demonstrated.

Frequency	Field strength (volts per meter)	
	Peak	Average
10 kHz–100 kHz .....	50	50
100 kHz–500 kHz .....	50	50
500 kHz–2 MHz .....	50	50
2 MHz–30 MHz .....	100	100
30 MHz–70 MHz .....	50	50
70 MHz–100 MHz .....	50	50
100 MHz–200 MHz .....	100	100
200 MHz–400 MHz .....	100	100
400 MHz–700 MHz .....	700	50
700 MHz–1 GHz .....	700	100
1 GHz–2 GHz .....	2000	200
2 GHz–4 GHz .....	3000	200
4 GHz–6 GHz .....	3000	200
6 GHz–8 GHz .....	1000	200
8 GHz–12 GHz .....	3000	300
12 GHz–18 GHz .....	2000	200
18 GHz–40 GHz .....	600	200

The field strengths are expressed in terms of peak of the root-mean-square (rms) over the complete modulation period.

The threat levels identified above are the result of an FAA review of existing studies on the subject of HIRF, in light of the ongoing work of the Electromagnetic Effects Harmonization Working Group of the Aviation Rulemaking Advisory Committee.

#### Applicability

As discussed above, these special conditions are applicable to Raytheon

Model HS.125 Series 700A and 700B airplanes modified by Raytheon Aircraft Services, Inc. Should Raytheon Aircraft Services, Inc. apply at a later date for a supplemental type certificate to modify any other model included on Type Certificate A3EU to incorporate the same or similar novel or unusual design feature, these special conditions would apply to that model as well as under the provisions of § 21.101(a)(1),

Amendment 21-69, effective September 16, 1991.

#### Conclusion

This action affects only certain novel or unusual design features on the Raytheon Model HS.125 Series 700A and 700B airplanes modified by Raytheon Aircraft Services, Inc. It is not a rule of general applicability and affects only the applicant which applied

to the FAA for approval of these features on the airplane.

The FAA has determined that notice and opportunity for public comment in accordance with 14 CFR 11.38 are unnecessary, because the FAA has provided previous opportunities to comment on substantially identical special conditions and has fully considered and addressed all the substantive comments received. Based on a review of the comment history and the comment resolution, the FAA is satisfied that new comments are unlikely. The FAA, therefore, finds that good cause exists for making these special conditions effective upon issuance.

#### List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and record keeping requirements.

■ The authority citation for these special conditions is as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

#### The Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the supplemental type certification basis for the Raytheon Model HS.125 Series 700A and 700B airplanes modified by Raytheon Aircraft Services, Inc.

1. *Protection from Unwanted Effects of High-Intensity Radiated Fields (HIRF).* Each electrical and electronic system that performs critical functions must be designed and installed to ensure that the operation and operational capability of these systems to perform critical functions are not adversely affected when the airplane is exposed to high intensity radiated fields.

2. For the purpose of these special conditions, the following definition applies: *Critical Functions:* Functions whose failure would contribute to or cause a failure condition that would prevent the continued safe flight and landing of the airplane.

Issued in Renton, Washington, on May 22, 2003.

**Ali Bahrami,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 03-14336 Filed 6-5-03; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 25

[Docket No. NM255; Special Conditions No. 25-03-04-SC]

#### Special Conditions: Bombardier Model BD-100-1A10 Airplane; Automatic Takeoff Thrust Control System

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final special conditions; request for comments.

**SUMMARY:** These special conditions are issued for the Bombardier Model BD-100-1A10 airplane. This airplane will have a novel or unusual design feature when compared to the state of technology envisioned in the airworthiness standards for transport category airplanes. This design feature is associated with an Automatic Takeoff Thrust Control System (ATTCS). The applicable airworthiness regulations do not contain adequate or appropriate safety standards for approach climb performance using an ATTCS. These special conditions contain the additional safety standards the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

**DATES:** The effective date of these special conditions is May 28, 2003.

Comments must be received on or before July 7, 2003.

**ADDRESSES:** Comments on this proposal may be mailed in duplicate to: Federal Aviation Administration, Transport Airplane Directorate, Attention: Rules Docket (ANM-113), Docket No. NM255, 1601 Lind Avenue SW., Renton, Washington 98055-4056; or delivered in duplicate to the Transport Airplane Directorate at that address. You must mark your comments: Docket No. NM255. Comments may be inspected in the Rules Docket at that address on weekdays, except Federal holidays, between 7:30 a.m. and 4 p.m.

#### FOR FURTHER INFORMATION CONTACT:

Larry Reising, FAA, Propulsion/Mechanical Systems Branch, Transport Airplane Directorate, Aircraft Certification Office, ANM-112, 1601 Lind Avenue SW., Renton, Washington, telephone (425) 227-2683; fax (425) 227-2683.

**SUPPLEMENTARY INFORMATION:** The FAA has determined that notice and opportunity for prior public comment hereon are impracticable, because those procedures would significantly delay

issuance of the approval design and thus delivery of the affected aircraft. In addition, the substance of these special conditions has been subject to the public comment process in several prior instances with no substantive comments received. The FAA, therefore, finds that good cause exists for making these special conditions effective upon issuance.

#### Comments Invited

The FAA has determined that notice and opportunity for public comment in accordance with 14 CFR 11.38 are unnecessary, because the FAA has provided previous opportunities to comment on substantially identical special conditions and has fully considered and addressed all the substantive comments received. Based on a review of the comment history and the comment resolution, the FAA is satisfied that new comments are unlikely. The FAA, therefore, finds that good cause exists for making these special conditions effective upon issuance.

However, the FAA invites interested persons to participate in this rulemaking by submitting written comments, data, and views. The most helpful comments reference a specific portion of the special conditions, explain the reason for any recommended change, and include supporting data. We ask that you send us two copies of written comments.

We will file in the docket all comments we receive as well as a report summarizing each substantive public contact with the FAA personnel concerning these proposed special conditions. The docket is available for public inspection before and after the comment closing date. If you wish to review the docket in person, go to the address in the **ADDRESSES** section of this notice between 7:30 a.m. and 4 p.m., Monday through Friday, except Federal holidays.

We will consider all comments we receive on or before the closing date for comments. We will consider comments filed late if it is possible to do so without incurring expense or delay. We may change the special conditions based on the comments we receive.

If you want the FAA to acknowledge receipt of your comments on these special conditions, include with your comments a pre-addressed, stamped postcard on which the docket number appears. We will stamp the date on the postcard and mail it back to you.

#### Background

On March 26, 1999, Bombardier Aerospace submitted an application to