Airport/Louis Schreiner Field. The geographic coordinates of the airport also are adjusted. The FAA is taking this action to enhance the safety and management of Instrument Flight Rule (IFR) operations at the airport. Due to subsequent decommissioning, the Shein locator outer marker/nondirectional radio beacon (LOM/NDB) will be removed from the regulatory text.

DATES: Effective date: 0901 UTC, November 15, 2012. The Director of the Federal Register approves this incorporation by reference action under 1 CFR Part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT:

Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone (817) 321– 7716

SUPPLEMENTARY INFORMATION:

History

On May 21, 2012, the FAA published in the **Federal Register** a notice of proposed rulemaking (NPRM) to amend Class E airspace for the Kerrville, TX, area, creating additional controlled airspace at Kerrville Municipal Airport/ Louis Schreiner Field (77 FR 29921) Docket No. FAA-2011-1399. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received. Subsequent to publication, it was discovered that the Shein LOM/NDB had been decommissioned. This action removes the Shein LOM/NDB from the regulatory text,

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9V dated August 9, 2011, and effective September 15, 2011, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) Part 71 by amending Class E airspace extending upward from 700 feet above the surface to accommodate new standard instrument approach procedures at Kerrville Municipal Airport/Louis Schreiner Field, Kerrville, TX. This action is necessary for the safety and management of IFR operations at the airport. Geographic coordinates are updated to coincide with the FAA's aeronautical database. This action also

removes the decommissioned Shein LOM/NDB from the regulatory text.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106, describes the authority of the FAA Administrator, Subtitle VII. Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends controlled airspace at Kerrville Municipal Airport/Louis Schreiner Field, Kerrville, TX.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1E, "Environmental Impacts: Policies and Procedures," paragraph 311a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air)

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR Part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§71.1 [Amended]

*

*

■ 2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9V, Airspace Designations and Reporting Points, dated August 9, 2011, and effective September 15, 2011, is amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface.

ASW TX E5 Kerrville, TX [Amended]

Kerrville Municipal Airport/Louis Schreiner Field, TX

(Lat. 29°58'36" N., long. 99°05'08" W)

That airspace extending upward from 700 feet above the surface within a 7.6-mile radius of Kerrville Municipal Airport/Louis Schreiner Field, and within 2 miles each side of the 310° bearing from the airport extending from the 7.6-mile radius to 12.3 miles northwest of the airport, and within 2.2 miles each side of the 131° bearing from the airport extending from the 7.6-mile radius to 11.6 miles southeast of the airport.

Issued in Fort Worth, Texas, on August 29, 2012.

David P. Medina,

Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2012–22585 Filed 9–13–12; 8:45 am]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30861; Amdt. No. 3496]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This rule establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are

needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective September 14, 2012. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 14, 2012.

ADDRESSES: Availability of matter incorporated by reference in the amendment is as follows:

For examination—

- 1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue SW., Washington, DC 20591;
- 2. The FAA Regional Office of the region in which the affected airport is located;
- 3. The National Flight Procedures Office, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,
- 4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Availability—All SIAPs are available online free of charge. Visit nfdc.faa.gov to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from:

- 1. FAA Public Inquiry Center (APA–200), FAA Headquarters Building, 800 Independence Avenue SW., Washington, DC 20591; or
- 2. The FAA Regional Office of the region in which the affected airport is located.

FOR FURTHER INFORMATION CONTACT:

Richard A. Dunham III, Flight Procedure Standards Branch (AFS–420) Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK 73125) telephone: (405) 954–4164. SUPPLEMENTARY INFORMATION: This rule amends Title 14, Code of Federal Regulations, Part 97 (14 CFR part 97) by amending the referenced SIAPs. The complete regulatory description of each SIAP is listed on the appropriate FAA Form 8260, as modified by the National Flight Data Center (FDC)/Permanent Notice to Airmen (P–NOTAM), and is incorporated by reference in the amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of Title 14 of the Code of Federal Regulations.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the Federal Register expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. This amendment provides the affected CFR sections and specifies the types of SIAP and the corresponding effective dates. This amendment also identifies the airport and its location, the procedure and the amendment number.

The Rule

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP as amended in the transmittal. For safety and timeliness of change considerations, this amendment incorporates only specific changes contained for each SIAP as modified by FDC/P–NOTAMs.

The SIAPs, as modified by FDC P– NOTAM, and contained in this amendment are based on the criteria contained in the U.S. Standard for **Terminal Instrument Procedures** (TERPS). In developing these changes to SIAPs, the TERPS criteria were applied only to specific conditions existing at the affected airports. All SIAP amendments in this rule have been previously issued by the FAA in a FDC NOTAM as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for all these SIAP amendments requires making them effective in less than 30 days.

Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and,

where applicable, that good cause exists for making these SIAPs effective in less than 30 days.

Conclusion

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 97

Air Traffic Control, Airports, Incorporation by reference, and Navigation (Air).

Issued in Washington, DC, on August 31, 2012.

Ray Towles,

Deputy Director, Flight Standards Service.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me, Title 14, Code of Federal regulations, Part 97, 14 CFR part 97, is amended by amending Standard Instrument Approach Procedures, effective at 0901 UTC on the dates specified, as follows:

PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

■ 1. The authority citation for part 97 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44701, 44719, 44721–44722.

■ 2. Part 97 is amended to read as follows:

§§ 97.23, 97.25, 97.27, 97.29, 97.31, 97.33, 97.35 [Amended]

By amending: § 97.23 VOR, VOR/ DME, VOR or TACAN, and VOR/DME or TACAN; § 97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; § 97.27 NDB, NDB/DME; § 97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; § 97.31 RADAR SIAPs; § 97.33 RNAV SIAPs; and § 97.35 COPTER SIAPs, Identified as follows:

* * * Effective Upon Publication

AIRAC date	State	City	Airport	FDC No.	FDC date	Subject
18-Oct-12	CA	Fresno	Fresno Chandler Exec- utive.	2/0072	08/28/12	GPS RWY 30, Orig-B.
18-Oct-12	CA	Fresno	Fresno Chandler Exec- utive.	2/0073	08/28/12	NDB OR GPS B, Amdt 7B.
18-Oct-12	MS	Greenville	Mid Delta Rgnl	2/2969	08/28/12	ILS OR LOC RWY 18L, Amdt 9E.
18-Oct-12	MS	Greenville	Mid Delta Rgnl	2/2983	08/28/12	RNAV (GPS) RWY 18L, Orig.
18-Oct-12	PA	Philadelphia	Philadelphia Intl	2/3006	08/28/12	RNAV (RNP) Z RWY 9R, Orig-A.
18-Oct-12	PA	Philadelphia	Philadelphia Intl	2/3007	08/28/12	RNAV (RNP) Z RWY 9L, Orig-A.
18-Oct-12	NM	Truth Or Consequences	Truth Or Consequences Muni.	2/4949	08/28/12	VOR A, Amdt 9B.
18-Oct-12	MO	St Louis	Lambert-St Louis Intl	2/4950	08/28/12	ILS OR LOC RWY 6, Amdt 1D.
18-Oct-12	NM	Silver City	Grant County	2/6726	08/28/12	RNAV (GPS) RWY 26, Orig.
18-Oct-12	AZ	Safford	Safford Rgnl	2/8256	08/28/12	RNAV (GPS) RWY 12, Orig.
18-Oct-12	ОК	Ardmore	Ardmore Downtown Ex- ecutive.	2/8543	08/28/12	RNAV (GPS) RWY 35, Orig.
18-Oct-12	ОК	Ardmore	Ardmore Downtown Ex- ecutive.	2/8545	08/28/12	RNAV (GPS) RWY 17, Orig.
18-Oct-12	IA	Sioux City	Sioux Gateway/Col. Bud Day Field.	2/8554	08/28/12	NDB RWY 13, Amdt 15D.
18-Oct-12	TX	Lubbock	Lubbock Preston Smith Intl.	2/8555	08/28/12	LOC BC RWY 35L, Amdt 18B.
18-Oct-12	TX	Center	Center Muni	2/8556	08/28/12	RNAV (GPS) RWY 17, Orig.
18-Oct-12	TX	Lubbock	Lubbock Preston Smith Intl.	2/8581	08/28/12	VOR A, Amdt 6B.
18-Oct-12	LA	Houma	Houma-Terrebonne	2/8629	08/28/12	VOR RWY 12, Amdt 5C.
18-Oct-12	OK	Stillwater	Stillwater Rgnl	2/8630	08/28/12	ILS OR LOC RWY 17, Amdt 2.
18-Oct-12	ОН	Bellefontaine	Bellefontaine Rgnl	2/8635	08/28/12	TAKEOFF MINIMUMS AND (OB- STACLE) DP, Orig.
18-Oct-12	MO	Kansas City	Charles B. Wheeler Downtown.	2/9138	08/28/12	RNAV (GPS) RWY 19, Orig.
18-Oct-12	МО	Kansas City	Charles B. Wheeler Downtown.	2/9139	08/28/12	RNAV (GPS) RWY 21, Amdt 1.

[FR Doc. 2012–22237 Filed 9–13–12; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30860; Amdt. No. 3495]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This rule establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient

use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective September 14, 2012. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 14, 2012.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For examination—

- 1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue SW., Washington, DC 20591;
- 2. The FAA Regional Office of the region in which the affected airport is located;
- 3. The National Flight Procedures Office, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,
- 4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http://www.archives.gov/federal_register/

code_of_federal_regulations/
ibr locations.html.

Āvailability—All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit http:// www.nfdc.faa.gov to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from:

- 1. FAA Public Inquiry Center (APA–200), FAA Headquarters Building, 800 Independence Avenue SW., Washington, DC 20591; or
- 2. The FAA Regional Office of the region in which the affected airport is located.

FOR FURTHER INFORMATION CONTACT:

Richard A. Dunham III, Flight Procedure Standards Branch (AFS–420), Flight Technologies and Programs Divisions, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082, Oklahoma City, OK 73125) Telephone: (405) 954–4164.

SUPPLEMENTARY INFORMATION: This rule amends Title 14 of the Code of Federal Regulations, Part 97 (14 CFR part 97), by establishing, amending, suspending, or revoking SIAPS, Takeoff Minimums and/or ODPS. The complete regulators description of each SIAP and its