When the petition is granted or denied, notice of the decision will also be published in the **Federal Register** pursuant to the authority indicated at the end of this notice.

All comments, background documentation, and supporting materials submitted to the docket may be viewed by anyone at the address and times given above. The documents may also be viewed on the Internet at <a href="https://www.regulations.gov">https://www.regulations.gov</a> by following the online instructions for accessing the dockets. The docket ID number for this petition is shown in the heading of this notice.

DOT's complete Privacy Act Statement is available for review in a **Federal Register** notice published on April 11, 2000, (65 FR 19477–78). SUPPLEMENTARY INFORMATION:

I. Overview: Volvo Trucks North America (VTNA), has determined that certain model year (MY) 2017 Volvo VNL and 2017 Volvo VNM heavy duty trucks do not fully comply with paragraph S5.2(b) of Federal Motor Vehicle Safety Standard (FMVSS) No. 120, Tire selection and rims and motor home/recreation vehicle trailer load carrying capacity information for motor vehicles with a GVWR of more than 4,536 kilograms (10,000 pounds). VTNA filed a noncompliance report dated February 9, 2017, pursuant to 49 CFR part 573, Defect and Noncompliance Responsibility and Reports. VTNA also petitioned NHTSA on February 28, 2017, pursuant to 49 U.S.C. 30118(d) and 30120(h) and 49 CFR part 556, and revised its petition on April 29, 2017, to obtain an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential as it relates to motor vehicle safety.

This notice of receipt of VTNA's petition is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of the petition.

II. Vehicles Involved: Approximately 862 MY 2017 Volvo VNL and 2017 Volvo VNM heavy duty trucks, manufactured between August 15, 2016, and November 10, 2016, are potentially involved.

III. Noncompliance: VTNA explains that the noncompliance is that the wheels on the subject vehicles incorrectly identify the rim size as 24.5" x 8.25" instead of 22.5" x 8.25", and therefore do not meet the requirements of paragraph S5.2(b) of FMVSS No. 120. Specifically, the marking error overstates the wheel diameter by 2".

IV. Rule Text: paragraph S5.2 of FMVSS No. 120 states:

S5.2 Rim marking. Each rim or, at the option of the manufacturer in the case of a single-piece wheel, wheel disc shall be marked with the information listed in paragraphs (a) through (e) of this paragraph, in lettering not less than 3 millimeters high, impressed to a depth or, at the option of the manufacturer, embossed to a height of not less than 0.125 millimeters . . .

(b) The rim size designation, and in case of multipiece rims, the rim type designation. For example:  $20 \times 5.50$ , or  $20 \times 5.5$ .

V. Summary of VTNA's Petition: VTNA described the subject noncompliance and stated its belief that the noncompliance is inconsequential as it relates to motor vehicle safety.

In support of its petition, VTNA referenced a letter to NHTSA, dated December 5, 2016, from Arconic Wheel and Transportation Products (Arconic), which is the rim manufacturer, and provided the following:

- 1. A 24.5" inch tire will not seat on the rim; therefore, if someone tries to mount a 24.5" tire to the rim, it will not hold air and therefore cannot be inflated.
- 2. When tires are replaced, the technician will select the tire based on the size and rating of the tire being replaced. When Volvo manufactured the vehicle, the tire used was a 22.5" (i.e., the correct size for the rim). Therefore, the tires installed by Volvo have the correct size on the sidewall of the tire.
- 3. Volvo is required to list the tires size and inflation pressures on the certification label as required by 49 CFR 567. The information printed on the label is the correct size, a 22.5" inch tire and reflects the tires that were installed when manufactured. The certification label is located inside the driver's door and can be easily accessed by the tire installer.

Volvo concluded by expressing the belief that the subject noncompliance is inconsequential as it relates to motor vehicle safety, and that its petition to be exempted from providing notification of the noncompliance, as required by 49 U.S.C. 30118, and a remedy for the noncompliance, as required by 49 U.S.C. 30120, should be granted.

To view VTNA's petition analyses in its entirety you can visit <a href="https://www.regulations.gov">https://www.regulations.gov</a> by following the online instructions for accessing the dockets and by using the docket ID number for this petition shown in the heading of this notice.

NHTSA notes that the statutory provisions (49 U.S.C. 30118(d) and 30120(h)) that permit manufacturers to file petitions for a determination of inconsequentiality allow NHTSA to exempt manufacturers only from the duties found in sections 30118 and

30120, respectively, to notify owners, purchasers, and dealers of a defect or noncompliance and to remedy the defect or noncompliance. Therefore, any decision on this petition only applies to the subject vehicles that VTNA no longer controlled at the time it determined that the noncompliance existed. However, any decision on this petition does not relieve vehicle distributors and dealers of the prohibitions on the sale, offer for sale, or introduction or delivery for introduction into interstate commerce of the noncompliant vehicles under their control after VTNA notified them that the subject noncompliance existed.

Authority: 49 U.S.C. 30118, 30120: Delegations of authority at 49 CFR 1.95 and 501.8.

## Jeffrey M. Giuseppe,

Director, Office of Vehicle Safety Compliance. [FR Doc. 2017–15253 Filed 7–19–17; 8:45 am] BILLING CODE 4910–59–P

#### **DEPARTMENT OF TRANSPORTATION**

## National Highway Traffic Safety Administration

Reports, Forms and Record Keeping Requirements; Agency Information Collection Activity Under OMB Review

**AGENCY:** National Highway Traffic Safety Administration, DOT.

**ACTION:** Notice.

SUMMARY: In compliance with the Paperwork Reduction Act of 1995, this notice announces that the Information Collection Request (ICR) abstracted below has been forwarded to the Office of Management and Budget (OMB) for review and comment. The ICR describes the nature of the information collections and their expected burden. The Federal Register Notice with a 60-day comment period was published on January 4, 2017

**DATES:** Comments must be submitted on or before August 21, 2017.

## FOR FURTHER INFORMATION CONTACT:

Coleman Sachs, Office of Vehicle Safety Compliance (NEF–230), National Highway Traffic Safety Administration, West Building, 4th Floor, Room W43– 481, 1200 New Jersey Avenue SE., Washington, DC 20590.

**SUPPLEMENTARY INFORMATION:** National Highway Traffic Safety Administration.

Title: 49 CFR part 566 Manufacturer Identification.

OMB Number: 2127-0043.

Type of Request: Extension of a Currently Approved Collection.

Abstract: The National Highway Traffic Safety Administration (NHTSA) has requested OMB to extend that agency's approval of the information collection that is incident to NHTSA's administration of the regulations at 49 CFR part 566 Manufacturer identification. Those regulations require manufacturers of motor vehicles or motor vehicle equipment, other than tires, to which a Federal motor vehicle safety standard (FMVSS) applies, to submit to NHTSA, on a one-time basis, identifying information on themselves and a description of the products that they manufacture to those standards. The information that must be submitted includes: (a) The full individual, partnership, or corporate name of the manufacturer; (b) the residence address of the manufacturer and State of incorporation, if applicable; and (c) a description of each type of motor vehicle or of covered equipment manufactured by the manufacturer, including, for motor vehicles, the approximate ranges of gross vehicle weight ratings (GVWR) for each type. The information must be submitted no later than 30 days after the manufacturer begins to manufacture motor vehicles or motor vehicle equipment subject to the FMVSS. No specific form need be used for the submission of this information. NHTSA provides an online portal with a fillable web-based format for use in submitting the required information. This is described in a handbook entitled Requirements for Manufacturers of Motor Vehicles and Motor Vehicle Equipment that can be accessed on the agency's Web site at https:// vpic.nhtsa.dot.gov. A description of the reporting requirement is included on pages 8 and 9 of the handbook. With changes implemented in 2015, manufacturers have been able to make these submissions using an online portal on the above agency Web site. Manufacturers who have previously submitted identifying information must ensure that the information on file is accurate and complete by submitting revised information no later than 30 days after a change in the business that affects the validity of that information has occurred.

This information collection is necessary to ensure that manufacturers of motor vehicles and motor vehicle equipment subject to the Federal motor vehicle safety standards identify themselves and their products to NHTSA so that NHTSA may contact them in the event that one of their products is suspected or found to contain a defect related to motor vehicle safety or fails to comply with an

applicable FMVSS. Manufacturers of defective or noncompliant motor vehicles or replacement motor vehicle equipment are required under 49 U.S.C. 30118 to furnish notification of the defect or noncompliance to the Secretary of Transportation, and as well as to owners, purchasers, and dealers of the motor vehicle or replacement equipment, and to remedy the defect or noncompliance without charge to the owner.

Affected Public: New manufacturers of motor vehicles and motor vehicle equipment, other than tires, subject to the Federal motor vehicle safety standards.

Estimated Total Annual Burden: 131 hours; \$3,930.

ADDRESSES: Send comments, within 30 days, to the Office of Information and Regulatory Affairs, Office of Management and Budget, 725 17th Street NW., Washington, DC 20503, Attention NHTSA Desk Officer.

Comments are invited on: Whether the proposed collection of information is necessary for the proper performance of the functions of the Department, including whether the information will have practical utility; the accuracy of the Department's estimate of the burden of the proposed information collection; ways to enhance the quality, utility and clarity of the information to be collected; and ways to minimize the burden of the collection of information on respondents, including the use of automated collection techniques or other forms of information technology.

A Comment to OMB is most effective if OMB receives it within 30 days of publication.

# Jeffrey M. Giuseppe,

Acting Associate Administrator, Enforcement. [FR Doc. 2017–15252 Filed 7–19–17; 8:45 am] BILLING CODE 4910–59–P

## **DEPARTMENT OF TRANSPORTATION**

# National Highway Traffic Safety Administration

[Docket No. NHTSA-2017-0011; Notice 2]

Daimler Trucks North America, LLC, Grant of Petition for Decision of Inconsequential Noncompliance

**AGENCY:** National Highway Traffic Safety Administration (NHTSA), Department of Transportation (DOT). **ACTION:** Grant of petition.

**SUMMARY:** Daimler Trucks North America, LLC (DTNA), has determined that certain model year (MY) 2016–2017 Freightliner trucks do not fully comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 101, Controls and Displays. DTNA filed a noncompliance report dated January 19, 2017, and amended it on January 25, 2017. DTNA also petitioned NHTSA on January 20, 2017, for a decision that the subject noncompliance is inconsequential as it relates to motor vehicle safety.

**ADDRESSES:** For further information on this decision contact Stu Seigel, Office of Vehicle Safety Compliance, the National Highway Traffic Safety Administration (NHTSA), telephone (202) 366–5287, facsimile (202) 366–3081.

#### SUPPLEMENTARY INFORMATION:

I. Overview: Daimler Trucks North America (DTNA), has determined that certain model year (MY) 2016-2017 Freightliner trucks do not fully comply with Table 2 of Federal Motor Vehicle Safety Standard (FMVSS) No. 101, Controls and Displays. DTNA filed a noncompliance report dated January 19, 2017, and amended it on January 25, 2017, pursuant to 49 CFR part 573, Defect and Noncompliance Responsibility and Reports. DTNA also petitioned NHTSA on January 20, 2017, pursuant to 49 U.S.C. 30118(d) and 30120(h) and 49 CFR part 556, for an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential as it relates to motor vehicle safety.

Notice of receipt of the petition was published with a 30-day public comment period, on April 7, 2017, in the **Federal Register** (82 FR 17069). No comments were received. To view the petition and all supporting documents log onto the Federal Docket Management System (FDMS) Web site at: https://www.regulations.gov/. Then follow the online search instructions to locate docket number "NHTSA-2017-0011."

II. Vehicles Involved: Affected are approximately 81,641 MY 2016–2017 versions of the following trucks, manufactured between March 2, 2015 and September 8, 2016:

- Freightliner 108SD
- Freightliner Business Class M2
- Freightliner Cascadia
- Freightliner 114SD

III. Noncompliance: DTNA explains that the noncompliance is that the Low Brake Air Pressure telltale for air brake systems displays the word "BRAKE" and a message on an adjacent display screen says "LOW AIR", rather than the words "BRAKE AIR," as specified in Table 2 of FMVSS No. 101. DTNA states